



PARIC CORPORATION
77 Westport Plaza Suite 250
St. Louis, MO 63146
TEL: 636-561-9500
FAX: 636-561-9501

REQUEST FOR INFORMATION	DATE: October 31, 2016	NO.: RFI-342
--------------------------------	-------------------------------	---------------------

To: Cannon Design

Attn: Kelvin Patel

From: Paric Corporation

Requested By: Devin Gates

Project Name: 15051-Webster University Interdisciplinary Science Building	Project No.: 15051
---	--------------------

Subject: Lug placed too low on column

Response Required By: November 07, 2016

Drawing / Spec Reference:

Information Requested:

The field reports that at column 508A (E6A & S0106, at lines A.2 and 3), the lug (e507) was shop installed 1'-0" too low (Stewart error). To continue steel erection, the field stripped one side of the bottom flange of beam 628A flush with the web of the beam and stuck erection bolts in the lowest two web holes on the right-hand end of the beam.

We believe we have three possible repair options:

1. Cut off the existing lug e507, and weld in a new lug
2. Cut off the existing lug e507, and re-weld it in the correct position
3. Cut off the lower 4-hole portion of the existing lug e507, and add an new 4-hole lug above the remaining 2-hole piece of e507

Response:

Options are all acceptable, but would recommend Option 3.

ARCHITECT'S RESPONSE:

This information is provided as an interpretation of the Contract Documents for implementation. It is not an authorization for change to the Contract Sum or Contract Time. If this information results in a claim for a change to the Contract, the Contractor shall notify the [Construction Manager][Architect] of a change through the change process.

Answered By: JILL WALKER / DMA

Date: 11.03.2016