



August 11, 2017

ARCHITECTURAL PUNCH LIST (EXTERIOR FAÇADE & ROOF)

Project: Webster University Interdisciplinary Science Building

Project No: CannonDesign #004561.01

Area of Division: Architectural, General Building Construction

Date of Observation: August 7, 2017

Attendees: Kelvin Patel, CannonDesign
Lynn Grossman, CannonDesign
George Crow, Heitmann & Associates
Devin Gates, PARIC
Jason Szachnieski, PARIC

Note: Failure by the Architect to include any item of non-compliance with the contract documents in this report does not relieve the Contractor of his responsibility to comply with the requirements of the contract documents.

Contractor to mark items completed and return to Architect.

General Summary:

An architectural punch list of the building was conducted for exterior façade and roof on August 7, 2017 using Autodesk BIM 360 Field. Additional comments are noted on the punch-list in magenta color text.

Items noted on this punch list are in addition to the Contractors punch list, punch lists issued by other disciplines, and any remaining open items from Field Reports.

The exterior site work punch-list and Landscape punch-list are still outstanding.

Major Areas that were not reviewed, incomplete or not included in this punch-list are listed below-

1. Metal panel installation on south elevation was incomplete and ongoing.
2. Fin installation on metal panels at east elevation was incomplete.
3. Mechanical louvers installation and metal panel installation at the east mechanical areaway was incomplete and ongoing.
4. The expansion joints were not reviewed due to construction equipment obstruction.
5. All the exterior hollow metal doors were not painted.
6. Metal panel installation at roof screen was incomplete and ongoing.

As of the date of this report, the building has not reached substantial completion.

Reported By:

Kelvin Patel, CannonDesign.

Attached:

1. Architectural Punch list for Exterior façade and Roof generated using Autodesk BIM 360 Field.

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
002092	OSHA Posters / OSHA 300 Form "Posted Feb 1st - April 30th"		<Top level>	Open	<not set>	Safety Non-conforming	07 Aug 2017	12 Aug 2017
002093	Superintendents Daily Inspection Log		<Top level>	Open	<not set>	Safety Non-conforming	07 Aug 2017	12 Aug 2017
002094	Safety Manual Present		<Top level>	Open	<not set>	Safety Non-conforming	07 Aug 2017	12 Aug 2017
002095	SDS Manual Present		<Top level>	Open	<not set>	Safety Non-conforming	07 Aug 2017	12 Aug 2017
002096	Glasses / goggles / face shields		<Top level>	Open	<not set>	Safety Non-conforming	07 Aug 2017	12 Aug 2017
002097	GFCI's Used		<Top level>	Open	<not set>	Safety Non-conforming	07 Aug 2017	12 Aug 2017

NOT APPLICABLE

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
002153	Metal support to extend up to face of stair - north courtyard stair		Site	Open	Atlas Iron Works	Architect Punch List	07 Aug 2017	12 Aug 2017



2017-08-07 15:04:08

End of 002153 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
002161	Touchup paint chips on handrail - courtyard		Site	Open	Atlas Iron Works	Architect Punch List	07 Aug 2017	12 Aug 2017



2017-08-07 15:26:15

End of 002161 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
002147	Cameras to be mounted flush to wall, not on brackets		Site	Open	Guarantee Electric	Architect Punch List	07 Aug 2017	12 Aug 2017




2017-08-07 14:21:26

End of 002147 images



Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
002107	Confirm all screws for rooftop mechanical equipment to stainless curbs are stainless, not galvanized.		Webster > Roof	Open	ICON Mechanical	Architect Punch List	07 Aug 2017	12 Aug 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
----------	-------------	-----------------	----------	--------	---------	------	--------------	----------



2017-08-07 10:29:19

End of 002107 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
002149	Patch concrete in dumpster enclosure		Site	Open	KCI Construction	Architect Punch List	07 Aug 2017	12 Aug 2017



2017-08-07 14:30:33

End of 002149 images



Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
002099	Membrane needs to be fully adhered to parapet substrate at all locations		Webster > Roof	Open	Kirberg Company	Architect Punch List	07 Aug 2017	12 Aug 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
----------	-------------	-----------------	----------	--------	---------	------	--------------	----------



2017-08-07 09:56:53

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
----------	-------------	-----------------	----------	--------	---------	------	--------------	----------



2017-08-07 09:56:56

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
----------	-------------	-----------------	----------	--------	---------	------	--------------	----------



2017-08-07 09:57:05

End of 002099 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
002100	Roof needs to slope so that there is no ponding above stair 1		Webster > Roof	Open	Kirberg Company	Architect Punch List	07 Aug 2017	12 Aug 2017



2017-08-07 10:06:30

End of 002100 images



Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
002101	Membrane needs to be sealed at terminations		Webster > Roof	Open	Kirberg Company	Architect Punch List	07 Aug 2017	12 Aug 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
----------	-------------	-----------------	----------	--------	---------	------	--------------	----------



2017-08-07 10:08:40

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
----------	-------------	-----------------	----------	--------	---------	------	--------------	----------



2017-08-07 10:08:45

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
----------	-------------	-----------------	----------	--------	---------	------	--------------	----------



2017-08-07 10:08:52

End of 002101 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
002102	Seal flashing to roof, repair damaged membrane as needed		Webster > Roof	Open	Kirberg Company	Architect Punch List	07 Aug 2017	12 Aug 2017



2017-08-07 10:12:06

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
----------	-------------	-----------------	----------	--------	---------	------	--------------	----------



2017-08-07 10:12:10

End of 002102 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
002105	Confirm gouges in pads at life safety tie offs do not affect roof membrane		Webster > Roof	Open	Kirberg Company	Architect Punch List	07 Aug 2017	12 Aug 2017



2017-08-07 10:25:23

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
----------	-------------	-----------------	----------	--------	---------	------	--------------	----------



2017-08-07 10:25:32

End of 002105 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
002106	Confirm walk off mats are adhered per specification (typical)		Webster > Roof	Open	Kirberg Company	Architect Punch List	07 Aug 2017	12 Aug 2017



2017-08-07 10:26:57

End of 002106 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
002109	Heads to be sealed at all turn bar fastener locations Counter-flashing missing		Webster > Roof	Open	Kirberg Company	Architect Punch List	07 Aug 2017	12 Aug 2017



2017-08-07 10:47:05

End of 002109 images



Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
002110	Pourable sealant needs to be sloped at all locations Such that there is no depression on top of sealant for the water to pool.		Webster > Roof	Open	Kirberg Company	Architect Punch List	07 Aug 2017	12 Aug 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
----------	-------------	-----------------	----------	--------	---------	------	--------------	----------



2017-08-07 10:57:51

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
----------	-------------	-----------------	----------	--------	---------	------	--------------	----------



2017-08-07 10:57:59

End of 002110 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
002111	Clamp needed at boot		Webster > Roof	Open	Kirberg Company	Architect Punch List	07 Aug 2017	12 Aug 2017



2017-08-07 10:59:32

End of 002111 images



Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
002112	Clamp and sealant needed at boot for fan		Webster > Roof	Open	Kirberg Company	Architect Punch List	07 Aug 2017	12 Aug 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
----------	-------------	-----------------	----------	--------	---------	------	--------------	----------



2017-08-07 11:01:31

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
----------	-------------	-----------------	----------	--------	---------	------	--------------	----------



2017-08-07 11:01:37

End of 002112 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
002114	Repair damaged membrane		Webster > Roof	Open	Kirberg Company	Architect Punch List	07 Aug 2017	12 Aug 2017



2017-08-07 11:04:12

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
----------	-------------	-----------------	----------	--------	---------	------	--------------	----------



2017-08-07 11:04:20

End of 002114 images



Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
002154	Fiber cement paneling not consistent with granite base - north courtyard stair		Site	Open	Kuenz Sheet Metal	Architect Punch List	07 Aug 2017	12 Aug 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
----------	-------------	-----------------	----------	--------	---------	------	--------------	----------



2017-08-07 15:06:18

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
----------	-------------	-----------------	----------	--------	---------	------	--------------	----------

Dimensional relationship of
Fiber cement panels and
Granite base to be
consistent per documents.



2017-08-07 15:06:22

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
----------	-------------	-----------------	----------	--------	---------	------	--------------	----------



2017-08-07 15:06:28

End of 002154 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
002155	Confirm bug screen is approved material		Site	Open	Kuenz Sheet Metal	Architect Punch List	07 Aug 2017	12 Aug 2017



2017-08-07 15:09:56

End of 002155 images



Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
002162	Add fiber cement to fill void at south courtyard stair OR Granite base to extend to the break metal cap.		Site	Open	Kuenz Sheet Metal	Architect Punch List	07 Aug 2017	12 Aug 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
----------	-------------	-----------------	----------	--------	---------	------	--------------	----------



2017-08-07 15:31:48

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
----------	-------------	-----------------	----------	--------	---------	------	--------------	----------



2017-08-07 15:31:51

End of 002162 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
002163	Fire sealant needed at could to deck and concrete wall		Webster > LEVEL_01 > 172A_RECYCLING	Open	Leonard Masonry, Inc.	Architect Punch List	07 Aug 2017	12 Aug 2017



2017-08-07 16:07:41

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
----------	-------------	-----------------	----------	--------	---------	------	--------------	----------



2017-08-07 16:07:51

End of 002163 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
002120	Cleanup caulk - west eab connector		Site	Open	National Glass & Glazing, Inc.	Architect Punch List	07 Aug 2017	12 Aug 2017



2017-08-07 11:32:34

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
----------	-------------	-----------------	----------	--------	---------	------	--------------	----------



2017-08-07 11:32:39

End of 002120 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
002123	Seal void at pavers and sidewalk to curtainwall - all locations Do not seal to Pavers. Provide sealant between the bottom mullion and concrete floor below per documents.		Site	Open	National Glass & Glazing, Inc.	Architect Punch List	07 Aug 2017	12 Aug 2017



2017-08-07 11:44:35

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
----------	-------------	-----------------	----------	--------	---------	------	--------------	----------



2017-08-07 11:44:46

End of 002123 images

002126	Cleanup sealant at southwest corner of curtainwall		Site	Open	National Glass & Glazing, Inc.	Architect Punch List	07 Aug 2017	12 Aug 2017
--------	--	--	------	------	--------------------------------	----------------------	-------------	-------------



Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
002127	Curtainwall sealant needs filled out at bottom and to be smooth at glass up to top, "feather out" snap covers at top and bottom.		Site	Open	National Glass & Glazing, Inc.	Architect Punch List	07 Aug 2017	12 Aug 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
----------	-------------	-----------------	----------	--------	---------	------	--------------	----------



2017-08-07 11:51:42

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
----------	-------------	-----------------	----------	--------	---------	------	--------------	----------



2017-08-07 11:51:47

End of 002127 images

002129	Repair sealant joint at northwest vestibule door		Site	Open	National Glass & Glazing, Inc.	Architect Punch List	07 Aug 2017	12 Aug 2017
--------	--	--	------	------	--------------------------------	----------------------	-------------	-------------



Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
002130	Automatic closer to be raised per shop drawings - northwest entrance At all entrance doors with automatic door opener (ADO), raise the ADO such that it is flush with the bottom of frame head. ADO should encroach into clear door opening.		Site	Open	National Glass & Glazing, Inc.	Architect Punch List	07 Aug 2017	12 Aug 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
002131	Sealant needs to be consistent, not "bubbling" - north side above well		Site	Open	National Glass & Glazing, Inc.	Architect Punch List	07 Aug 2017	12 Aug 2017



2017-08-07 13:35:10

End of 002131 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
002132	Remove sealant from exterior of curtainwall		Site	Open	National Glass & Glazing, Inc.	Architect Punch List	07 Aug 2017	12 Aug 2017



2017-08-07 13:36:22

End of 002132 images



Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
002133	Sealant needs to be consistent - north radius		Site	Open	National Glass & Glazing, Inc.	Architect Punch List	07 Aug 2017	12 Aug 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
----------	-------------	-----------------	----------	--------	---------	------	--------------	----------



2017-08-07 13:41:35

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
----------	-------------	-----------------	----------	--------	---------	------	--------------	----------



2017-08-07 13:41:43

End of 002133 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
002134	Cleanup sealant joint curtainwall to masonry		Site	Open	National Glass & Glazing, Inc.	Architect Punch List	07 Aug 2017	12 Aug 2017



2017-08-07 13:45:56

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
----------	-------------	-----------------	----------	--------	---------	------	--------------	----------



2017-08-07 13:46:02

End of 002134 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
002136	Repair substandard sealant at north window		Site	Open	National Glass & Glazing, Inc.	Architect Punch List	07 Aug 2017	12 Aug 2017

At north vertical window, the vertical sealant joints along the jambs are wider and does not conform to documents. The sealant has to be tooled to have smooth consistent finish.



2017-08-07 13:49:53

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
----------	-------------	-----------------	----------	--------	---------	------	--------------	----------



2017-08-07 13:49:58

End of 002136 images

002139	Seal at top right corner of projected window by generator	Site	Open	National Glass & Glazing, Inc.	Architect Punch List	07 Aug 2017	12 Aug 2017
--------	---	------	------	--------------------------------	----------------------	-------------	-------------

Sealant at the top of all the projected windows on east elevation to sealed flush with masonry surface per documents.



Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
002140	Misalignment at window sill - east projection window		Site	Open	National Glass & Glazing, Inc.	Architect Punch List	07 Aug 2017	12 Aug 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
----------	-------------	-----------------	----------	--------	---------	------	--------------	----------



2017-08-07 14:02:18

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
----------	-------------	-----------------	----------	--------	---------	------	--------------	----------



2017-08-07 14:02:31

End of 002140 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
002141	Clean bottom of projected window - east		Site	Open	National Glass & Glazing, Inc.	Architect Punch List	07 Aug 2017	12 Aug 2017




2017-08-07 14:04:48

End of 002141 images



Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
002142	Cleanup excess sealant on masonry, tool joint correctly - east projection window		Site	Open	National Glass & Glazing, Inc.	Architect Punch List	07 Aug 2017	12 Aug 2017


Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
----------	-------------	-----------------	----------	--------	---------	------	--------------	----------



2017-08-07 14:08:12

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
----------	-------------	-----------------	----------	--------	---------	------	--------------	----------

Paint pipe, color to match metal panels



End of 002142 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
002150	Touchup sealant at curtainwall - eab connector - east		Site	Open	National Glass & Glazing, Inc.	Architect Punch List	07 Aug 2017	12 Aug 2017



2017-08-07 14:35:19

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
----------	-------------	-----------------	----------	--------	---------	------	--------------	----------



2017-08-07 14:35:23

End of 002150 images

002152	Mullion to extend to ceiling panels - southwest		Site	Open	National Glass & Glazing, Inc.	Architect Punch List	07 Aug 2017	12 Aug 2017
--------	---	--	------	------	--------------------------------	----------------------	-------------	-------------



Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
002156	Corner sealant needs to be cleaned up - possible break metal solution?		Site	Open	National Glass & Glazing, Inc.	Architect Punch List	07 Aug 2017	12 Aug 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
----------	-------------	-----------------	----------	--------	---------	------	--------------	----------



2017-08-07 15:11:26

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
----------	-------------	-----------------	----------	--------	---------	------	--------------	----------



2017-08-07 15:11:36

End of 002156 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
002157	Hole in door at lock - courtyard		Site	Open	National Glass & Glazing, Inc.	Architect Punch List	07 Aug 2017	12 Aug 2017



2017-08-07 15:13:43

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
----------	-------------	-----------------	----------	--------	---------	------	--------------	----------



2017-08-07 15:13:48


End of 002157 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
002158	Confirm why joint is larger at this location, - courtyard		Site	Open	National Glass & Glazing, Inc.	Architect Punch List	07 Aug 2017	12 Aug 2017



2017-08-07 15:16:49

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
----------	-------------	-----------------	----------	--------	---------	------	--------------	----------



2017-08-07 15:16:53

End of 002158 images

002118	Finish drywall at top of wall and seal voids at roof hatch		Webster > Roof	Open	PARIC (Self-Perform)	Architect Punch List	07 Aug 2017	12 Aug 2017
--------	--	--	----------------	------	----------------------	----------------------	-------------	-------------



Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
002137	Seal around north door frame (stair 2)		Site	Open	PARIC (Self-Perform)	Architect Punch List	07 Aug 2017	12 Aug 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
002159	Dent in door - courtyard		Site	Open	PARIC (Self-Perform)	Architect Punch List	07 Aug 2017	12 Aug 2017



2017-08-07 15:19:04

End of 002159 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
002121	Clean dirt from eab masonry - west eab connector		Site	Open	Paric Corp.	Architect Punch List	07 Aug 2017	12 Aug 2017



2017-08-07 11:33:35

End of 002121 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
002160	Need cover at drain - scope? For <u>both</u> exposed drains at each end of the seating wall.		Site	Open	Paric Corp.	Architect Punch List	07 Aug 2017	12 Aug 2017



2017-08-07 15:21:51

End of 002160 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
002164	Touchup fireproofing		Webster > LEVEL_01 > 172A_RECYCLING	Open	Phillips Co.	Architect Punch List	07 Aug 2017	12 Aug 2017



2017-08-07 16:09:16

End of 002164 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
002143	Paint pipes to match metal panels		Site	Open	Spectra Painting	Architect Punch List	07 Aug 2017	12 Aug 2017



2017-08-07 14:09:48

End of 002143 images



Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
002138	Remove excess sealant from face of brick		Site	Open	Staat Tuckpointing	Architect Punch List	07 Aug 2017	12 Aug 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
----------	-------------	-----------------	----------	--------	---------	------	--------------	----------



2017-08-07 13:56:18

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
----------	-------------	-----------------	----------	--------	---------	------	--------------	----------



2017-08-07 13:56:23

End of 002138 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
002145	Sealant needed at sky joint and horizontal joint of masonry cap		Site	Open	Staat Tuckpointing	Architect Punch List	07 Aug 2017	12 Aug 2017



2017-08-07 14:17:28

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
----------	-------------	-----------------	----------	--------	---------	------	--------------	----------



2017-08-07 14:17:30

End of 002145 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
002125	Clean concrete from base of curtainwall - west		Site	Open	Vee Jay Cement	Architect Punch List	07 Aug 2017	12 Aug 2017



2017-08-07 11:48:58

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
----------	-------------	-----------------	----------	--------	---------	------	--------------	----------



2017-08-07 11:49:02

End of 002125 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
002148	Curb needed at dumpster		Site	Open	Vee Jay Cement	Architect Punch List	07 Aug 2017	12 Aug 2017



2017-08-07 14:28:17

End of 002148 images



Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
002098	Seal gaps at coping (typical all location)		Webster > Roof	Open	VOGEL HEATING & COOLING	Architect Punch List	07 Aug 2017	12 Aug 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
----------	-------------	-----------------	----------	--------	---------	------	--------------	----------



2017-08-07 09:55:28

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
----------	-------------	-----------------	----------	--------	---------	------	--------------	----------



2017-08-07 10:20:36

End of 002098 images



Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
002103	Screws should be stainless at flashing		Webster > Roof	Open	VOGEL HEATING & COOLING	Architect Punch List	07 Aug 2017	12 Aug 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
----------	-------------	-----------------	----------	--------	---------	------	--------------	----------



2017-08-07 10:12:53

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
----------	-------------	-----------------	----------	--------	---------	------	--------------	----------



2017-08-07 10:12:56

End of 002103 images



Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
002104	Seal flashing to metal at clerestory roof		Webster > Roof	Open	VOGEL HEATING & COOLING	Architect Punch List	07 Aug 2017	12 Aug 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
----------	-------------	-----------------	----------	--------	---------	------	--------------	----------



2017-08-07 10:23:20

End of 002104 images



Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
002108	Two piece flashing to cover turn bar under glazing still needed		Webster > Roof	Open	VOGEL HEATING & COOLING	Architect Punch List	07 Aug 2017	12 Aug 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
----------	-------------	-----------------	----------	--------	---------	------	--------------	----------



2017-08-07 10:45:48

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
----------	-------------	-----------------	----------	--------	---------	------	--------------	----------



2017-08-07 10:46:04

End of 002108 images



Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
002113	Finish metal panel installation and doors		Webster > Roof	Open	VOGEL HEATING & COOLING	Architect Punch List	07 Aug 2017	12 Aug 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
----------	-------------	-----------------	----------	--------	---------	------	--------------	----------



2017-08-07 11:02:46

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
----------	-------------	-----------------	----------	--------	---------	------	--------------	----------



2017-08-07 11:02:48

End of 002113 images



Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
002115	Seal gaps where two types of coping meet		Webster > Roof	Open	VOGEL HEATING & COOLING	Architect Punch List	07 Aug 2017	12 Aug 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
----------	-------------	-----------------	----------	--------	---------	------	--------------	----------



2017-08-07 11:05:37

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
----------	-------------	-----------------	----------	--------	---------	------	--------------	----------



2017-08-07 11:05:42

End of 002115 images



Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
002116	Coping should slope onto roof, no "hump"		Webster > Roof	Open	VOGEL HEATING & COOLING	Architect Punch List	07 Aug 2017	12 Aug 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
----------	-------------	-----------------	----------	--------	---------	------	--------------	----------



2017-08-07 11:07:01

End of 002116 images



Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
002117	Missing coping at corner		Webster > Roof	Open	VOGEL HEATING & COOLING	Architect Punch List	07 Aug 2017	12 Aug 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
----------	-------------	-----------------	----------	--------	---------	------	--------------	----------



2017-08-07 11:12:06

End of 002117 images



Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
002119	Automatic door closer to be raised - eab connector		Site	Open	VOGEL HEATING & COOLING	Architect Punch List	07 Aug 2017	12 Aug 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
----------	-------------	-----------------	----------	--------	---------	------	--------------	----------



2017-08-07 11:30:41

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
----------	-------------	-----------------	----------	--------	---------	------	--------------	----------



2017-08-07 11:30:47

End of 002119 images



Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
002122	Scuffs at joint of panels - southwest corner		Site	Open	VOGEL HEATING & COOLING	Architect Punch List	07 Aug 2017	12 Aug 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
002128	Clean up marks along panel joints		Site	Open	VOGEL HEATING & COOLING	Architect Punch List	07 Aug 2017	12 Aug 2017



2017-08-07 11:56:16



Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
End of 002128 images								

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
002135	Backer rod exposed from under coping - north		Site	Open	VOGEL HEATING & COOLING	Architect Punch List	07 Aug 2017	12 Aug 2017



2017-08-07 13:47:23

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
----------	-------------	-----------------	----------	--------	---------	------	--------------	----------



2017-08-07 13:47:29

End of 002135 images



Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
002144	Joints out of alignment at metal panel intersection - east		Site	Open	VOGEL HEATING & COOLING	Architect Punch List	07 Aug 2017	12 Aug 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
----------	-------------	-----------------	----------	--------	---------	------	--------------	----------



2017-08-07 14:12:25

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
----------	-------------	-----------------	----------	--------	---------	------	--------------	----------



2017-08-07 14:12:36

End of 002144 images



Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
002146	Cover plate needed at opening above east loading dock door		Site	Open	VOGEL HEATING & COOLING	Architect Punch List	07 Aug 2017	12 Aug 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
----------	-------------	-----------------	----------	--------	---------	------	--------------	----------



2017-08-07 14:19:31

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
----------	-------------	-----------------	----------	--------	---------	------	--------------	----------



2017-08-07 14:19:40

End of 002146 images



Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
002151	Metal panel to masonry detail not per approved shops At south elevation.		Site	Open	VOGEL HEATING & COOLING	Architect Punch List	07 Aug 2017	12 Aug 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
----------	-------------	-----------------	----------	--------	---------	------	--------------	----------



2017-08-07 14:44:38

End of 002151 images



Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
002124	Paver to be replaced so that there is thinner gap at light		Site	Open	Western Specialty Contractors	Architect Punch List	07 Aug 2017	12 Aug 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
----------	-------------	-----------------	----------	--------	---------	------	--------------	----------



2017-08-07 11:47:58

Additional item: On level 02, at Grids A & 1.6, the corner mullion's triangular snap cover does not extend to the retainer clips of the yellow metal panels at the cantilever.

End of 002124 images