Webster - ISB **Level 0 Punchlist**

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001724	Sprinkler head to be secured in cabinets		Webster > LEVEL_01 > 137_MODELS/ ASSESSMENT STORAGE/RESEARCH	Open	Ahern Fire Protection	Architect Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 13:26:23



2017-07-19 13:26:27

End of 001724 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001711	Missing trench covers		Webster > LEVEL_01 > 133B_SIM LAB	Open	Atlas Iron Works	Architect Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 11:19:07

2017-07-19 11:19:18

End of 001711 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001908	Install fasteners for handrail		Webster > LEVEL_01 > S176_STAIR 3-1	Open	Atlas Iron Works	Architect Punch List	20 Jul 2017	25 Jul 2017

2017-07-20 12:17:43

End of 001908 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001716	Ensure pull out drawer is installed at all locations (missing in multiple)		Webster > LEVEL_01 > 135_DRY SKILLS LAB / COHORT CLASSROOM	Open	Carroll Seating	Architect Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 12:08:10

2017-07-19 12:08:24

End of 001716 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001717	Scratches and marks on casework		Webster > LEVEL_01 > 135_DRY SKILLS LAB / COHORT CLASSROOM	Open	Carroll Seating	Architect Punch List	19 Jul 2017	24 Jul 2017



2017-07-19 12:12:08

2017-07-19 12:12:14

End of 001717 images

001721	Mobile cabinet missing clips for shelf	Webster > LEVEL_01 > 135_DRY SKILLS LAB / COHORT CLASSROOM	Open	Carroll Seating	Architect Punch List	19 Jul 2017	24 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001722	All cabinet shelves to be adjusted so they do not wiggle		Webster > LEVEL_01 > 137_MODELS/ ASSESSMENT STORAGE/RESEARCH	Open	Carroll Seating	Architect Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 13:22:40

End of 001722 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001723	Missing filler panel		Webster > LEVEL_01 > 137_MODELS/ ASSESSMENT STORAGE/RESEARCH	Open	Carroll Seating	Architect Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 13:23:12

End of 001723 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001725	Flaw in face of cabinet		Webster > LEVEL_01 > 137_MODELS/ ASSESSMENT STORAGE/RESEARCH	Open	Carroll Seating	Architect Punch List	19 Jul 2017	24 Jul 2017



2017-07-19 13:27:12

End of 001725 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001732	Install grommets in countertops		Webster > LEVEL_01 > 133A_CONTROL ROOM / TECH OFF / PREP LAB	Open	Carroll Seating	Architect Punch List	19 Jul 2017	24 Jul 2017



2017-07-19 14:14:36

2017-07-19 14:14:40

End of 001732 images

001733	Missing latch	Webster > LEVEL_01 > 133A_CONTROL ROOM / TECH OFF / PREP LAB	Open	Carroll Seating	Architect Punch List	19 Jul 2017	24 Jul 2017
001734	Screws exposed on shelf	Webster > LEVEL_01 > 133A_CONTROL ROOM / TECH OFF / PREP LAB	Open	Carroll Seating	Architect Punch List	19 Jul 2017	24 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001891	Adjust cabinet doors		Webster > LEVEL_01 > 191_CADAVER LAB	Open	Carroll Seating	Architect Punch List	20 Jul 2017	25 Jul 2017

2017-07-20 11:47:25

End of 001891 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001894	Shelf missing		Webster > LEVEL_01 > 191_CADAVER LAB	Open	Carroll Seating	Architect Punch List	20 Jul 2017	25 Jul 2017

2017-07-20 11:49:48

End of 001894 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001897	Chip in shelf		Webster > LEVEL_01 > 183C_BIO VESTIBULE	Open	Carroll Seating	Architect Punch List	20 Jul 2017	25 Jul 2017

2017-07-20 11:52:09

End of 001897 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001772	Finish insulating domestic water piping		Webster > LEVEL_01 > 178_MECHANICAL ROOM	Open	Deluca Plumbing	Engineer Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 13:55:37

End of 001772 images

001773	Domestic water pipe insulation not continuous	Webster > LEVEL_01 > 178_MECHANICAL ROOM	Open	Deluca Plumbing	Engineer Punch List	19 Jul 2017	24 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001890	Missing paper towel dispenser		Webster > LEVEL_01 > 191_CADAVER LAB	Open	Deluca Plumbing	Architect Punch List	20 Jul 2017	25 Jul 2017

2017-07-20 11:46:37

End of 001890 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001662	Fix base so that cabinet doors and pocket doors are operable		Webster > LEVEL_01 > 100C_K'ETTE	Open	Flooring Systems, Inc.	Architect Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 09:30:26

2017-07-19 09:36:25

End of 001662 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001663	Fix holes in grout		Webster > LEVEL_01 > 100C_K'ETTE	Open	Flooring Systems, Inc.	Architect Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 09:31:21

End of 001663 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001747	Threshold needed		Webster > LEVEL_01 > 160_LECTURE HALL	Open	Flooring Systems, Inc.	Architect Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 15:23:52

End of 001747 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001751	Flooring needed at stage, stairs, and sloped wall		Webster > LEVEL_01 > 160_LECTURE HALL	Open	Flooring Systems, Inc.	Architect Punch List	19 Jul 2017	24 Jul 2017



2017-07-19 15:28:12

2017-07-19 15:28:24

End of 001751 images

001837	Repair carpet		Webster > LEVEL_01 > 154_CONF ROOM (10)	Open	Flooring Systems, Inc.	Architect Punch List	20 Jul 2017	25 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001866	Patch all grout holes		Webster > LEVEL_01 > 179_MEN	Open	Flooring Systems, Inc.	Architect Punch List	20 Jul 2017	25 Jul 2017

2017-07-20 11:22:08

End of 001866 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001879	Chips in tile		Webster > LEVEL_01 > 180_TOILET	Open	Flooring Systems, Inc.	Architect Punch List	20 Jul 2017	25 Jul 2017

2017-07-20 11:36:34

End of 001879 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001667	Remove plastic from lights		Webster > LEVEL_01 > 101_OFF. STAFF (2)	Open	Guarantee Electric	Architect Punch List	19 Jul 2017	24 Jul 2017



2017-07-19 09:38:16

End of 001667 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001687	Seal penetration		Webster > LEVEL_01 > 110B_ELEC	Open	Guarantee Electric	Architect Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 10:32:36

End of 001687 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001729	Lower raceway to top of backsplash (creating dust pocket), backer rod and sealant needed at void		Webster > LEVEL_01 > 133A_CONTROL ROOM / TECH OFF / PREP LAB	Open	Guarantee Electric	Architect Punch List	19 Jul 2017	24 Jul 2017



2017-07-19 14:09:27

2017-07-19 14:16:01

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-19 14:16:09

End of 001729 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001742	Lights need to be straight (in line with ceilings)		Webster > LEVEL_01 > 160_LECTURE HALL	Open	Guarantee Electric	Architect Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 15:14:35

End of 001742 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001754	Install switch cover		Webster > LEVEL_01 > 160B_CONTROL	Open	Guarantee Electric	Architect Punch List	19 Jul 2017	24 Jul 2017



2017-07-19 15:32:11

End of 001754 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001815	Seal floor penetrations in structure above		Webster > LEVEL_01 > 110B_ELEC	Open	Guarantee Electric	Engineer Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 15:29:32

End of 001815 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001819	Lights to align to west edge of ceiling to eliminate gap		Webster > LEVEL_01 > 160_LECTURE HALL	Open	Guarantee Electric	Architect Punch List	20 Jul 2017	25 Jul 2017



2017-07-20 09:48:29

End of 001819 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001853	Eliminate gap at end of cove light		Webster > LEVEL_01 > C140_CORRIDOR	Open	Guarantee Electric	Architect Punch List	20 Jul 2017	25 Jul 2017



2017-07-20 10:57:26

End of 001853 images

001856	Eliminate gap at the end of cove light	Webster > LEVEL_01 > C170_CORRIDOR	Open	Guarantee Electric	Architect Punch List	20 Jul 2017	25 Jul 2017
001861	Missing electrical outlet at end of island	Webster > LEVEL_01 > 174_TEACHING KITCHEN	Open	Guarantee Electric	Architect Punch List	20 Jul 2017	25 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001862	Missing electrical outlets at open knee space (2 locations)		Webster > LEVEL_01 > 174_TEACHING KITCHEN	Open	Guarantee Electric	Architect Punch List	20 Jul 2017	25 Jul 2017



2017-07-20 11:15:09

End of 001862 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001887	Move wiremold down to backsplash		Webster > LEVEL_01 > 183B_CADAVER LAB WORKROOM	Open	Guarantee Electric	Architect Punch List	20 Jul 2017	25 Jul 2017



2017-07-20 11:43:43

End of 001887 images

001928	In main electrical room, provide nameplate on panel 1SL1-A.		Webster > LEVEL_01	Open	Guarantee Electric	Engineer Punch List	20 Jul 2017	25 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001929	In main electrical room, install covers over open pull boxes and junction boxes.		Webster > LEVEL_01	Open	Guarantee Electric	Engineer Punch List	20 Jul 2017	25 Jul 2017



2017-07-19 11:04:17

End of 001929 images

001930	In main electrical room, install cover on panel 1NL2.	Webster > LEVEL_01	Open	Guarantee Electric	Engineer Punch List	20 Jul 2017	25 Jul 2017
001931	In MDF 195, provide covers over open junction boxes.	Webster > LEVEL_01	Open	Guarantee Electric	Engineer Punch List	20 Jul 2017	25 Jul 2017
001932	In Cylinder Room 187, install missing receptacle.	Webster > LEVEL_01	Open	Guarantee Electric	Engineer Punch List	20 Jul 2017	25 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001933	In Spill Closet 185, cover open junction box.		Webster > LEVEL_01	Open	Guarantee Electric	Engineer Punch List	20 Jul 2017	25 Jul 2017
001934	In JC 175, fill conduit wall penetrations.		Webster > LEVEL_01	Open	Guarantee Electric	Engineer Punch List	20 Jul 2017	25 Jul 2017
001935	In Teaching Kitchen 174, install missing receptacle for computer. Receptacles marked with E24 are not in the location indicated by architect.		Webster > LEVEL_01	Open	Guarantee Electric	Engineer Punch List	20 Jul 2017	25 Jul 2017
001936	In Teaching Kitchen 174, the lighting control keypad is being covered up by the Television. Swap keypads or relocate obstructed keypad. Coordinate with owner.		Webster > LEVEL_01	Open	Guarantee Electric	Engineer Punch List	20 Jul 2017	25 Jul 2017
001937	In Cadaver Lab 191, one of the light fixtures is dim. Confirm fixture is operating correctly.		Webster > LEVEL_01	Open	Guarantee Electric	Engineer Punch List	20 Jul 2017	25 Jul 2017
001939	In EAB Connector, install missing Type WA fixture lenses.		Webster > LEVEL_01	Open	Guarantee Electric	Engineer Punch List	20 Jul 2017	25 Jul 2017
001940	In Health Assessment 131, a number of junction boxes are installed but the devices are missing. Install missing devices.		Webster > LEVEL_01	Open	Guarantee Electric	Engineer Punch List	20 Jul 2017	25 Jul 2017
001942	In AV Equip 160D, install missing general purpose receptacle.		Webster > LEVEL_01	Open	Guarantee Electric	Engineer Punch List	20 Jul 2017	25 Jul 2017
001944	In the Lecture Hall, the lighting control keypads are missing. The lighting operation has not been observed.		Webster > LEVEL_01	Open	Guarantee Electric	Engineer Punch List	20 Jul 2017	25 Jul 2017
001945	In Lecture Entry 160C, install Type RB4 light fixture and lighting control keypad.		Webster > LEVEL_01	Open	Guarantee Electric	Engineer Punch List	20 Jul 2017	25 Jul 2017
001946	In Vest C153, install missing lenses.		Webster > LEVEL_01	Open	Guarantee Electric	Engineer Punch List	20 Jul 2017	25 Jul 2017
001947	In Lobby C150, replace inoperable Type RR fixture section.		Webster > LEVEL_01	Open	Guarantee Electric	Engineer Punch List	20 Jul 2017	25 Jul 2017
001948	In Corridor C140, install missing downlights.		Webster > LEVEL_01	Open	Guarantee Electric	Engineer Punch List	20 Jul 2017	25 Jul 2017
001949	In Office Staff 101, relocate switch so it’s not behind the door.		Webster > LEVEL_01	Open	Guarantee Electric	Engineer Punch List	20 Jul 2017	25 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001771	Combustion Air Piping not properly supported. Support piping per spec.		Webster > LEVEL_01 > 178_MECHANICAL ROOM	Open	ICON Mechanical	Engineer Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 13:54:23

End of 001771 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001776	Install boiler safety switch and sign per contract documents.		Webster > LEVEL_01 > 178_MECHANICAL ROOM	Open	ICON Mechanical	Engineer Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 14:02:39

End of 001776 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001777	Seal gas pipe penetration into building		Webster > LEVEL_01	Open	ICON Mechanical	Engineer Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 14:04:56

End of 001777 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001788	First supply diffuser off of Box is not currently installed. Install Per contract documents		Webster > LEVEL_01 > 183C_BIO VESTIBULE	Open	ICON Mechanical	Engineer Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 14:27:23

End of 001788 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001795	Patch and seal wall penetrations as required		Webster > LEVEL_01 > 172A_RECYCLING	Open	ICON Mechanical	11 Month Warranty Walk	19 Jul 2017	24 Jul 2017



2017-07-19 14:38:13

End of 001795 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001799	Install CO2 sensor clean thermostat for VAV-110		Webster > LEVEL_01 > 131_HEALTH ASSESSMENT LAB	Open	ICON Mechanical	Engineer Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 14:49:10

End of 001799 images

001801	Verify thermostat is combo type with CO2 sensor.	Webster > LEVEL_01 > 135_DRY SKILLS LAB / COHORT CLASSROOM	Open	ICON Mechanical	Engineer Punch List	19 Jul 2017	24 Jul 2017
001802	Supplier diffuser plaque is crooked. Adjust as required.	Webster > LEVEL_01	Open	ICON Mechanical	Engineer Punch List	19 Jul 2017	24 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001804	Finish sensor installations		Webster > LEVEL_01 > 140_CONF. ROOM (24 SEATS)	Open	ICON Mechanical	Engineer Punch List	19 Jul 2017	24 Jul 2017



2017-07-19 15:00:04

End of 001804 images

001806	Install thermostat for cabinet unit heater and vestibule		Webster > LEVEL_01 > C153_VEST.	Open	ICON Mechanical	Engineer Punch List	19 Jul 2017	24 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001807	Confirm thermostat is combination type with CO2 sensor.		Webster > LEVEL_01 > 160_LECTURE HALL	Open	ICON Mechanical	Engineer Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 15:04:25

End of 001807 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001813	Finish installing thermostat for VA V – 118 which is loose		Webster > LEVEL_01 > C151_COMMONS	Open	ICON Mechanical	Engineer Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 15:22:50

End of 001813 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001739	Custom terrazzo base needed at column		Webster > LEVEL_01 > C130_CORRIDOR	Open	Missouri Terrazzo Co.	Architect Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 14:37:23

End of 001739 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001693	Scuffs on aluminum framing		Webster > LEVEL_01 > 111_OFF. NU	Open	National Glass & Glazing, Inc.	Architect Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 10:37:03

End of 001693 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001707	Gaps in covers too large		Webster > LEVEL_01 > 115_OFF. NU	Open	National Glass & Glazing, Inc.	Architect Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 11:09:51

End of 001707 images

001708	Gaps in covers too large	Webster > LEVEL_01 > 113_OFF. NU	Open	National Glass & Glazing, Inc.	Architect Punch List	19 Jul 2017	24 Jul 2017
001720	Backer rod and sealant needed	Webster > LEVEL_01 > 135_DRY SKILLS LAB / COHORT CLASSROOM	Open	National Glass & Glazing, Inc.	Architect Punch List	19 Jul 2017	24 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001738	Remove decals from doors		Webster > LEVEL_01 > 133A_CONTROL ROOM / TECH OFF / PREP LAB	Open	National Glass & Glazing, Inc.	Architect Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 14:34:40

End of 001738 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001753	Install window		Webster > LEVEL_01 > 160_LECTURE HALL	Open	National Glass & Glazing, Inc.	Architect Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 15:31:40

End of 001753 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001824	Gap in aluminum trim		Webster > LEVEL_01 > 156_SM MTG/ GREEN RM	Open	National Glass & Glazing, Inc.	Architect Punch List	20 Jul 2017	25 Jul 2017



2017-07-20 09:58:52

End of 001824 images

001825	Repair aluminum trim		Webster > LEVEL_01 > 156_SM MTG/ GREEN RM	Open	National Glass & Glazing, Inc.	Architect Punch List	20 Jul 2017	25 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001826	Missing silicon at store front windows		Webster > LEVEL_01 > 156_SM MTG/ GREEN RM	Open	National Glass & Glazing, Inc.	Architect Punch List	20 Jul 2017	25 Jul 2017

2017-07-20 10:01:35

End of 001826 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001835	Repair aluminum trim		Webster > LEVEL_01 > 154_CONF ROOM (10)	Open	National Glass & Glazing, Inc.	Architect Punch List	20 Jul 2017	25 Jul 2017

2017-07-20 10:13:13

End of 001835 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001851	Repair aluminum trim		Webster > LEVEL_01 > 144_OFF. NU / NA ADJ.	Open	National Glass & Glazing, Inc.	Architect Punch List	20 Jul 2017	25 Jul 2017

2017-07-20 10:54:51

End of 001851 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001847	Metal panel not flush at elevator 1		Webster > LEVEL_01 > C170_CORRIDOR	Open	Otis Elevator Company	Architect Punch List	20 Jul 2017	25 Jul 2017

2017-07-20 10:28:43

End of 001847 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001660	Repair drywall		Webster > LEVEL_01 > 100C_K'ETTE	Open	PARIC (Self-Perform)	Architect Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 09:28:59

2017-07-19 09:35:59

End of 001660 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001661	Seal countertops to walls		Webster > LEVEL_01 > 100C_K'ETTE	Open	PARIC (Self-Perform)	Architect Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 09:29:42

2017-07-19 09:29:46

End of 001661 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001664	Install cabinet doors		Webster > LEVEL_01 > 100C_K'ETTE	Open	PARIC (Self-Perform)	Architect Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 09:32:19

End of 001664 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001666	Cover needed to hide interior components of pocket door, possibly break metal		Webster > LEVEL_01 > 100C_K'ETTE	Open	PARIC (Self-Perform)	Architect Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 09:34:53

End of 001666 images

001669	Damaged door	Webster > LEVEL_01 > 101_OFF. STAFF (2)	Open	PARIC (Self-Perform)	Architect Punch List	19 Jul 2017	24 Jul 2017
001679	Damaged door	Webster > LEVEL_01 > 109_OFF. NU	Open	PARIC (Self-Perform)	Architect Punch List	19 Jul 2017	24 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001694	Damaged door		Webster > LEVEL_01 > 111_OFF. NU	Open	PARIC (Self-Perform)	Architect Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 10:37:31

2017-07-19 10:37:36

End of 001694 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001697	Seal countertops to wall		Webster > LEVEL_01 > 114_MOCK EXAM	Open	PARIC (Self-Perform)	Architect Punch List	19 Jul 2017	24 Jul 2017



2017-07-19 10:49:02

End of 001697 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001698	Adjust cabinet doors to be flush		Webster > LEVEL_01 > 114_MOCK EXAM	Open	PARIC (Self-Perform)	Architect Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 10:49:41

End of 001698 images

001699	Computer mounting arm and coat hooks missing (shipping end of month)	Webster > LEVEL_01 > 114_MOCK EXAM	Open	PARIC (Self-Perform)	Architect Punch List	19 Jul 2017	24 Jul 2017
001702	Handle mounted incorrectly	Webster > LEVEL_01 > 116_MOCK EXAM	Open	PARIC (Self-Perform)	Architect Punch List	19 Jul 2017	24 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001706	Damaged door		Webster > LEVEL_01 > 116_MOCK EXAM	Open	PARIC (Self-Perform)	Architect Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 11:08:26

End of 001706 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001714	Missing door silencers		Webster > LEVEL_01 > 133B_SIM LAB	Open	PARIC (Self-Perform)	Architect Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 11:44:22

End of 001714 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001740	Wall built incorrectly, should be fire rated per arch detail		Webster > LEVEL_01 > 160_LECTURE HALL	Open	PARIC (Self-Perform)	Architect Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 15:11:23

End of 001740 images

001745	Screws needed in exterior door jamb		Webster > LEVEL_01 > 160_LECTURE HALL	Open	PARIC (Self-Perform)	Architect Punch List	19 Jul 2017	24 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001746	No light should be visible when door is closed		Webster > LEVEL_01 > 160_LECTURE HALL	Open	PARIC (Self-Perform)	Architect Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 15:22:57

2017-07-19 15:23:00

End of 001746 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001748	Base at grills to be corrected per observation report 14		Webster > LEVEL_01 > 160_LECTURE HALL	Open	PARIC (Self-Perform)	Architect Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 15:25:57

End of 001748 images

001750	Subwoofer fabric needed	Webster > LEVEL_01 > 160_LECTURE HALL	Open	PARIC (Self-Perform)	Architect Punch List	19 Jul 2017	24 Jul 2017
001752	Install wall panel (cut to fit below equipment)	Webster > LEVEL_01 > 160_LECTURE HALL	Open	PARIC (Self-Perform)	Architect Punch List	19 Jul 2017	24 Jul 2017
001803	Clean rough edges on slot diffusers	Webster > LEVEL_01 > 140_CONF. ROOM (24 SEATS)	Open	PARIC (Self-Perform)	Engineer Punch List	19 Jul 2017	24 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001816	Damaged door frames		Webster > LEVEL_01 > 160A_CORR.	Open	PARIC (Self-Perform)	Architect Punch List	20 Jul 2017	25 Jul 2017



2017-07-20 09:45:43

2017-07-20 09:46:07

End of 001816 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001820	Coordinate wood panels with window frame		Webster > LEVEL_01 > 160B_CONTROL	Open	PARIC (Self-Perform)	Architect Punch List	20 Jul 2017	25 Jul 2017



2017-07-20 09:54:37

End of 001820 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001821	Damaged door frames		Webster > LEVEL_01 > 156_SM MTG/ GREEN RM	Open	PARIC (Self-Perform)	Architect Punch List	20 Jul 2017	25 Jul 2017

2017-07-20 09:55:33

End of 001821 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001828	Top of entry not finished		Webster > LEVEL_01 > 158_COAT	Open	PARIC (Self-Perform)	Architect Punch List	20 Jul 2017	25 Jul 2017



2017-07-20 10:04:38

End of 001828 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001832	Seal countertop to wall		Webster > LEVEL_01 > 154_CONF ROOM (10)	Open	PARIC (Self-Perform)	Architect Punch List	20 Jul 2017	25 Jul 2017

2017-07-20 10:09:18

End of 001832 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001833	Repair touch latches		Webster > LEVEL_01 > 154_CONF ROOM (10)	Open	PARIC (Self-Perform)	Architect Punch List	20 Jul 2017	25 Jul 2017



2017-07-20 10:10:00

End of 001833 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001840	Top on entry not finished		Webster > LEVEL_01 > 154_CONF ROOM (10)	Open	PARIC (Self-Perform)	Architect Punch List	20 Jul 2017	25 Jul 2017

2017-07-20 10:17:56

End of 001840 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001842	Repair damaged wood panels		Webster > LEVEL_01 > C151_COMMONS	Open	PARIC (Self-Perform)	Architect Punch List	20 Jul 2017	25 Jul 2017

2017-07-20 10:20:50

End of 001842 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001844	Panel is not flush		Webster > LEVEL_01 > C151_COMMONS	Open	PARIC (Self-Perform)	Architect Punch List	20 Jul 2017	25 Jul 2017

2017-07-20 10:23:05

End of 001844 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001845	Wood panel is not flush		Webster > LEVEL_01 > 152_VENDING	Open	PARIC (Self-Perform)	Architect Punch List	20 Jul 2017	25 Jul 2017

2017-07-20 10:24:44

End of 001845 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001846	Panel not properly cut		Webster > LEVEL_01 > C150_LOBBY	Open	PARIC (Self-Perform)	Architect Punch List	20 Jul 2017	25 Jul 2017

2017-07-20 10:26:04

End of 001846 images

001848	Seal gap at elevator 1		Webster > LEVEL_01 > C170_CORRIDOR	Open	PARIC (Self-Perform)	Architect Punch List	20 Jul 2017	25 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001850	Missing screws		Webster > LEVEL_01 > 156_SM MTG/ GREEN RM	Open	PARIC (Self-Perform)	Architect Punch List	20 Jul 2017	25 Jul 2017

2017-07-20 10:53:41

End of 001850 images

001852	Repair scuff marks, paint, and scratches in wood paneling	Webster > LEVEL_01 > C140_CORRIDOR	Open	PARIC (Self-Perform)	Architect Punch List	20 Jul 2017	25 Jul 2017
001854	Repair chips in paneling trim	Webster > LEVEL_01 > C140_CORRIDOR	Open	PARIC (Self-Perform)	Architect Punch List	20 Jul 2017	25 Jul 2017
001855	Repair chips in wood paneling	Webster > LEVEL_01 > C170_CORRIDOR	Open	PARIC (Self-Perform)	Architect Punch List	20 Jul 2017	25 Jul 2017
001857	Missing aluminum trim at wood panels	Webster > LEVEL_01 > C170_CORRIDOR	Open	PARIC (Self-Perform)	Architect Punch List	20 Jul 2017	25 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001858	Water damage at EAB connector door		Webster > LEVEL_01 > C170_CORRIDOR	Open	PARIC (Self-Perform)	Architect Punch List	20 Jul 2017	25 Jul 2017
001864	Scratch on mirror		Webster > LEVEL_01 > 179_MEN	Open	PARIC (Self-Perform)	Architect Punch List	20 Jul 2017	25 Jul 2017



2017-07-20 11:20:21

End of 001864 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001865	Chip in j-channel		Webster > LEVEL_01 > 179_MEN	Open	PARIC (Self-Perform)	Architect Punch List	20 Jul 2017	25 Jul 2017



2017-07-20 11:21:11

End of 001865 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001870	Multiple chips in door		Webster > LEVEL_01 > 179_MEN	Open	PARIC (Self-Perform)	Architect Punch List	20 Jul 2017	25 Jul 2017

2017-07-20 11:26:26

End of 001870 images

001871	Rubber frame gasget missing		Webster > LEVEL_01 > 179_MEN	Open	PARIC (Self-Perform)	Architect Punch List	20 Jul 2017	25 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001872	No door lock needed		Webster > LEVEL_01 > 177_WOMEN	Open	PARIC (Self-Perform)	Architect Punch List	20 Jul 2017	25 Jul 2017



2017-07-20 11:29:42

End of 001872 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001873	Damaged door frames		Webster > LEVEL_01 > 177_WOMEN	Open	PARIC (Self-Perform)	Architect Punch List	20 Jul 2017	25 Jul 2017

2017-07-20 11:30:06

End of 001873 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001874	Chips in door		Webster > LEVEL_01 > 177_WOMEN	Open	PARIC (Self-Perform)	Architect Punch List	20 Jul 2017	25 Jul 2017

2017-07-20 11:31:24

End of 001874 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001875	Counter sealant missing		Webster > LEVEL_01 > 177_WOMEN	Open	PARIC (Self-Perform)	Architect Punch List	20 Jul 2017	25 Jul 2017

2017-07-20 11:32:15

End of 001875 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001876	Counter sealant missing		Webster > LEVEL_01 > 179_MEN	Open	PARIC (Self-Perform)	Architect Punch List	20 Jul 2017	25 Jul 2017



2017-07-20 11:33:10

End of 001876 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001878	Mirror missing		Webster > LEVEL_01 > 180_TOILET	Open	PARIC (Self-Perform)	Architect Punch List	20 Jul 2017	25 Jul 2017



2017-07-20 11:35:47

End of 001878 images

001882	Mirror missing		Webster > LEVEL_01 > 182_TOILET	Open	PARIC (Self-Perform)	Architect Punch List	20 Jul 2017	25 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001885	Damaged door frame		Webster > LEVEL_01 > 182_TOILET	Open	PARIC (Self-Perform)	Architect Punch List	20 Jul 2017	25 Jul 2017

2017-07-20 11:41:19

End of 001885 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001898	Polish countertop edges		Webster > LEVEL_01 > 183C_BIO VESTIBULE	Open	PARIC (Self-Perform)	Architect Punch List	20 Jul 2017	25 Jul 2017

2017-07-20 11:52:56

End of 001898 images

001907	Close the ends of the stair stringers		Webster > LEVEL_01 > S176_STAIR 3-1	Open	PARIC (Self-Perform)	Architect Punch List	20 Jul 2017	25 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001910	Provide fire rated sealant between CMU wall and floor		Webster > LEVEL_01 > S176_STAIR 3-1	Open	PARIC (Self-Perform)	Architect Punch List	20 Jul 2017	25 Jul 2017

2017-07-20 12:19:31

End of 001910 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001911	Provide fire rated sealant between drywall and floor		Webster > LEVEL_01 > S176_STAIR 3-1	Open	PARIC (Self-Perform)	Architect Punch List	20 Jul 2017	25 Jul 2017

2017-07-20 12:20:59

End of 001911 images

001938	In Toilet 182, patch drywall around downlight.	Webster > LEVEL_01	Open	PARIC (Self-Perform)	Engineer Punch List	20 Jul 2017	25 Jul 2017
001943	In the Lecture Hall, there is a large gap between the Type RC fixtures and the wall. Extend wall up/into RC fixture or provide trim piece to complete installation.	Webster > LEVEL_01	Open	PARIC (Self-Perform)	Engineer Punch List	20 Jul 2017	25 Jul 2017
001909	Provide fire rated closure	Webster > LEVEL_01 > S176_STAIR 3-1	Open	Paric Corp.	Architect Punch List	20 Jul 2017	25 Jul 2017

Webster - ISB **Level 0 Punchlist**

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001927	In Stair 2, provide missing Fire Alarm ceiling access panel.		Webster > LEVEL_01	Open	Paric Corp.	Engineer Punch List	20 Jul 2017	25 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001659	Repaint entire kitchen area/ add cork board and writeable paint surface		Webster > LEVEL_01 > 100C_K'ETTE	Open	Spectra Painting	Architect Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 09:27:46

2017-07-19 09:27:51

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-19 09:27:55

End of 001659 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001670	Finish wall coverings		Webster > LEVEL_01 > 101_OFF. STAFF (2)	Open	Spectra Painting	Architect Punch List	19 Jul 2017	24 Jul 2017



2017-07-19 09:42:00

End of 001670 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001671	Repaint walls as needed		Webster > LEVEL_01 > 105_OFF. NA	Open	Spectra Painting	Architect Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 09:54:04



2017-07-19 09:54:11

End of 001671 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001673	Repaint walls as needed		Webster > LEVEL_01 > 106_OFF. NA	Open	Spectra Painting	Architect Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 09:55:38

2017-07-19 09:55:51

End of 001673 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001675	Repaint walls as needed		Webster > LEVEL_01 > 108_OFF. NU	Open	Spectra Painting	Architect Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 09:58:29

2017-07-19 09:58:55

End of 001675 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001678	Repaint walls as needed		Webster > LEVEL_01 > 109_OFF. NU	Open	Spectra Painting	Architect Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 10:04:00

2017-07-19 10:04:07

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-19 10:04:18

End of 001678 images

001680	Repaint walls as needed		Webster > LEVEL_01 > 107_OFF. NU	Open	Spectra Painting	Architect Punch List	19 Jul 2017	24 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001681	Repaint walls as needed		Webster > LEVEL_01 > 109_OFF. NU	Open	Spectra Painting	Architect Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 10:07:16

2017-07-19 10:07:24

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-19 10:07:32

End of 001681 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001683	Repaint walls as needed		Webster > LEVEL_01 > 111_OFF. NU	Open	Spectra Painting	Architect Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 10:28:19

End of 001683 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001685	Remove paint from carpet		Webster > LEVEL_01 > 111_OFF. NU	Open	Spectra Painting	Architect Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 10:30:24

End of 001685 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001686	Repaint walls as needed		Webster > LEVEL_01 > 110B_ELEC	Open	Spectra Painting	Architect Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 10:31:52

2017-07-19 10:32:02

End of 001686 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001688	Repaint walls as needed		Webster > LEVEL_01 > 112_STORAGE	Open	Spectra Painting	Architect Punch List	19 Jul 2017	24 Jul 2017



2017-07-19 10:33:53

2017-07-19 10:34:03

End of 001688 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001689	Replace damaged ceiling tile		Webster > LEVEL_01 > 112_STORAGE	Open	Spectra Painting	Architect Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 10:34:22

End of 001689 images

001690	Repaint walls as needed		Webster > LEVEL_01 > 112_STORAGE	Open	Spectra Painting	Architect Punch List	19 Jul 2017	24 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001692	Repaint walls as needed		Webster > LEVEL_01 > 111_OFF. NU	Open	Spectra Painting	Architect Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 10:35:55

2017-07-19 10:36:13

End of 001692 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001696	Repaint walls as needed		Webster > LEVEL_01 > 113_OFF. NU	Open	Spectra Painting	Architect Punch List	19 Jul 2017	24 Jul 2017



2017-07-19 10:40:01

End of 001696 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001701	Repaint walls as needed		Webster > LEVEL_01 > 114_MOCK EXAM	Open	Spectra Painting	Architect Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 10:54:02

2017-07-19 10:54:11

End of 001701 images

001704	Repaint walls as needed		Webster > LEVEL_01 > 116_MOCK EXAM	Open	Spectra Painting	Architect Punch List	19 Jul 2017	24 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001709	Repaint walls as needed		Webster > LEVEL_01 > 117_OFF. FUT	Open	Spectra Painting	Architect Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 11:15:26

End of 001709 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001712	Repaint walls as needed		Webster > LEVEL_01 > 133B_SIM LAB	Open	Spectra Painting	Architect Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 11:22:11

2017-07-19 11:22:14

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-19 11:22:18

2017-07-19 11:22:20

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-19 11:37:58

End of 001712 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001719	Repaint walls as needed		Webster > LEVEL_01 > 135_DRY SKILLS LAB / COHORT CLASSROOM	Open	Spectra Painting	Architect Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 12:13:23

2017-07-19 12:13:27

End of 001719 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001727	Repaint walls as needed		Webster > LEVEL_01 > 137_MODELS/ ASSESSMENT STORAGE/RESEARCH	Open	Spectra Painting	Architect Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 13:28:16

End of 001727 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001731	Repaint walls as needed		Webster > LEVEL_01 > 133A_CONTROL ROOM / TECH OFF / PREP LAB	Open	Spectra Painting	Architect Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 14:11:39

End of 001731 images

001735	Walltalker needed on east wall		Webster > LEVEL_01 > 133A_CONTROL ROOM / TECH OFF / PREP LAB	Open	Spectra Painting	Architect Punch List	19 Jul 2017	24 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001737	Repaint walls as needed		Webster > LEVEL_01 > 133A_CONTROL ROOM / TECH OFF / PREP LAB	Open	Spectra Painting	Architect Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 14:34:01



2017-07-19 14:34:10

End of 001737 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001781	Clean paint off of all thermostats		Webster > LEVEL_01	Open	Spectra Painting	Engineer Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 14:12:19

End of 001781 images

001789	Clean paint off of access door in ceiling of women's restroom		Webster > LEVEL_01 > 177_WOMEN	Open	Spectra Painting	Engineer Punch List	19 Jul 2017	24 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001798	Clean paint off of thermostat for VA V – 105		Webster > LEVEL_01 > 100A_WORK / COPY	Open	Spectra Painting	Engineer Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 14:44:39

End of 001798 images

001808	Clean white paint off of black parts of slot diffusers		Webster > LEVEL_01 > 160_LECTURE HALL	Open	Spectra Painting	Engineer Punch List	19 Jul 2017	24 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001809	Clean paint splatter off of diffuser		Webster > LEVEL_01 > 160D_AV EQUIP	Open	Spectra Painting	Engineer Punch List	19 Jul 2017	24 Jul 2017



2017-07-19 15:12:57

End of 001809 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001812	Clean paint off of thermostat for VA V – 121		Webster > LEVEL_01 > 156_SM MTG/ GREEN RM	Open	Spectra Painting	Engineer Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 15:20:50

End of 001812 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001817	Repair paint scuff marks, drips, and damages		Webster > LEVEL_01 > 160A_CORR.	Open	Spectra Painting	Architect Punch List	20 Jul 2017	25 Jul 2017

2017-07-20 09:44:13

End of 001817 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001822	Repair paint scuff marks, drips, and damages		Webster > LEVEL_01 > 156_SM MTG/ GREEN RM	Open	Spectra Painting	Architect Punch List	20 Jul 2017	25 Jul 2017



2017-07-20 09:56:50

End of 001822 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001827	Shelf supports not finished		Webster > LEVEL_01 > 158_COAT	Open	Spectra Painting	Architect Punch List	20 Jul 2017	25 Jul 2017

2017-07-20 10:03:27

End of 001827 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001829	Repair paint scuff marks, drips, and damages		Webster > LEVEL_01 > 158_COAT	Open	Spectra Painting	Architect Punch List	20 Jul 2017	25 Jul 2017

2017-07-20 10:05:27

End of 001829 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001831	Repair paint scuff marks, drips, and damages		Webster > LEVEL_01 > 154_CONF ROOM (10)	Open	Spectra Painting	Architect Punch List	20 Jul 2017	25 Jul 2017



2017-07-20 10:08:12

End of 001831 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001838	Repair paint scuff marks, drips, and damages		Webster > LEVEL_01 > 154_CONF ROOM (10)	Open	Spectra Painting	Architect Punch List	20 Jul 2017	25 Jul 2017

2017-07-20 10:16:25

End of 001838 images

001860	Seal concrete floor where necessary		Webster > LEVEL_01	Open	Spectra Painting	Architect Punch List	20 Jul 2017	25 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001868	Access panel not to be painted		Webster > LEVEL_01 > 179_MEN	Open	Spectra Painting	Architect Punch List	20 Jul 2017	25 Jul 2017

2017-07-20 11:24:43

End of 001868 images

001869	Repair paint scuff marks, drips, and damages		Webster > LEVEL_01 > 179_MEN	Open	Spectra Painting	Architect Punch List	20 Jul 2017	25 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001877	Repair paint scuff marks, drips, and damages		Webster > LEVEL_01 > 177_WOMEN	Open	Spectra Painting	Architect Punch List	20 Jul 2017	25 Jul 2017

2017-07-20 11:34:24

End of 001877 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001880	Repair paint scuff marks, drips, and damages		Webster > LEVEL_01 > 180_TOILET	Open	Spectra Painting	Architect Punch List	20 Jul 2017	25 Jul 2017

2017-07-20 11:36:55

End of 001880 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001881	Paint door		Webster > LEVEL_01 > 185_SPILL CLOSET	Open	Spectra Painting	Architect Punch List	20 Jul 2017	25 Jul 2017

2017-07-20 11:38:35

End of 001881 images

001883	Repair paint scuff marks, drips, and damages	Webster > LEVEL_01 > 182_TOILET	Open	Spectra Painting	Architect Punch List	20 Jul 2017	25 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001888	Walls are not complete		Webster > LEVEL_01 > 183B_CADAVER LAB WORKROOM	Open	Spectra Painting	Architect Punch List	20 Jul 2017	25 Jul 2017



2017-07-20 11:45:03

End of 001888 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001893	Walls are not complete		Webster > LEVEL_01 > 191_CADAVER LAB	Open	Spectra Painting	Architect Punch List	20 Jul 2017	25 Jul 2017



2017-07-20 11:49:13

End of 001893 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001896	Walls not complete		Webster > LEVEL_01 > 183C_BIO VESTIBULE	Open	Spectra Painting	Architect Punch List	20 Jul 2017	25 Jul 2017



2017-07-20 11:51:15

End of 001896 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001902	Do not paint on any fire labels		Webster > LEVEL_01 > 186_CUST. STOR.	Open	Spectra Painting	Architect Punch List	20 Jul 2017	25 Jul 2017



2017-07-20 12:00:24

End of 001902 images

001903	Paint door		Webster > LEVEL_01 > 186_CUST. STOR.	Open	Spectra Painting	Architect Punch List	20 Jul 2017	25 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001905	Repair paint scuff marks, drips, and damages		Webster > LEVEL_01 > C180_CORRIDOR	Open	Spectra Painting	Architect Punch List	20 Jul 2017	25 Jul 2017

2017-07-20 12:11:19

End of 001905 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001906	Repair paint scuff marks, drips, and damages		Webster > LEVEL_01 > S176_STAIR 3-1	Open	Spectra Painting	Architect Punch List	20 Jul 2017	25 Jul 2017



2017-07-20 12:16:06

End of 001906 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001665	Repair ceiling components as needed -		Webster > LEVEL_01 > 100C_K'ETTE	Open	St Charles Acoustics	Architect Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 09:33:28

2017-07-19 09:33:32

End of 001665 images

001668	Replace missing ceiling tile		Webster > LEVEL_01 > 101_OFF. STAFF (2)	Open	St Charles Acoustics	Architect Punch List	19 Jul 2017	24 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001674	Repair ceiling components as needed -		Webster > LEVEL_01 > 106_OFF. NA	Open	St Charles Acoustics	Architect Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 09:56:31

End of 001674 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001676	Repair ceiling components as needed -		Webster > LEVEL_01 > 108_OFF. NU	Open	St Charles Acoustics	Architect Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 09:59:39

2017-07-19 09:59:46

End of 001676 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001677	Adjust diffuser to sit flush		Webster > LEVEL_01 > 107_OFF. NU	Open	St Charles Acoustics	Architect Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 10:03:28

End of 001677 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001684	Repair ceiling components as needed -		Webster > LEVEL_01 > 111_OFF. NU	Open	St Charles Acoustics	Architect Punch List	19 Jul 2017	24 Jul 2017



2017-07-19 10:29:30

End of 001684 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001691	Repair ceiling components as needed -		Webster > LEVEL_01 > 111_OFF. NU	Open	St Charles Acoustics	Architect Punch List	19 Jul 2017	24 Jul 2017



2017-07-19 10:35:25

End of 001691 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001695	Repair ceiling components as needed -		Webster > LEVEL_01 > 111_OFF. NU	Open	St Charles Acoustics	Architect Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 10:38:07

End of 001695 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001700	Replace damaged ceiling tile		Webster > LEVEL_01 > 114_MOCK EXAM	Open	St Charles Acoustics	Architect Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 10:52:54

End of 001700 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001703	Repair ceiling components as needed -		Webster > LEVEL_01 > 116_MOCK EXAM	Open	St Charles Acoustics	Architect Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 11:05:47

End of 001703 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001710	Repair ceiling components as needed -		Webster > LEVEL_01 > 117_OFF. FUT	Open	St Charles Acoustics	Architect Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 11:16:32

End of 001710 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001715	Need to seal between ceiling grid and wall in entire room		Webster > LEVEL_01 > 135_DRY SKILLS LAB / COHORT CLASSROOM	Open	St Charles Acoustics	Architect Punch List	19 Jul 2017	24 Jul 2017



2017-07-19 11:56:04



2017-07-19 11:56:18

End of 001715 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001718	Repair ceiling components as needed -		Webster > LEVEL_01 > 135_DRY SKILLS LAB / COHORT CLASSROOM	Open	St Charles Acoustics	Architect Punch List	19 Jul 2017	24 Jul 2017



2017-07-19 12:12:41

2017-07-19 12:12:45

End of 001718 images

001726	Repair ceiling components as needed -		Webster > LEVEL_01 > 137_MODELS/ ASSESSMENT STORAGE/RESEARCH	Open	St Charles Acoustics	Architect Punch List	19 Jul 2017	24 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001730	Repair ceiling components as needed -		Webster > LEVEL_01 > 133A_CONTROL ROOM / TECH OFF / PREP LAB	Open	St Charles Acoustics	Architect Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 14:10:48

End of 001730 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001736	Repair ceiling components as needed -		Webster > LEVEL_01 > 133A_CONTROL ROOM / TECH OFF / PREP LAB	Open	St Charles Acoustics	Architect Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 14:33:31

2017-07-19 14:33:37

End of 001736 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001741	Closer panel needed to fill voids between lights and ceiling - scope?		Webster > LEVEL_01 > 160_LECTURE HALL	Open	St Charles Acoustics	Architect Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 15:13:37

End of 001741 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001744	Wood grill split		Webster > LEVEL_01 > 160_LECTURE HALL	Open	St Charles Acoustics	Architect Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 15:18:14

End of 001744 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001818	Repair damaged ceiling components		Webster > LEVEL_01 > 160A_CORR.	Open	St Charles Acoustics	Architect Punch List	20 Jul 2017	25 Jul 2017



2017-07-20 09:44:48

End of 001818 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001823	Repair damaged ceiling components		Webster > LEVEL_01 > 156_SM MTG/ GREEN RM	Open	St Charles Acoustics	Architect Punch List	20 Jul 2017	25 Jul 2017

2017-07-20 09:57:36

End of 001823 images

001830	Repair damaged ceiling components		Webster > LEVEL_01 > 154_CONF ROOM (10)	Open	St Charles Acoustics	Architect Punch List	20 Jul 2017	25 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001839	Repair damaged ceiling components		Webster > LEVEL_01 > 154_CONF ROOM (10)	Open	St Charles Acoustics	Architect Punch List	20 Jul 2017	25 Jul 2017



2017-07-20 10:17:02

End of 001839 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001841	Repair damaged ceiling components		Webster > LEVEL_01 > C151_COMMONS	Open	St Charles Acoustics	Architect Punch List	20 Jul 2017	25 Jul 2017



2017-07-20 10:19:53

End of 001841 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001849	Repair damaged ceiling components		Webster > LEVEL_01 > 144_OFF. NU / NA ADJ.	Open	St Charles Acoustics	Architect Punch List	20 Jul 2017	25 Jul 2017



2017-07-20 10:40:05

End of 001849 images

001886	Repair damaged ceiling components	Webster > LEVEL_01 > 183B_CADAVER LAB WORKROOM	Open	St Charles Acoustics	Architect Punch List	20 Jul 2017	25 Jul 2017
001889	Repair damaged ceiling components	Webster > LEVEL_01 > 191_CADAVER LAB	Open	St Charles Acoustics	Architect Punch List	20 Jul 2017	25 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001899	Repair damaged ceiling components		Webster > LEVEL_01 > 183C_BIO VESTIBULE	Open	St Charles Acoustics	Architect Punch List	20 Jul 2017	25 Jul 2017



2017-07-20 11:53:31

End of 001899 images

001904	Repair damaged ceiling components		Webster > LEVEL_01 > C180_CORRIDOR	Open	St Charles Acoustics	Architect Punch List	20 Jul 2017	25 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001743	Upper and lower wood grill sections on wall not in line		Webster > LEVEL_01 > 160_LECTURE HALL	Open	St. Charles Acoustics L.L.C.	Architect Punch List	19 Jul 2017	24 Jul 2017



2017-07-19 15:15:55



2017-07-19 15:17:44

End of 001743 images

001749	Ceiling and wall items to be corrected per observation report 14		Webster > LEVEL_01 > 160_LECTURE HALL	Open	St. Charles Acoustics L.L.C.	Architect Punch List	19 Jul 2017	24 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001705	Clean inside of cabinet		Webster > LEVEL_01 > 116_MOCK EXAM	Open	Titan Contractor Services	Architect Punch List	19 Jul 2017	24 Jul 2017



2017-07-19 11:07:07

End of 001705 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001728	General cleanup needed in room		Webster > LEVEL_01 > 137_MODELS/ ASSESSMENT STORAGE/RESEARCH	Open	Titan Contractor Services	Architect Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 13:28:48

End of 001728 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001770	Clean unit heater		Webster > LEVEL_01 > 178_MECHANICAL ROOM	Open	Titan Contractor Services	Engineer Punch List	19 Jul 2017	24 Jul 2017

2017-07-19 13:52:15

End of 001770 images

001792	Clean thermostat		Webster > LEVEL_01 > 150_EAB CONNECTOR	Open	Titan Contractor Services	Engineer Punch List	19 Jul 2017	24 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001834	Clean base and floor		Webster > LEVEL_01 > 154_CONF ROOM (10)	Open	Titan Contractor Services	Architect Punch List	20 Jul 2017	25 Jul 2017



2017-07-20 10:11:30

End of 001834 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001836	Clean carpet		Webster > LEVEL_01 > 154_CONF ROOM (10)	Open	Titan Contractor Services	Architect Punch List	20 Jul 2017	25 Jul 2017

2017-07-20 10:14:50

End of 001836 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001843	Clean paint from wood panels		Webster > LEVEL_01 > C151_COMMONS	Open	Titan Contractor Services	Architect Punch List	20 Jul 2017	25 Jul 2017

2017-07-20 10:21:56

End of 001843 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001859	Finish around sprinkler		Webster > LEVEL_01 > C170_CORRIDOR	Open	Titan Contractor Services	Architect Punch List	20 Jul 2017	25 Jul 2017

2017-07-20 11:08:17

End of 001859 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001884	Clean paint on door		Webster > LEVEL_01 > 182_TOILET	Open	Titan Contractor Services	Architect Punch List	20 Jul 2017	25 Jul 2017

2017-07-20 11:40:49

End of 001884 images