Webster - ISB **Level 0 Punchlist**

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001192	C280: Sprinkler installation incomplete at North End of Corridor		Webster > LEVEL_02 > C280_CORR	Open	Ahern Fire Protection	Engineer Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 16:29:31

End of 001192 images

001573	Missing lab tables	Webster > LEVEL_02 > 272B_LAB STOR.	Open	Carroll Seating	Architect Punch List	18 Jul 2017	23 Jul 2017
001574	Black closure strip behind door missing	Webster > LEVEL_02 > 272A_CHEM STOCK ROOM	Open	Carroll Seating	Architect Punch List	18 Jul 2017	23 Jul 2017
001582	Missing tables under wiremold	Webster > LEVEL_02 > 282_PHYS LAB PREP	Open	Carroll Seating	Architect Punch List	18 Jul 2017	23 Jul 2017

Webster - ISB **Level 0 Punchlist**

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001593	Repair scuff marks on unistrut system		Webster > LEVEL_02 > 284_PHYSICS LAB	Open	Carroll Seating	Architect Punch List	18 Jul 2017	23 Jul 2017
001594	Repair scuff marks on unistrut system		Webster > LEVEL_02 > 276_SCIN CLASSROOM	Open	Carroll Seating	Architect Punch List	18 Jul 2017	23 Jul 2017
001596	Missing tables under wall mounted shelves		Webster > LEVEL_02 > 292_PHYS RESEARCH LAB	Open	Carroll Seating	Architect Punch List	18 Jul 2017	23 Jul 2017
001598	Seismic lips are missing on wall mounted shelves		Webster > LEVEL_02 > 292_PHYS RESEARCH LAB	Open	Carroll Seating	Architect Punch List	18 Jul 2017	23 Jul 2017
001619	Flammable storage cabinet missing (and at all locations)		Webster > LEVEL_02 > 289B_TISSUE CULTURE B	Open	Carroll Seating	Architect Punch List	18 Jul 2017	23 Jul 2017
001624	Missing flammable storage cabinets		Webster > LEVEL_02 > 289A_MICROBIO PREP	Open	Carroll Seating	Architect Punch List	18 Jul 2017	23 Jul 2017
001611	Relocate paper towel dispenser to other side of rack		Webster > LEVEL_02 > 291_CELL BIO / PHYS RESEARCH LAB	Open	Deluca Plumbing	Architect Punch List	18 Jul 2017	23 Jul 2017
001615	Eyewash missing		Webster > LEVEL_02 > 289B_TISSUE CULTURE B	Open	Deluca Plumbing	Architect Punch List	18 Jul 2017	23 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001431	Repair damaged backsplash		Webster > LEVEL_02 > 200A_WORK / COPY	Open	Flooring Systems, Inc.	Architect Punch List	17 Jul 2017	22 Jul 2017

2017-07-17 09:12:00

End of 001431 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001437	Install base		Webster > LEVEL_02 > 200A_WORK / COPY	Open	Flooring Systems, Inc.	Architect Punch List	18 Jul 2017	23 Jul 2017

2017-07-18 08:23:03

2017-07-18 08:23:08

End of 001437 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001439	Adjust base so cabinet door can work properly		Webster > LEVEL_02 > 200A_WORK / COPY	Open	Flooring Systems, Inc.	Architect Punch List	18 Jul 2017	23 Jul 2017

2017-07-18 08:39:40

End of 001439 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001443	Patch grout		Webster > LEVEL_02 > 200A_WORK / COPY	Open	Flooring Systems, Inc.	Architect Punch List	18 Jul 2017	23 Jul 2017

2017-07-18 09:17:57

End of 001443 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001444	Base missing around cabinets		Webster > LEVEL_02 > 200A_WORK / COPY	Open	Flooring Systems, Inc.	Architect Punch List	18 Jul 2017	23 Jul 2017

2017-07-18 09:20:22

2017-07-18 09:20:49

End of 001444 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001459	Column needs wood base		Webster > LEVEL_02 > 205_OFF. GLOBAL	Open	Flooring Systems, Inc.	Architect Punch List	18 Jul 2017	23 Jul 2017

2017-07-18 09:54:24

End of 001459 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001512	Flooring transition repair		Webster > LEVEL_02 > 235_GEN. CLASSROOM (24 Seat)	Open	Flooring Systems, Inc.	Architect Punch List	18 Jul 2017	23 Jul 2017

2017-07-18 12:14:04

End of 001512 images

001560	Fill gap between elevator and terrazzo	Webster > LEVEL_02 > C270_CORR	Open	Flooring Systems, Inc.	Architect Punch List	18 Jul 2017	23 Jul 2017
001584	Flooring is exposed at m seal locations	Webster > LEVEL_02	Open	Flooring Systems, Inc.	Architect Punch List	18 Jul 2017	23 Jul 2017
001602	Reweld flooring behind brace	Webster > LEVEL_02 > 292_PHYS RESEARCH LAB	Open	Flooring Systems, Inc.	Architect Punch List	18 Jul 2017	23 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001614	Flooring is missing on backside of drain		Webster > LEVEL_02 > 291_CELL BIO / PHYS RESEARCH LAB	Open	Flooring Systems, Inc.	Architect Punch List	18 Jul 2017	23 Jul 2017
001628	Patch holes in grout		Webster > LEVEL_02 > 279_MEN	Open	Flooring Systems, Inc.	Architect Punch List	18 Jul 2017	23 Jul 2017
001631	Clean up excess grout		Webster > LEVEL_02 > 279_MEN	Open	Flooring Systems, Inc.	Architect Punch List	18 Jul 2017	23 Jul 2017
001633	Remove tile spacer		Webster > LEVEL_02 > 279_MEN	Open	Flooring Systems, Inc.	Architect Punch List	18 Jul 2017	23 Jul 2017
001634	Repair chipped tile		Webster > LEVEL_02 > 279_MEN	Open	Flooring Systems, Inc.	Architect Punch List	18 Jul 2017	23 Jul 2017
001640	Patch grout holes		Webster > LEVEL_02 > 277_WOMEN	Open	Flooring Systems, Inc.	Architect Punch List	18 Jul 2017	23 Jul 2017
001642	Patch grout at tile base		Webster > LEVEL_02 > 277_WOMEN	Open	Flooring Systems, Inc.	Architect Punch List	18 Jul 2017	23 Jul 2017
001207	Same comments as floor above electrical room		Webster > LEVEL_02 > 210B_ELEC	Open	Guarantee Electric	Engineer Punch List	13 Jul 2017	18 Jul 2017
001393	In Vestibule C250A, install lens in light fixture.		Webster > LEVEL_02	Open	Guarantee Electric	Engineer Punch List	17 Jul 2017	22 Jul 2017
001394	In Office 211 and 209, the lights are not operational. Correct operation.		Webster > LEVEL_02	Open	Guarantee Electric	Engineer Punch List	17 Jul 2017	22 Jul 2017
001395	Remove plastic from Type RA light fixtures.		Webster > LEVEL_02	Open	Guarantee Electric	Engineer Punch List	17 Jul 2017	22 Jul 2017
001399	In 289A, install missing receptacle on south wall.		Webster > LEVEL_02	Open	Guarantee Electric	Engineer Punch List	17 Jul 2017	22 Jul 2017
001400	In 291, there is an open junction box in overhead carrier. Provide device and/or coverplate as required.		Webster > LEVEL_02	Open	Guarantee Electric	Engineer Punch List	17 Jul 2017	22 Jul 2017
001402	In elevator lobby, Type RC12 is not working. Investigate and correct.		Webster > LEVEL_02	Open	Guarantee Electric	Engineer Punch List	17 Jul 2017	22 Jul 2017
001403	Outside Microscopy Room 274, install missing Type YA light fixture.		Webster > LEVEL_02	Open	Guarantee Electric	Engineer Punch List	17 Jul 2017	22 Jul 2017
001404	In Women 277, install missing lens in RB6.		Webster > LEVEL_02	Open	Guarantee Electric	Engineer Punch List	17 Jul 2017	22 Jul 2017
001405	In Men 279, replace bad LED board in RB6.		Webster > LEVEL_02	Open	Guarantee Electric	Engineer Punch List	17 Jul 2017	22 Jul 2017
001406	Lighting Control Keypads are not working in rooms 282, 284, and 289A.		Webster > LEVEL_02	Open	Guarantee Electric	Engineer Punch List	17 Jul 2017	22 Jul 2017
001407	Most exit signs on this floor are missing the Acrylic panel. Install missing acrylic panel.		Webster > LEVEL_02	Open	Guarantee Electric	Engineer Punch List	17 Jul 2017	22 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001489	Remove plastic covering from lights		Webster > LEVEL_02 > C210_CORR	Open	Guarantee Electric	Architect Punch List	18 Jul 2017	23 Jul 2017

2017-07-18 11:13:07

End of 001489 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001490	Seal wire penetrations at WAPs		Webster > LEVEL_02 > C210_CORR	Open	Guarantee Electric	Architect Punch List	18 Jul 2017	23 Jul 2017

2017-07-18 11:12:39

End of 001490 images

001580	Scratches on table mounted electrical outlet plates	Webster > LEVEL_02 > 276_SCIN CLASSROOM	Open	Guarantee Electric	Architect Punch List	18 Jul 2017	23 Jul 2017
001586	Gap in wiremold	Webster > LEVEL_02 > 284_PHYSICS LAB	Open	Guarantee Electric	Architect Punch List	18 Jul 2017	23 Jul 2017
001613	Finish electrical boxes	Webster > LEVEL_02 > 291_CELL BIO / PHYS RESEARCH LAB	Open	Guarantee Electric	Architect Punch List	18 Jul 2017	23 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001622	Light switch does not work properly		Webster > LEVEL_02 > 289A_MICROBIO PREP	Open	Guarantee Electric	Architect Punch List	18 Jul 2017	23 Jul 2017
001625	Missing cover plate		Webster > LEVEL_02 > 289A_MICROBIO PREP	Open	Guarantee Electric	Architect Punch List	18 Jul 2017	23 Jul 2017
001641	Missing light		Webster > LEVEL_02 > 277_WOMEN	Open	Guarantee Electric	Architect Punch List	18 Jul 2017	23 Jul 2017
Cx-0103-6	Complete insulation on the hot water supply for VAV 2-14.		Webster > LEVEL_02 > 206_OFF. DEAN'S ASSIST.	Open	ICON Mechanical	Commissioning	28 Jun 2017	12 Jul 2017
001457	Attach shade brackets		Webster > LEVEL_02 > 203_CONF	Open	Interior Investments	Architect Punch List	18 Jul 2017	23 Jul 2017



2017-07-18 09:49:48

End of 001457 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001463	Attach shade brackets		Webster > LEVEL_02 > 205_OFF. GLOBAL	Open	Interior Investments	Architect Punch List	18 Jul 2017	23 Jul 2017
001499	Ends of shade pockets are open - need to be closed		Webster > LEVEL_02 > 231_COMP. LAB / GEN. CLASSROOM	Open	Interior Investments	Architect Punch List	18 Jul 2017	23 Jul 2017



2017-07-18 11:43:29

End of 001499 images

001509	Ends of shade pockets are open - need to be closed	Webster > LEVEL_02 > 233_GEN. CLASSROOM (24 Seat)	Open	Interior Investments	Architect Punch List	18 Jul 2017	23 Jul 2017
001510	Ends of shade pockets are open - need to be closed	Webster > LEVEL_02 > 235_GEN. CLASSROOM (24 Seat)	Open	Interior Investments	Architect Punch List	18 Jul 2017	23 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001585	Missing shade		Webster > LEVEL_02 > 282_PHYS LAB PREP	Open	Interior Investments	Architect Punch List	18 Jul 2017	23 Jul 2017
001454	Scuff marks on storefront aluminum frames (entire level 2)		Webster > LEVEL_02	Open	National Glass & Glazing, Inc.	Architect Punch List	18 Jul 2017	23 Jul 2017

2017-07-18 09:42:05

2017-07-18 09:42:28

End of 001454 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001455	Seal storefront frames to drywall (entire level 2)		Webster > LEVEL_02	Open	National Glass & Glazing, Inc.	Architect Punch List	18 Jul 2017	23 Jul 2017

2017-07-18 09:44:10



2017-07-18 09:44:28

End of 001455 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001503	Seal between curtain wall and storefront		Webster > LEVEL_02 > 235_GEN. CLASSROOM (24 Seat)	Open	National Glass & Glazing, Inc.	Architect Punch List	18 Jul 2017	23 Jul 2017

2017-07-18 11:53:41

End of 001503 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001515	Readjust automatic door openers at all locations (if necessary)		Webster > LEVEL_02	Open	National Glass & Glazing, Inc.	Architect Punch List	18 Jul 2017	23 Jul 2017

2017-07-18 12:20:27

End of 001515 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001517	Scuff mark on mullion		Webster > LEVEL_02 > C230_CORR	Open	National Glass & Glazing, Inc.	Architect Punch List	18 Jul 2017	23 Jul 2017

2017-07-18 12:25:47

End of 001517 images

001600	Sealant between flooring and store front framing to be gray not white (entire floor)		Webster > LEVEL_02	Open	National Glass & Glazing, Inc.	Architect Punch List	18 Jul 2017	23 Jul 2017
001555	Panel above elevator is not flush with the frame		Webster > LEVEL_02 > C270_CORR	Open	Otis Elevator Company	Architect Punch List	18 Jul 2017	23 Jul 2017
001657	Cover plates are too wide		Webster > LEVEL_02 > C280_CORR	Open	Otis Elevator Company	Architect Punch List	18 Jul 2017	23 Jul 2017

Webster - ISB **Level 0 Punchlist**

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001398	In Lab 283, patch drywall at window where conduit for surface mounted raceway is stubbed out.		Webster > LEVEL_02	Open	PARIC (Self-Perform)	Engineer Punch List	17 Jul 2017	22 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001432	Seal countertop to wall at all locations		Webster > LEVEL_02 > 200A_WORK / COPY	Open	PARIC (Self-Perform)	Architect Punch List	17 Jul 2017	22 Jul 2017

2017-07-18 08:06:48



2017-07-18 08:15:08

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date



2017-07-18 08:15:19

End of 001432 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001435	Repair drywall at data cover		Webster > LEVEL_02 > 200A_WORK / COPY	Open	PARIC (Self-Perform)	Architect Punch List	18 Jul 2017	23 Jul 2017

2017-07-18 08:18:46

End of 001435 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001436	Repair drywall at receptical		Webster > LEVEL_02 > 200A_WORK / COPY	Open	PARIC (Self-Perform)	Architect Punch List	18 Jul 2017	23 Jul 2017

2017-07-18 08:21:46

End of 001436 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001441	Scuff marks on interior door frame		Webster > LEVEL_02 > 200B_DATA	Open	PARIC (Self-Perform)	Architect Punch List	18 Jul 2017	23 Jul 2017



2017-07-18 09:13:31

2017-07-18 09:14:13

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-18 09:14:23

End of 001441 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001452	Seal end caps to mullion mates (entire level 2)		Webster > LEVEL_02	Open	PARIC (Self-Perform)	Architect Punch List	18 Jul 2017	23 Jul 2017

2017-07-18 09:37:39

End of 001452 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001453	Seal drywall connection to mullion (entire level 2)		Webster > LEVEL_02	Open	PARIC (Self-Perform)	Architect Punch List	18 Jul 2017	23 Jul 2017

2017-07-18 09:40:10

End of 001453 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001456	Door corner chipped		Webster > LEVEL_02 > 200A_WORK / COPY	Open	PARIC (Self-Perform)	Architect Punch List	18 Jul 2017	23 Jul 2017

2017-07-18 09:46:18

End of 001456 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001461	Repair door chips		Webster > LEVEL_02 > 205_OFF. GLOBAL	Open	PARIC (Self-Perform)	Architect Punch List	18 Jul 2017	23 Jul 2017

2017-07-18 09:59:20

End of 001461 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001465	Repaint 2" aluminum trim below gray painted facia (entire level 2)		Webster > LEVEL_02	Open	PARIC (Self-Perform)	Architect Punch List	18 Jul 2017	23 Jul 2017

2017-07-18 10:26:49

End of 001465 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001474	Door frame dent		Webster > LEVEL_02 > 210A_STORAGE	Open	PARIC (Self-Perform)	Architect Punch List	18 Jul 2017	23 Jul 2017

2017-07-18 10:43:55

End of 001474 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001475	Seal ends of 2" aluminum trim below facia (entire level 2)		Webster > LEVEL_02	Open	PARIC (Self-Perform)	Architect Punch List	18 Jul 2017	23 Jul 2017



2017-07-18 10:48:14

End of 001475 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001478	Dented drywall sill		Webster > LEVEL_02 > 211_OFF. ASSOC. DEAN	Open	PARIC (Self-Perform)	Architect Punch List	18 Jul 2017	23 Jul 2017

2017-07-18 10:51:34

End of 001478 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001482	Door chip		Webster > LEVEL_02 > 212_OFF. COMMUNICATIONS	Open	PARIC (Self-Perform)	Architect Punch List	18 Jul 2017	23 Jul 2017



2017-07-18 10:56:38

End of 001482 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001483	Mullion mate missing		Webster > LEVEL_02 > 215_DEAN'S OFFICE	Open	PARIC (Self-Perform)	Architect Punch List	18 Jul 2017	23 Jul 2017

2017-07-18 10:59:42

End of 001483 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001495	Door frame dent		Webster > LEVEL_02 > 210B_ELEC	Open	PARIC (Self-Perform)	Architect Punch List	18 Jul 2017	23 Jul 2017

2017-07-18 11:23:32

2017-07-18 11:23:38

End of 001495 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001496	Door chips @ c210		Webster > LEVEL_02 > C210_CORR	Open	PARIC (Self-Perform)	Architect Punch List	18 Jul 2017	23 Jul 2017



2017-07-18 11:25:25

End of 001496 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001497	Door frame damage @C210		Webster > LEVEL_02 > C210_CORR	Open	PARIC (Self-Perform)	Architect Punch List	18 Jul 2017	23 Jul 2017

2017-07-18 11:26:32

End of 001497 images

001514	Soffit incomplete	Webster > LEVEL_02 > C230_CORR	Open	PARIC (Self-Perform)	Architect Punch List	18 Jul 2017	23 Jul 2017
001516	South wall missing sound acoustic pads (ID0102)	Webster > LEVEL_02 > C230_CORR	Open	PARIC (Self-Perform)	Architect Punch List	18 Jul 2017	23 Jul 2017
001556	Repair scratches, scuff marks, and chips on wood panels	Webster > LEVEL_02 > C270_CORR	Open	PARIC (Self-Perform)	Architect Punch List	18 Jul 2017	23 Jul 2017
001558	Repair scratches, scuff marks, and chips in wood paneling	Webster > LEVEL_02 > C250_LOBBY	Open	PARIC (Self-Perform)	Architect Punch List	18 Jul 2017	23 Jul 2017

Webster - ISB **Level 0 Punchlist**

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001561	Repair door chips		Webster > LEVEL_02 > 274_MICROSCOPY ROOM	Open	PARIC (Self-Perform)	Architect Punch List	18 Jul 2017	23 Jul 2017
001564	Missing closure plate for door bottom		Webster > LEVEL_02 > 274_MICROSCOPY ROOM	Open	PARIC (Self-Perform)	Architect Punch List	18 Jul 2017	23 Jul 2017
001567	Dented door frame		Webster > LEVEL_02 > 274_MICROSCOPY ROOM	Open	PARIC (Self-Perform)	Architect Punch List	18 Jul 2017	23 Jul 2017
001571	Missing screws at shelving		Webster > LEVEL_02 > 272B_LAB STOR.	Open	PARIC (Self-Perform)	Architect Punch List	18 Jul 2017	23 Jul 2017
001575	Missing floor door stop		Webster > LEVEL_02 > 272B_LAB STOR.	Open	PARIC (Self-Perform)	Architect Punch List	18 Jul 2017	23 Jul 2017
001577	Chalk tray missing		Webster > LEVEL_02 > 276_SCIN CLASSROOM	Open	PARIC (Self-Perform)	Architect Punch List	18 Jul 2017	23 Jul 2017
001581	Door frame banged up		Webster > LEVEL_02 > 282_PHYS LAB PREP	Open	PARIC (Self-Perform)	Architect Punch List	18 Jul 2017	23 Jul 2017
001591	Projectable surface covering not installed in all labs		Webster > LEVEL_02	Open	PARIC (Self-Perform)	Architect Punch List	18 Jul 2017	23 Jul 2017
001592	Seal around structural brace		Webster > LEVEL_02 > 284_PHYSICS LAB	Open	PARIC (Self-Perform)	Architect Punch List	18 Jul 2017	23 Jul 2017
001595	Seal around structural brace (top and bottom)		Webster > LEVEL_02 > 292_PHYS RESEARCH LAB	Open	PARIC (Self-Perform)	Architect Punch List	18 Jul 2017	23 Jul 2017
001605	Repair drywall above cabinets on teaching wall		Webster > LEVEL_02 > 291_CELL BIO / PHYS RESEARCH LAB	Open	PARIC (Self-Perform)	Architect Punch List	18 Jul 2017	23 Jul 2017
001606	End panels are missing at base cabinets on the teaching wall in all labs		Webster > LEVEL_02	Open	PARIC (Self-Perform)	Architect Punch List	18 Jul 2017	23 Jul 2017
001607	Drywall repair at wiremold		Webster > LEVEL_02 > 291_CELL BIO / PHYS RESEARCH LAB	Open	PARIC (Self-Perform)	Architect Punch List	18 Jul 2017	23 Jul 2017
001610	Repair drywall under wiremold		Webster > LEVEL_02 > 283_MICROBIO/ PLANT RESEARCH LAB	Open	PARIC (Self-Perform)	Architect Punch List	18 Jul 2017	23 Jul 2017
001617	Dented door frame		Webster > LEVEL_02 > 289B_TISSUE CULTURE B	Open	PARIC (Self-Perform)	Architect Punch List	18 Jul 2017	23 Jul 2017
001621	Seal column to wall		Webster > LEVEL_02 > 289B_TISSUE CULTURE B	Open	PARIC (Self-Perform)	Architect Punch List	18 Jul 2017	23 Jul 2017
001623	Chip in door		Webster > LEVEL_02 > 289A_MICROBIO PREP	Open	PARIC (Self-Perform)	Architect Punch List	18 Jul 2017	23 Jul 2017
001626	Repair door frame		Webster > LEVEL_02 > 289A_MICROBIO PREP	Open	PARIC (Self-Perform)	Architect Punch List	18 Jul 2017	23 Jul 2017
001627	Seal door frame to drywall		Webster > LEVEL_02 > 289A_MICROBIO PREP	Open	PARIC (Self-Perform)	Architect Punch List	18 Jul 2017	23 Jul 2017

Webster - ISB **Level 0 Punchlist**

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001635	Repair drywall at sink		Webster > LEVEL_02 > 279_MEN	Open	PARIC (Self-Perform)	Architect Punch List	18 Jul 2017	23 Jul 2017
001636	Seal countertop to wall		Webster > LEVEL_02 > 279_MEN	Open	PARIC (Self-Perform)	Architect Punch List	18 Jul 2017	23 Jul 2017
001637	Door chip		Webster > LEVEL_02 > 279_MEN	Open	PARIC (Self-Perform)	Architect Punch List	18 Jul 2017	23 Jul 2017
001638	Damaged door frame		Webster > LEVEL_02 > 279_MEN	Open	PARIC (Self-Perform)	Architect Punch List	18 Jul 2017	23 Jul 2017
001643	Door frame damage		Webster > LEVEL_02 > 277_WOMEN	Open	PARIC (Self-Perform)	Architect Punch List	18 Jul 2017	23 Jul 2017
001646	Door frame damage		Webster > LEVEL_02 > 275_LACT.	Open	PARIC (Self-Perform)	Architect Punch List	18 Jul 2017	23 Jul 2017
001648	Seal around wood panelling at lab entries		Webster > LEVEL_02 > C280_CORR	Open	PARIC (Self-Perform)	Architect Punch List	18 Jul 2017	23 Jul 2017
001649	Missing wood panelling around bathroom entries		Webster > LEVEL_02 > C280_CORR	Open	PARIC (Self-Perform)	Architect Punch List	18 Jul 2017	23 Jul 2017
001655	Repair chips in wood panels		Webster > LEVEL_02 > C280_CORR	Open	PARIC (Self-Perform)	Architect Punch List	18 Jul 2017	23 Jul 2017
001656	Gap at floor and elevator door frames		Webster > LEVEL_02 > C280_CORR	Open	PARIC (Self-Perform)	Architect Punch List	18 Jul 2017	23 Jul 2017
001658	Seal between wood panelling and wall		Webster > LEVEL_02 > C280_CORR	Open	PARIC (Self-Perform)	Architect Punch List	18 Jul 2017	23 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000329	Contractor to confirm control valves serving level 2 area "B" FTR's will be accessible.		Webster > LEVEL_02 > 235_GEN. CLASSROOM (24 Seat)	Open	Ross and Baruzzini	Commissioning	20 Mar 2017	25 Mar 2017



2017-03-15 15:24:47

2017-03-15 15:26:31

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-02-20 14:39:40

2017-02-20 14:40:56

End of 000329 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001201	Clean white paint off of black blades of slot diffuser in Corridor near 2nd Floor Elev 1 Doors		Webster > LEVEL_02 > C250B_COMMONS	Open	Spectra Painting	Engineer Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 16:48:36

End of 001201 images

001202	Clean paint off of slot diffuser		Webster > LEVEL_02 > C250B_COMMONS	Open	Spectra Painting	Engineer Punch List	13 Jul 2017	18 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001397	At the intersection of C280 corridor and elevator lobby, remove paint from fire alarm device.		Webster > LEVEL_02	Open	Spectra Painting	Engineer Punch List	17 Jul 2017	22 Jul 2017

2017-07-13 14:33:51

End of 001397 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001433	Remove adhesive from wall under cork board		Webster > LEVEL_02 > 200A_WORK / COPY	Open	Spectra Painting	Architect Punch List	18 Jul 2017	23 Jul 2017

2017-07-18 08:08:42

End of 001433 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001438	Clean paint off cabinets		Webster > LEVEL_02 > 200A_WORK / COPY	Open	Spectra Painting	Architect Punch List	18 Jul 2017	23 Jul 2017

2017-07-18 08:26:04

2017-07-18 08:26:12

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-18 08:27:19

2017-07-18 08:27:29

End of 001438 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001440	Repair paint chips on door		Webster > LEVEL_02 > 200B_DATA	Open	Spectra Painting	Architect Punch List	18 Jul 2017	23 Jul 2017

2017-07-18 09:11:33

End of 001440 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001442	Repair paint scuff marks, drips, and damages		Webster > LEVEL_02 > 200A_WORK / COPY	Open	Spectra Painting	Architect Punch List	18 Jul 2017	23 Jul 2017

2017-07-18 09:15:26

2017-07-18 09:16:26

End of 001442 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001447	Repaint soffit		Webster > LEVEL_02 > 203_CONF	Open	Spectra Painting	Architect Punch List	18 Jul 2017	23 Jul 2017



2017-07-18 09:27:53

End of 001447 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001449	Repair paint scuff marks, drips, and damages		Webster > LEVEL_02 > 203_CONF	Open	Spectra Painting	Architect Punch List	18 Jul 2017	23 Jul 2017



2017-07-18 09:34:24



2017-07-18 09:34:29

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date



2017-07-18 09:34:47

2017-07-18 09:34:58

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-18 09:53:22

End of 001449 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001451	Paint end caps at mullion mates (entire level 2)		Webster > LEVEL_02	Open	Spectra Painting	Architect Punch List	18 Jul 2017	23 Jul 2017



2017-07-18 09:38:31

End of 001451 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001460	Repair paint scuff marks, drips, and damages		Webster > LEVEL_02 > 205_OFF. GLOBAL	Open	Spectra Painting	Architect Punch List	18 Jul 2017	23 Jul 2017

2017-07-18 09:56:14



2017-07-18 09:57:04

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-18 09:58:08

End of 001460 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001464	Clean gray paint bleed along painted facia (entire level 2)		Webster > LEVEL_02	Open	Spectra Painting	Architect Punch List	18 Jul 2017	23 Jul 2017

2017-07-18 10:24:56

End of 001464 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001468	Repair paint scuff marks, drips, and damages		Webster > LEVEL_02 > 209_OFF. ASSOC. DEAN	Open	Spectra Painting	Architect Punch List	18 Jul 2017	23 Jul 2017

2017-07-18 10:34:38



2017-07-18 10:34:43

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date



2017-07-18 10:34:49

2017-07-18 10:34:54

End of 001468 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001469	Repair paint scuff marks, drips, and damages		Webster > LEVEL_02 > 207_OFF. STRATEGIC	Open	Spectra Painting	Architect Punch List	18 Jul 2017	23 Jul 2017



2017-07-18 10:36:14

2017-07-18 10:36:20

End of 001469 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001471	Repair paint scuff marks, drips, and damages		Webster > LEVEL_02 > 206_OFF. DEAN'S ASSIST.	Open	Spectra Painting	Architect Punch List	18 Jul 2017	23 Jul 2017



2017-07-18 10:37:24

2017-07-18 10:37:32

End of 001471 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001472	Repair paint scuff marks, drips, and damages		Webster > LEVEL_02 > 208_OFF. ASSESSMENT	Open	Spectra Painting	Architect Punch List	18 Jul 2017	23 Jul 2017



2017-07-18 10:41:40

2017-07-18 10:41:48

End of 001472 images

001476	Paint drips on carpet and base		Webster > LEVEL_02 > 211_OFF. ASSOC. DEAN	Open	Spectra Painting	Architect Punch List	18 Jul 2017	23 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001477	Repair paint scuff marks, drips, and damages		Webster > LEVEL_02 > 211_OFF. ASSOC. DEAN	Open	Spectra Painting	Architect Punch List	18 Jul 2017	23 Jul 2017

2017-07-18 10:50:22



2017-07-18 10:50:29

End of 001477 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001480	Repair paint scuff marks, drips, and damages		Webster > LEVEL_02 > 212_OFF. COMMUNICATIONS	Open	Spectra Painting	Architect Punch List	18 Jul 2017	23 Jul 2017



2017-07-18 10:54:59

End of 001480 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001481	Paint on carpet		Webster > LEVEL_02 > 212_OFF. COMMUNICATIONS	Open	Spectra Painting	Architect Punch List	18 Jul 2017	23 Jul 2017

2017-07-18 10:55:56

End of 001481 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001485	Repair paint scuff marks, drips, and damages		Webster > LEVEL_02 > 215_DEAN'S OFFICE	Open	Spectra Painting	Architect Punch List	18 Jul 2017	23 Jul 2017

2017-07-18 11:00:50

2017-07-18 11:01:03

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-18 11:01:13

End of 001485 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001487	Repair paint scuff marks, drips, and damages		Webster > LEVEL_02 > 214_OFF. OPERATIONS	Open	Spectra Painting	Architect Punch List	18 Jul 2017	23 Jul 2017

2017-07-18 11:05:59

2017-07-18 11:06:04

End of 001487 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001491	Repair paint scuff marks, drips, and damages		Webster > LEVEL_02 > C210_CORR	Open	Spectra Painting	Architect Punch List	18 Jul 2017	23 Jul 2017

2017-07-18 11:19:56

2017-07-18 11:20:01

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-18 11:20:12

2017-07-18 11:20:28

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-18 11:20:33

2017-07-18 11:22:08

End of 001491 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001494	Repair paint scuff marks, drips, and damages		Webster > LEVEL_02 > 202_RECEPTION	Open	Spectra Painting	Architect Punch List	18 Jul 2017	23 Jul 2017



2017-07-18 11:18:56

2017-07-18 11:19:35

End of 001494 images

001559	Repair paint scuff marks, drips, and damages	Webster > LEVEL_02 > C270_CORR	Open	Spectra Painting	Architect Punch List	18 Jul 2017	23 Jul 2017
001562	Repair paint scuff marks, drips, and damages	Webster > LEVEL_02 > 274_MICROSCOPY ROOM	Open	Spectra Painting	Architect Punch List	18 Jul 2017	23 Jul 2017
001565	Clean paint off wiremold	Webster > LEVEL_02 > 274_MICROSCOPY ROOM	Open	Spectra Painting	Architect Punch List	18 Jul 2017	23 Jul 2017

Webster - ISB **Level 0 Punchlist**

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001568	Repair paint scuff marks, drips, and damages		Webster > LEVEL_02 > 272A_CHEM STOCK ROOM	Open	Spectra Painting	Architect Punch List	18 Jul 2017	23 Jul 2017
001572	Repair paint scuff marks, drips, and damages		Webster > LEVEL_02 > 272B_LAB STOR.	Open	Spectra Painting	Architect Punch List	18 Jul 2017	23 Jul 2017
001576	Repair paint scuff marks, drips, and damages in common area		Webster > LEVEL_02 > C270_CORR	Open	Spectra Painting	Architect Punch List	18 Jul 2017	23 Jul 2017
001578	Repair paint scuff marks, drips, and damages		Webster > LEVEL_02 > 276_SCIN CLASSROOM	Open	Spectra Painting	Architect Punch List	18 Jul 2017	23 Jul 2017
001583	Repair paint scuff marks, drips, and damages		Webster > LEVEL_02 > 282_PHYS LAB PREP	Open	Spectra Painting	Architect Punch List	18 Jul 2017	23 Jul 2017
001589	Repair paint scuff marks, drips, and damages		Webster > LEVEL_02 > 284_PHYSICS LAB	Open	Spectra Painting	Architect Punch List	18 Jul 2017	23 Jul 2017
001590	Repaint window sill		Webster > LEVEL_02 > 284_PHYSICS LAB	Open	Spectra Painting	Architect Punch List	18 Jul 2017	23 Jul 2017
001599	Repair paint scuff marks, drips, and damages		Webster > LEVEL_02 > 292_PHYS RESEARCH LAB	Open	Spectra Painting	Architect Punch List	18 Jul 2017	23 Jul 2017
001601	Clean paint off flooring		Webster > LEVEL_02 > 292_PHYS RESEARCH LAB	Open	Spectra Painting	Architect Punch List	18 Jul 2017	23 Jul 2017
001604	Repair paint scuff marks, drips, and damages		Webster > LEVEL_02 > 291_CELL BIO / PHYS RESEARCH LAB	Open	Spectra Painting	Architect Punch List	18 Jul 2017	23 Jul 2017
001609	Repair paint scuff marks, drips, and damages		Webster > LEVEL_02 > 283_MICROBIO/ PLANT RESEARCH LAB	Open	Spectra Painting	Architect Punch List	18 Jul 2017	23 Jul 2017
001618	Repair paint scuff marks, drips, and damages		Webster > LEVEL_02 > 289B_TISSUE CULTURE B	Open	Spectra Painting	Architect Punch List	18 Jul 2017	23 Jul 2017
001630	All access panels with enamel finish were not supposed to be painted		Webster > LEVEL_02 > 279_MEN	Open	Spectra Painting	Architect Punch List	18 Jul 2017	23 Jul 2017
001644	Repair paint scuff marks, drips, and damages		Webster > LEVEL_02 > 277_WOMEN	Open	Spectra Painting	Architect Punch List	18 Jul 2017	23 Jul 2017
001650	Repair paint scuff marks, drips, and damages		Webster > LEVEL_02 > C280_CORR	Open	Spectra Painting	Architect Punch List	18 Jul 2017	23 Jul 2017
001651	Level 5 finish on all walls		Webster > LEVEL_02 > C280_CORR	Open	Spectra Painting	Architect Punch List	18 Jul 2017	23 Jul 2017
001652	Clean and repair drywall around columns		Webster > LEVEL_02 > C280_CORR	Open	Spectra Painting	Architect Punch List	18 Jul 2017	23 Jul 2017
001653	Clean all paint on wood panels		Webster > LEVEL_02 > C280_CORR	Open	Spectra Painting	Architect Punch List	18 Jul 2017	23 Jul 2017
001654	Paint facia and soffit at north vertical window to be gray		Webster > LEVEL_02 > C280A_COMMONS	Open	Spectra Painting	Architect Punch List	18 Jul 2017	23 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001434	Repair damaged ceiling components		Webster > LEVEL_02 > 200A_WORK / COPY	Open	St Charles Acoustics	Architect Punch List	18 Jul 2017	23 Jul 2017



2017-07-18 09:19:00

2017-07-18 09:19:11

End of 001434 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001445	Visible crack at light		Webster > LEVEL_02 > 203_CONF	Open	St Charles Acoustics	Architect Punch List	18 Jul 2017	23 Jul 2017

2017-07-18 09:23:42

End of 001445 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001446	Seal gap around ceiling main		Webster > LEVEL_02 > 203_CONF	Open	St Charles Acoustics	Architect Punch List	18 Jul 2017	23 Jul 2017



2017-07-18 09:25:14

End of 001446 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001448	Bent wall angle		Webster > LEVEL_02 > 203_CONF	Open	St Charles Acoustics	Architect Punch List	18 Jul 2017	23 Jul 2017



2017-07-18 09:30:11

End of 001448 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001450	Repair damaged ceiling components		Webster > LEVEL_02 > 203_CONF	Open	St Charles Acoustics	Architect Punch List	18 Jul 2017	23 Jul 2017

2017-07-18 09:33:35

End of 001450 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001462	Repair damaged ceiling components		Webster > LEVEL_02 > 205_OFF. GLOBAL	Open	St Charles Acoustics	Architect Punch List	18 Jul 2017	23 Jul 2017

2017-07-18 10:01:23



2017-07-18 10:16:15

End of 001462 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001466	Raw cut edges of ceiling tiles not painted (entire level 2)		Webster > LEVEL_02	Open	St Charles Acoustics	Architect Punch List	18 Jul 2017	23 Jul 2017



2017-07-18 10:29:03

End of 001466 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001467	Repair damaged ceiling components		Webster > LEVEL_02 > 209_OFF. ASSOC. DEAN	Open	St Charles Acoustics	Architect Punch List	18 Jul 2017	23 Jul 2017

2017-07-18 10:34:24

End of 001467 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001470	Repair damaged ceiling components		Webster > LEVEL_02 > 207_OFF. STRATEGIC	Open	St Charles Acoustics	Architect Punch List	18 Jul 2017	23 Jul 2017

2017-07-18 10:35:57

End of 001470 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001473	Repair damaged ceiling components		Webster > LEVEL_02 > 208_OFF. ASSESSMENT	Open	St Charles Acoustics	Architect Punch List	18 Jul 2017	23 Jul 2017

2017-07-18 10:42:39

End of 001473 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001479	Paint raw cut edge ceiling tiles		Webster > LEVEL_02 > 212_OFF. COMMUNICATIONS	Open	St Charles Acoustics	Architect Punch List	18 Jul 2017	23 Jul 2017



2017-07-18 10:53:48

End of 001479 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001484	Repair damaged ceiling components		Webster > LEVEL_02 > 215_DEAN'S OFFICE	Open	St Charles Acoustics	Architect Punch List	18 Jul 2017	23 Jul 2017



2017-07-18 11:01:40

End of 001484 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001486	Seal ceiling to drywall		Webster > LEVEL_02 > 214_OFF. OPERATIONS	Open	St Charles Acoustics	Architect Punch List	18 Jul 2017	23 Jul 2017



2017-07-18 11:05:13

End of 001486 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001492	Repair damaged ceiling components		Webster > LEVEL_02 > C210_CORR	Open	St Charles Acoustics	Architect Punch List	18 Jul 2017	23 Jul 2017

2017-07-18 11:13:58

2017-07-18 11:14:08

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-18 11:14:18



2017-07-18 11:14:30

End of 001492 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001493	Repair damaged ceiling components		Webster > LEVEL_02 > 202_RECEPTION	Open	St Charles Acoustics	Architect Punch List	18 Jul 2017	23 Jul 2017

2017-07-18 11:16:22



2017-07-18 11:16:29

End of 001493 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001501	Repair damaged ceiling components		Webster > LEVEL_02 > 231_COMP. LAB / GEN. CLASSROOM	Open	St Charles Acoustics	Architect Punch List	18 Jul 2017	23 Jul 2017



2017-07-18 11:48:34

2017-07-18 11:48:50

End of 001501 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001502	Repair damaged ceiling components		Webster > LEVEL_02 > 233_GEN. CLASSROOM (24 Seat)	Open	St Charles Acoustics	Architect Punch List	18 Jul 2017	23 Jul 2017

2017-07-18 11:50:23

2017-07-18 11:50:32

End of 001502 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001504	Repair damaged ceiling components		Webster > LEVEL_02 > 235_GEN. CLASSROOM (24 Seat)	Open	St Charles Acoustics	Architect Punch List	18 Jul 2017	23 Jul 2017

2017-07-18 11:56:04



2017-07-18 11:56:10

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-18 11:56:52

End of 001504 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001506	Paint all raw cut edges of ceiling tiles		Webster > LEVEL_02 > 235_GEN. CLASSROOM (24 Seat)	Open	St Charles Acoustics	Architect Punch List	18 Jul 2017	23 Jul 2017

2017-07-18 11:59:08

2017-07-18 11:59:16

End of 001506 images

001513	Repair damaged ceiling components	Webster > LEVEL_02 > C230_CORR	Open	St Charles Acoustics	Architect Punch List	18 Jul 2017	23 Jul 2017
001563	Repair damaged ceiling components	Webster > LEVEL_02 > 274_MICROSCOPY ROOM	Open	St Charles Acoustics	Architect Punch List	18 Jul 2017	23 Jul 2017
001570	Repair damaged ceiling components	Webster > LEVEL_02 > 272A_CHEM STOCK ROOM	Open	St Charles Acoustics	Architect Punch List	18 Jul 2017	23 Jul 2017

Webster - ISB **Level 0 Punchlist**

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001579	Repair damaged ceiling components		Webster > LEVEL_02 > 276_SCIN CLASSROOM	Open	St Charles Acoustics	Architect Punch List	18 Jul 2017	23 Jul 2017
001588	Repair damaged ceiling components		Webster > LEVEL_02 > 282_PHYS LAB PREP	Open	St Charles Acoustics	Architect Punch List	18 Jul 2017	23 Jul 2017
001597	Repair damaged ceiling components		Webster > LEVEL_02 > 292_PHYS RESEARCH LAB	Open	St Charles Acoustics	Architect Punch List	18 Jul 2017	23 Jul 2017
001603	Repair damaged ceiling components		Webster > LEVEL_02 > 291_CELL BIO / PHYS RESEARCH LAB	Open	St Charles Acoustics	Architect Punch List	18 Jul 2017	23 Jul 2017
001608	Repair damaged ceiling components		Webster > LEVEL_02 > 283_MICROBIO/ PLANT RESEARCH LAB	Open	St Charles Acoustics	Architect Punch List	18 Jul 2017	23 Jul 2017
001616	Reinstall ceiling grid		Webster > LEVEL_02 > 289B_TISSUE CULTURE B	Open	St Charles Acoustics	Architect Punch List	18 Jul 2017	23 Jul 2017
001620	Repair damaged ceiling components		Webster > LEVEL_02 > 289B_TISSUE CULTURE B	Open	St Charles Acoustics	Architect Punch List	18 Jul 2017	23 Jul 2017
001647	Repair damaged ceiling components		Webster > LEVEL_02 > C280_CORR	Open	St Charles Acoustics	Architect Punch List	18 Jul 2017	23 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001507	Clean angled glass behind column		Webster > LEVEL_02 > 235_GEN. CLASSROOM (24 Seat)	Open	Titan Contractor Services	Architect Punch List	18 Jul 2017	23 Jul 2017

2017-07-18 12:03:13

End of 001507 images

001629	Clean light lense	Webster > LEVEL_02 > 279_MEN	Open	Titan Contractor Services	Architect Punch List	18 Jul 2017	23 Jul 2017
001632	Clean floor and tile base	Webster > LEVEL_02 > 279_MEN	Open	Titan Contractor Services	Architect Punch List	18 Jul 2017	23 Jul 2017