Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001317	Repair chipped tiles and holes in grout		Webster > LEVEL_03 > 379_MEN	Open	<not set>	Architect Punch List	14 Jul 2017	19 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-14 11:12:35

2017-07-14 11:12:41

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-14 11:12:51

2017-07-14 11:13:02

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-14 11:13:11

End of 001317 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001318	Install fire sprinkler escutcheons		Webster > LEVEL_03 > 379_MEN	Open	<not set>	Architect Punch List	14 Jul 2017	19 Jul 2017

2017-07-14 11:13:37



2017-07-14 11:13:46

End of 001318 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001325	Replace chipped tile, corner of tile should not extend, fill holes in grout		Webster > LEVEL_03 > 377_WOMEN	Open	<not set>	Architect Punch List	14 Jul 2017	19 Jul 2017



2017-07-14 11:31:41

2017-07-14 11:31:54

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-14 11:32:03

End of 001325 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001082	Metal table needed		Webster > LEVEL_03 > 374A_BIO FAC. RESEARCH	Open	Carroll Seating	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 15:54:11

End of 001082 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001088	Lab benches missing		Webster > LEVEL_03 > 374A_BIO FAC. RESEARCH	Open	Carroll Seating	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 16:01:05

End of 001088 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001091	Missing casters		Webster > LEVEL_03 > 378_ORGANIS. BIO LAB	Open	Carroll Seating	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 16:12:52

2017-07-13 16:12:59

End of 001091 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001092	Install back panel		Webster > LEVEL_03 > 378_ORGANIS. BIO LAB	Open	Carroll Seating	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 16:13:59

End of 001092 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001093	Cut off shims under shelf brackets		Webster > LEVEL_03 > 378_ORGANIS. BIO LAB	Open	Carroll Seating	Architect Punch List	13 Jul 2017	18 Jul 2017



2017-07-13 16:15:42



2017-07-13 16:15:47

End of 001093 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001094	Wood to have vertical grain, finish to match others		Webster > LEVEL_03 > 378_ORGANIS. BIO LAB	Open	Carroll Seating	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 16:16:56

End of 001094 images

001101	P-lam under countertops to be cleaned and all scuff marks removed		Webster > LEVEL_03 > 378_ORGANIS. BIO LAB	Open	Carroll Seating	Architect Punch List	13 Jul 2017	18 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001105	Bottom of cabinet damaged		Webster > LEVEL_03 > 378_ORGANIS. BIO LAB	Open	Carroll Seating	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 16:41:09

2017-07-13 16:41:13

End of 001105 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001106	Scratch at base cabinet under sink (due to screw touching when sliding in)		Webster > LEVEL_03 > 378_ORGANIS. BIO LAB	Open	Carroll Seating	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 16:46:09

2017-07-13 16:46:17

End of 001106 images

001107	Broken glass in fume hood (ships 7/11)		Webster > LEVEL_03 > 386_BIO LAB PREP ROOM B	Open	Carroll Seating	Architect Punch List	13 Jul 2017	18 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001110	Remove scuffs from cylinder rack		Webster > LEVEL_03 > 388_MOLECULAR BIO LAB	Open	Carroll Seating	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 16:57:25

End of 001110 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001295	Edges of brackets to be ground smooth where cut off (under countertops)		Webster > LEVEL_03	Open	Carroll Seating	Architect Punch List	14 Jul 2017	19 Jul 2017

2017-07-14 09:43:07

End of 001295 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001298	Doors under sink not closing property		Webster > LEVEL_03 > C310_CORRIDOR	Open	Carroll Seating	Architect Punch List	14 Jul 2017	19 Jul 2017

2017-07-14 09:59:35

End of 001298 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000901	Remove surface rust from sink		Webster > LEVEL_03 > 300A_WORK / COPY	Open	Deluca Plumbing	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 13:47:44

End of 000901 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001334	Dent in drinking fountain back panel		Webster > LEVEL_03 > 375_JC	Open	Deluca Plumbing	Architect Punch List	14 Jul 2017	19 Jul 2017

2017-07-14 12:07:36

End of 001334 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000899	Trim base so that cabinet doors can be installed		Webster > LEVEL_03 > 300A_WORK / COPY	Open	Flooring Systems, Inc.	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 13:46:09

End of 000899 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000913	Carpet should extend to curtainwall, base to be secured to column		Webster > LEVEL_03 > 305_OFF. STAFF (3)	Open	Flooring Systems, Inc.	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 14:22:13

End of 000913 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000918	There should be no gaps at inside and outside corners on base. Seal as needed. (Typical all locations)		Webster > LEVEL_03	Open	Flooring Systems, Inc.	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 14:29:26

2017-07-12 14:29:32

End of 000918 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000939	Fill in carpet behind column		Webster > LEVEL_03 > 317_OFF. SCI	Open	Flooring Systems, Inc.	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 15:04:35

End of 000939 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001054	Flooring should extend to curtainwall		Webster > LEVEL_03 > 360_OFF. ASP	Open	Flooring Systems, Inc.	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 13:56:59

2017-07-13 13:57:04

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-13 13:57:14

2017-07-13 13:57:18

End of 001054 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001309	Damaged floor (from bio safety cabinets)		Webster > LEVEL_03 > 383_CELL BIO / BIOCHEM LAB	Open	Flooring Systems, Inc.	Architect Punch List	14 Jul 2017	19 Jul 2017

2017-07-14 10:41:05

End of 001309 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001310	Missing base		Webster > LEVEL_03 > 383_CELL BIO / BIOCHEM LAB	Open	Flooring Systems, Inc.	Architect Punch List	14 Jul 2017	19 Jul 2017



2017-07-14 10:42:05

End of 001310 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001333	Install transition strip at flooring		Webster > LEVEL_03 > 375_JC	Open	Flooring Systems, Inc.	Architect Punch List	14 Jul 2017	19 Jul 2017

2017-07-14 12:03:27

End of 001333 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000898	Outlet cover to match others		Webster > LEVEL_03 > 300A_WORK / COPY	Open	Guarantee Electric	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 13:45:05

End of 000898 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000906	Missing switch cover		Webster > LEVEL_03 > 300B_DATA	Open	Guarantee Electric	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 13:52:52

End of 000906 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000925	Fire caulk penetrations		Webster > LEVEL_03 > 310A_ELEC	Open	Guarantee Electric	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 14:40:41

End of 000925 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000992	Wires hanging from light		Webster > LEVEL_03 > 323_OFF. SCI	Open	Guarantee Electric	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 10:43:21

End of 000992 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001002	Seal penetrations in wall for light		Webster > LEVEL_03 > 317_OFF. SCI	Open	Guarantee Electric	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 11:10:02

End of 001002 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001009	Lower light escutcheon		Webster > LEVEL_03 > 335_OFF. ASP	Open	Guarantee Electric	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 11:18:45

End of 001009 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001023	Lower escutcheon		Webster > LEVEL_03 > 342_OFF. ASP	Open	Guarantee Electric	Architect Punch List	13 Jul 2017	18 Jul 2017



2017-07-13 13:08:25

End of 001023 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001036	Install speaker covers - scope?		Webster > LEVEL_03 > 352_CONF ROOM (10)	Open	Guarantee Electric	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 13:29:31

End of 001036 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001040	Panel to be flush against wall		Webster > LEVEL_03 > 352_CONF ROOM (10)	Open	Guarantee Electric	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 13:32:58

2017-07-13 13:33:05

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-13 13:37:39

2017-07-13 13:37:51

End of 001040 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001044	Install cover		Webster > LEVEL_03 > 352_CONF ROOM (10)	Open	Guarantee Electric	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 13:36:33

End of 001044 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001050	Install cover		Webster > LEVEL_03 > 356_COMMONS/ (OFF FUT)	Open	Guarantee Electric	Architect Punch List	13 Jul 2017	18 Jul 2017



2017-07-13 13:46:51

End of 001050 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001053	Raise lights per observation report #?		Webster > LEVEL_03 > 356_COMMONS/ (OFF FUT)	Open	Guarantee Electric	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 13:51:15

End of 001053 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001055	Lower escutcheon		Webster > LEVEL_03 > 360_OFF. ASP	Open	Guarantee Electric	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 13:57:54

End of 001055 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001079	Missing cover		Webster > LEVEL_03 > 372D_OFF. LAB MGR	Open	Guarantee Electric	Architect Punch List	13 Jul 2017	18 Jul 2017



2017-07-13 15:34:36

End of 001079 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001081	Install cover		Webster > LEVEL_03 > 374A_BIO FAC. RESEARCH	Open	Guarantee Electric	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 15:52:16



2017-07-13 15:52:24

End of 001081 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001096	Wiremold to extend to end of backsplash		Webster > LEVEL_03 > 378_ORGANIS. BIO LAB	Open	Guarantee Electric	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 16:19:24

End of 001096 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001109	Missing cover		Webster > LEVEL_03 > 386_BIO LAB PREP ROOM B	Open	Guarantee Electric	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 16:56:45

End of 001109 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001299	Finish cable tray		Webster > LEVEL_03 > 391_ANATOMY / PHYSIO LAB	Open	Guarantee Electric	Architect Punch List	14 Jul 2017	19 Jul 2017



2017-07-14 10:00:49

End of 001299 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001308	Install missing covers		Webster > LEVEL_03 > 389_BIO LAB PREP ROOM A	Open	Guarantee Electric	Architect Punch List	14 Jul 2017	19 Jul 2017

2017-07-14 10:21:34

End of 001308 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000923	Replace grill with correct size		Webster > LEVEL_03 > 310A_ELEC	In Dispute	ICON Mechanical	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 14:39:08

End of 000923 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000924	Fire caulk penetrations		Webster > LEVEL_03 > 310A_ELEC	In Dispute	ICON Mechanical	Architect Punch List	12 Jul 2017	17 Jul 2017



2017-07-12 14:39:55

End of 000924 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000931	Scratch on diffuser		Webster > LEVEL_03 > 312_STOR.	Ready to Inspect	ICON Mechanical	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 14:49:15

End of 000931 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001017	Replace grill (angle cut poorly)		Webster > LEVEL_03 > 342_OFF. ASP	Ready to Inspect	ICON Mechanical	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 12:55:07

End of 001017 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001028	Secure cover		Webster > LEVEL_03 > 342_OFF. ASP	In Dispute	ICON Mechanical	Architect Punch List	13 Jul 2017	18 Jul 2017



2017-07-13 13:16:05

2017-07-13 13:16:09

End of 001028 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001034	Secure cover		Webster > LEVEL_03 > 352_CONF ROOM (10)	Ready to Inspect	ICON Mechanical	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 13:23:49

End of 001034 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001045	Cover needed between wall and column		Webster > LEVEL_03 > 356_COMMONS/ (OFF FUT)	Open	ICON Mechanical	Architect Punch List	13 Jul 2017	18 Jul 2017



2017-07-13 13:42:52

End of 001045 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001061	End cap needed		Webster > LEVEL_03 > 364_SM. MTG.	Open	ICON Mechanical	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 14:08:43

End of 001061 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001063	Diffuser bent		Webster > LEVEL_03 > 364_SM. MTG.	Ready to Inspect	ICON Mechanical	Architect Punch List	13 Jul 2017	18 Jul 2017



2017-07-13 14:10:40

End of 001063 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001090	DI water drips at north faucet		Webster > LEVEL_03 > 378_ORGANIS. BIO LAB	Ready to Inspect	ICON Mechanical	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 16:08:58

End of 001090 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001306	Diffuser to lay flush in ceiling		Webster > LEVEL_03 > 389_BIO LAB PREP ROOM A	In Dispute	ICON Mechanical	Architect Punch List	14 Jul 2017	19 Jul 2017

2017-07-14 10:19:28

End of 001306 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001033	Fabric damaged at end		Webster > LEVEL_03 > 352_CONF ROOM (10)	Open	Interior Investments	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 13:22:41

2017-07-13 13:22:46

End of 001033 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001304	Shades not aligning with mullions		Webster > LEVEL_03 > 391_ANATOMY / PHYSIO LAB	Open	Interior Investments	Architect Punch List	14 Jul 2017	19 Jul 2017

2017-07-14 10:06:55

2017-07-14 10:07:01

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-14 10:07:08

End of 001304 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000912	Repair scratches and dings in curtainwall		Webster > LEVEL_03 > 305_OFF. STAFF (3)	Open	National Glass & Glazing, Inc.	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 14:20:23

2017-07-12 14:20:33

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-12 14:20:59

End of 000912 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000915	Touch up all scuffs on aluminum framing (typical all locations)		Webster > LEVEL_03	Open	National Glass & Glazing, Inc.	Architect Punch List	12 Jul 2017	17 Jul 2017



2017-07-12 14:24:42

End of 000915 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000946	Fix mullion		Webster > LEVEL_03 > 319_OFF. SCI	Open	National Glass & Glazing, Inc.	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 15:21:07

End of 000946 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000961	Scratches on curtainwall		Webster > LEVEL_03 > 325_INTERVIEW / CONF.	Open	National Glass & Glazing, Inc.	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 15:56:28

End of 000961 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000999	Face of horizontal mullions to be flush with vertical mullions		Webster > LEVEL_03 > 319_OFF. SCI	Open	National Glass & Glazing, Inc.	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 10:57:33

End of 000999 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001006	Scratches in interior glass must be corrected, glass will be used as a marker board.		Webster > LEVEL_03 > 317_OFF. SCI	Open	National Glass & Glazing, Inc.	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 11:12:20

End of 001006 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001013	Scratches on curtainwall		Webster > LEVEL_03 > 337_OFF. ASP	Open	National Glass & Glazing, Inc.	Architect Punch List	13 Jul 2017	18 Jul 2017



2017-07-13 12:43:44

2017-07-13 12:43:50

End of 001013 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001019	Repair curtainwall mullion and all scratches and holes in mullions, clean up joints on angled corner.		Webster > LEVEL_03 > 342_OFF. ASP	Open	National Glass & Glazing, Inc.	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 12:58:00

2017-07-13 12:58:06

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-13 12:58:13

2017-07-13 12:58:21

End of 001019 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001024	Touchup scratches on curtainwall		Webster > LEVEL_03 > 342_OFF. ASP	Open	National Glass & Glazing, Inc.	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 13:09:36

End of 001024 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001032	Touchup scratches on curtainwall		Webster > LEVEL_03 > 352_CONF ROOM (10)	Open	National Glass & Glazing, Inc.	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 13:21:14

2017-07-13 13:21:18

End of 001032 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001051	Remove rust spots (exterior)		Webster > LEVEL_03 > 356_COMMONS/ (OFF FUT)	Open	National Glass & Glazing, Inc.	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 13:48:46

End of 001051 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001060	Top of vertical mullion "depressed"		Webster > LEVEL_03 > 362_OFF. HR DIR	Open	National Glass & Glazing, Inc.	Architect Punch List	13 Jul 2017	18 Jul 2017



2017-07-13 14:04:44

End of 001060 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001064	Touchup scratches on curtainwall		Webster > LEVEL_03 > 364_SM. MTG.	Open	National Glass & Glazing, Inc.	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 14:11:13

End of 001064 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001097	Gap under door too large		Webster > LEVEL_03 > 378_ORGANIS. BIO LAB	Open	National Glass & Glazing, Inc.	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 16:28:01

End of 001097 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001069	Scratches in elevator jamb, should be cover that wraps, not just plate, gaps too large		Webster > LEVEL_03	Open	Otis Elevator Company	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 15:02:19

2017-07-13 15:02:23

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-13 15:02:28

2017-07-13 15:02:37

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-13 15:03:08

End of 001069 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000897	Adjust all shelves and cabinets doors to be flush and level		Webster > LEVEL_03	Open	PARIC (Self-Perform)	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 13:44:07

End of 000897 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000900	Install base cabinet doors (after base is corrected)		Webster > LEVEL_03 > 300A_WORK / COPY	Open	PARIC (Self-Perform)	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 13:47:05

End of 000900 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000902	Finish edge around opening for sliding door (proposed to use break metal)		Webster > LEVEL_03 > 300A_WORK / COPY	Open	PARIC (Self-Perform)	Architect Punch List	12 Jul 2017	17 Jul 2017



2017-07-12 13:48:48

End of 000902 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000927	Chip on door		Webster > LEVEL_03 > 311_OFF. SCI	Open	PARIC (Self-Perform)	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 14:44:30

End of 000927 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000928	Patch hole in drywall		Webster > LEVEL_03 > 311_OFF. SCI	Open	PARIC (Self-Perform)	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 14:45:13

End of 000928 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000962	Scratches on door		Webster > LEVEL_03 > 325_INTERVIEW / CONF.	Open	PARIC (Self-Perform)	Architect Punch List	12 Jul 2017	17 Jul 2017



2017-07-12 15:57:58

2017-07-12 15:58:07

End of 000962 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001005	Chip in door		Webster > LEVEL_03 > 317_OFF. SCI	Open	PARIC (Self-Perform)	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 11:11:44

End of 001005 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001021	Chips in door		Webster > LEVEL_03 > 342_OFF. ASP	Open	PARIC (Self-Perform)	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 13:00:54

2017-07-13 13:01:01

End of 001021 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001025	3 sided emseal needed at both sides of wall		Webster > LEVEL_03 > 344_OFF. ASP	Open	PARIC (Self-Perform)	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 13:10:01

End of 001025 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001030	Repair "dent" in drywall above shade		Webster > LEVEL_03 > 352_CONF ROOM (10)	Open	PARIC (Self-Perform)	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 13:19:15

End of 001030 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001041	Patch drywall		Webster > LEVEL_03 > 352_CONF ROOM (10)	Open	PARIC (Self-Perform)	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 13:34:23

End of 001041 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001043	Adjust door handle		Webster > LEVEL_03 > 352_CONF ROOM (10)	Open	PARIC (Self-Perform)	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 13:35:55

End of 001043 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001047	Repair drywall		Webster > LEVEL_03 > 356_COMMONS/ (OFF FUT)	Open	PARIC (Self-Perform)	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 13:44:35

End of 001047 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001052	Finish around fp escutcheons		Webster > LEVEL_03 > 356_COMMONS/ (OFF FUT)	Open	PARIC (Self-Perform)	Architect Punch List	13 Jul 2017	18 Jul 2017



2017-07-13 13:49:28

2017-07-13 13:49:36

End of 001052 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001068	Scratches in feature wall		Webster > LEVEL_03	Open	PARIC (Self-Perform)	Architect Punch List	13 Jul 2017	18 Jul 2017



2017-07-13 14:52:24

2017-07-13 14:52:36

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-13 14:52:39

2017-07-13 14:52:46

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date



2017-07-13 14:55:43

2017-07-13 14:55:49

End of 001068 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001070	Missing counter		Webster > LEVEL_03 > C370B_COMMONS	Open	PARIC (Self-Perform)	Architect Punch List	13 Jul 2017	18 Jul 2017



2017-07-13 15:09:07

End of 001070 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001085	Patch drywall		Webster > LEVEL_03 > 374B_TISSUE CULTURE A	Open	PARIC (Self-Perform)	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 15:57:58



2017-07-13 15:58:04

End of 001085 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001086	Door frame damaged, install silencers		Webster > LEVEL_03 > 374B_TISSUE CULTURE A	Open	PARIC (Self-Perform)	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 15:58:56

2017-07-13 16:00:24

End of 001086 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001089	Missing casework for aquarium, wall should be changed to filler panel.		Webster > LEVEL_03 > 378_ORGANIS. BIO LAB	Open	PARIC (Self-Perform)	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 16:06:35

End of 001089 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001104	Touchup drywall		Webster > LEVEL_03 > 378_ORGANIS. BIO LAB	Open	PARIC (Self-Perform)	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 16:40:08



2017-07-13 16:40:13

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-13 16:40:22

End of 001104 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001108	Door frames damaged		Webster > LEVEL_03 > 386_BIO LAB PREP ROOM B	Open	PARIC (Self-Perform)	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 16:49:48

2017-07-13 16:49:54

End of 001108 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001113	Patch drywall at window sill		Webster > LEVEL_03 > 388_MOLECULAR BIO LAB	Open	PARIC (Self-Perform)	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 17:06:22

End of 001113 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001305	Finish drywall		Webster > LEVEL_03 > 389_BIO LAB PREP ROOM A	Open	PARIC (Self-Perform)	Architect Punch List	14 Jul 2017	19 Jul 2017

2017-07-14 10:18:57

End of 001305 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001311	Patch drywall		Webster > LEVEL_03 > 383_CELL BIO / BIOCHEM LAB	Open	PARIC (Self-Perform)	Architect Punch List	14 Jul 2017	19 Jul 2017

2017-07-14 10:42:45

End of 001311 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001321	Remove red scuff from door		Webster > LEVEL_03 > 377_WOMEN	Open	PARIC (Self-Perform)	Architect Punch List	14 Jul 2017	19 Jul 2017

2017-07-14 11:19:47

End of 001321 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001322	Touch up drywall		Webster > LEVEL_03 > 377_WOMEN	Open	PARIC (Self-Perform)	Architect Punch List	14 Jul 2017	19 Jul 2017



2017-07-14 11:25:13

2017-07-14 11:25:17

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-14 11:25:28

End of 001322 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001324	All partition hardware to be tightened.		Webster > LEVEL_03 > 377_WOMEN	Open	PARIC (Self-Perform)	Architect Punch List	14 Jul 2017	19 Jul 2017

2017-07-14 11:27:04



2017-07-14 11:27:08

End of 001324 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001329	Seal from wall to cold room		Webster > LEVEL_03	Open	PARIC (Self-Perform)	Architect Punch List	14 Jul 2017	19 Jul 2017

2017-07-14 11:56:48

2017-07-14 11:56:52

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-14 11:56:55

End of 001329 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001332	Repair gap in FRP at switch		Webster > LEVEL_03 > 375_JC	Open	PARIC (Self-Perform)	Architect Punch List	14 Jul 2017	19 Jul 2017

2017-07-14 12:03:04

End of 001332 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000921	Touch up penetrations		Webster > LEVEL_03 > 310B_STOR	Open	Paric Corp.	Architect Punch List	12 Jul 2017	17 Jul 2017



2017-07-12 14:35:36

End of 000921 images

000934	Acoustic sealant needed at all radiant heat penetrations (typical) - scope?		Webster > LEVEL_03 > 313_OFF. SCI	Open	Paric Corp.	Architect Punch List	12 Jul 2017	17 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001112	Cut off bolt, grind off concrete, repaint after. Scope?		Webster > LEVEL_03 > 388_MOLECULAR BIO LAB	Open	Paric Corp.	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 17:02:52



2017-07-13 17:02:59

End of 001112 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001314	Approved acoustical sealant solution needed where emseal cannot be used.		Webster > LEVEL_03 > 383_CELL BIO / BIOCHEM LAB	Open	Paric Corp.	Architect Punch List	14 Jul 2017	19 Jul 2017

2017-07-14 10:58:06

End of 001314 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001335	Hinge missing cap - bio cold		Webster > LEVEL_03 > 375_JC	Open	Paric Corp.	Architect Punch List	14 Jul 2017	19 Jul 2017

2017-07-14 12:09:26

End of 001335 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000903	Touchup paint		Webster > LEVEL_03 > 300A_WORK / COPY	Open	Spectra Painting	Architect Punch List	12 Jul 2017	17 Jul 2017



2017-07-12 13:49:51

2017-07-12 13:49:55

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date



2017-07-12 13:49:59

2017-07-12 13:50:10

End of 000903 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000905	Touchup door paint		Webster > LEVEL_03 > 300B_DATA	Open	Spectra Painting	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 13:52:11

End of 000905 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000907	Touchup paint		Webster > LEVEL_03 > 300B_DATA	Open	Spectra Painting	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 14:09:53

2017-07-12 14:10:04

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-12 14:10:11

End of 000907 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000910	Remove paint from pipes		Webster > LEVEL_03 > 319_OFF. SCI	Open	Spectra Painting	Architect Punch List	12 Jul 2017	17 Jul 2017



2017-07-12 14:18:07

End of 000910 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000911	Paint all copper pipes pewter (typical all locations)		Webster > LEVEL_03 > 319_OFF. SCI	Open	Spectra Painting	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 14:19:19

End of 000911 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000914	Paint edges of walls not covered by mullion mate (typical at all locations)		Webster > LEVEL_03 > 305_OFF. STAFF (3)	Open	Spectra Painting	Architect Punch List	12 Jul 2017	17 Jul 2017



2017-07-12 14:23:26

End of 000914 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000916	Touch up paint		Webster > LEVEL_03	Open	Spectra Painting	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 14:26:50

2017-07-12 14:26:56

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-12 14:27:01



2017-07-12 14:27:19

End of 000916 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000919	Touch up paint		Webster > LEVEL_03 > 306_OFF. SCI	Open	Spectra Painting	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 14:32:44



2017-07-12 14:32:52

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-12 14:32:57

End of 000919 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000922	Touch up paint on door frames		Webster > LEVEL_03 > 310B_STOR	Open	Spectra Painting	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 14:36:24

2017-07-12 14:36:30

End of 000922 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000926	Touch up paint on door		Webster > LEVEL_03 > 310A_ELEC	Open	Spectra Painting	Architect Punch List	12 Jul 2017	17 Jul 2017



2017-07-12 14:41:51

End of 000926 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000929	Clean paint from curtainwall		Webster > LEVEL_03 > 311_OFF. SCI	Open	Spectra Painting	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 14:46:11

End of 000929 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000930	Touch up paint		Webster > LEVEL_03 > 311_OFF. SCI	Open	Spectra Painting	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 14:46:50

2017-07-12 14:46:59

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-12 14:47:04

2017-07-12 14:47:09

End of 000930 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000932	Touch up paint		Webster > LEVEL_03 > 312_STOR.	Open	Spectra Painting	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 14:49:54

2017-07-12 14:49:56

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date



2017-07-12 14:50:03

End of 000932 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000933	Touch up all paint at high ceiling and exposed beam		Webster > LEVEL_03 > 312_STOR.	Open	Spectra Painting	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 14:52:58

2017-07-12 14:53:05

End of 000933 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000936	Touchup paint		Webster > LEVEL_03 > 315_OFF. SCI	Open	Spectra Painting	Architect Punch List	12 Jul 2017	17 Jul 2017



2017-07-12 14:59:08

2017-07-12 14:59:12

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-12 14:59:23

End of 000936 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000937	Replace damaged ceiling tile		Webster > LEVEL_03 > 315_OFF. SCI	Open	Spectra Painting	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 15:01:07

2017-07-12 15:01:14

End of 000937 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000940	Touch up paint		Webster > LEVEL_03 > 317_OFF. SCI	Open	Spectra Painting	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 15:07:42

2017-07-12 15:07:46

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-12 15:07:51

End of 000940 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000941	Replace damaged ceiling tile		Webster > LEVEL_03 > 317_OFF. SCI	Open	Spectra Painting	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 15:08:22

2017-07-12 15:08:33

End of 000941 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000942	Touch up paint		Webster > LEVEL_03 > 316_OFF. ASP	Open	Spectra Painting	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 15:11:01

2017-07-12 15:11:11

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-12 15:11:14

End of 000942 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000943	Replace damaged ceiling tile		Webster > LEVEL_03 > 316_OFF. ASP	Open	Spectra Painting	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 15:12:06

2017-07-12 15:12:09

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-12 15:12:13

End of 000943 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000944	Touch up paint		Webster > LEVEL_03 > 318_OFF. ASP	Open	Spectra Painting	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 15:14:07

2017-07-12 15:14:12

End of 000944 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000945	Replace damaged ceiling tile		Webster > LEVEL_03 > 318_OFF. ASP	Open	Spectra Painting	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 15:14:55

2017-07-12 15:15:02

End of 000945 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000948	Touch up paint		Webster > LEVEL_03 > 319_OFF. SCI	Open	Spectra Painting	Architect Punch List	12 Jul 2017	17 Jul 2017



2017-07-12 15:24:14



2017-07-12 15:24:20

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-12 15:24:28

End of 000948 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000949	Replace damaged ceiling tile		Webster > LEVEL_03 > 319_OFF. SCI	Open	Spectra Painting	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 15:25:07

2017-07-12 15:25:13

End of 000949 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000950	Touch up paint		Webster > LEVEL_03 > 321_OFF. SCI	Open	Spectra Painting	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 15:27:46

2017-07-12 15:27:50

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-12 15:27:54

End of 000950 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000951	Replace damaged ceiling tile		Webster > LEVEL_03 > 321_OFF. SCI	Open	Spectra Painting	Architect Punch List	12 Jul 2017	17 Jul 2017



2017-07-12 15:28:30

End of 000951 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000952	Touch up paint		Webster > LEVEL_03 > 320_OFF. ASP	Open	Spectra Painting	Architect Punch List	12 Jul 2017	17 Jul 2017



2017-07-12 15:31:46

End of 000952 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000953	Replace damaged ceiling tile		Webster > LEVEL_03 > 320_OFF. ASP	Open	Spectra Painting	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 15:32:10



2017-07-12 15:32:16

End of 000953 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000954	Replace damaged ceiling tile		Webster > LEVEL_03 > 322_OFF. ASP	Open	Spectra Painting	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 15:35:56

2017-07-12 15:36:04

End of 000954 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000955	Touch up paint		Webster > LEVEL_03 > 322_OFF. ASP	Open	Spectra Painting	Architect Punch List	12 Jul 2017	17 Jul 2017



2017-07-12 15:36:38



2017-07-12 15:36:43

End of 000955 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000957	Replace damaged ceiling tile		Webster > LEVEL_03 > 323_OFF. SCI	Open	Spectra Painting	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 15:40:41

2017-07-12 15:40:44

End of 000957 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000958	Touch up paint		Webster > LEVEL_03 > 323_OFF. SCI	Open	Spectra Painting	Architect Punch List	12 Jul 2017	17 Jul 2017



2017-07-12 15:41:09

2017-07-12 15:41:14

End of 000958 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000959	Touch up paint		Webster > LEVEL_03 > 325_INTERVIEW / CONF.	Open	Spectra Painting	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 15:54:52

2017-07-12 15:55:15

End of 000959 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000960	Replace damaged ceiling tile		Webster > LEVEL_03 > 325_INTERVIEW / CONF.	Open	Spectra Painting	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 15:55:46

2017-07-12 15:55:51

End of 000960 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000991	Repaint walls as needed		Webster > LEVEL_03 > 323_OFF. SCI	Open	Spectra Painting	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 10:42:10

2017-07-13 10:42:21

End of 000991 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000995	Repaint walls as needed		Webster > LEVEL_03 > 321_OFF. SCI	Open	Spectra Painting	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 10:48:16

2017-07-13 10:48:27

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date



2017-07-13 10:48:34

2017-07-13 10:48:42

End of 000995 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000996	Repaint walls as needed		Webster > LEVEL_03 > 319_OFF. SCI	Open	Spectra Painting	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 10:50:42

2017-07-13 10:50:48

End of 000996 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001000	Repaint walls as needed		Webster > LEVEL_03 > 332_OFF. ADJ.	Open	Spectra Painting	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 10:59:18



2017-07-13 10:59:25

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date



2017-07-13 11:04:27

End of 001000 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001003	Replace damaged ceiling tile		Webster > LEVEL_03 > 317_OFF. SCI	Open	Spectra Painting	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 11:10:44

End of 001003 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001004	Repaint walls as needed		Webster > LEVEL_03 > 317_OFF. SCI	Open	Spectra Painting	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 11:11:04

2017-07-13 11:11:10

End of 001004 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001008	Replace damaged ceiling tile		Webster > LEVEL_03 > 335_OFF. ASP	Open	Spectra Painting	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 11:18:18

End of 001008 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001010	Repaint walls as needed		Webster > LEVEL_03 > 335_OFF. ASP	Open	Spectra Painting	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 11:19:17



2017-07-13 11:19:25

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-13 11:19:27

End of 001010 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001012	Repaint walls as needed		Webster > LEVEL_03 > 337_OFF. ASP	Open	Spectra Painting	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 12:43:04

2017-07-13 12:43:11

End of 001012 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001015	Repaint walls as needed		Webster > LEVEL_03 > 337_OFF. ASP	Open	Spectra Painting	Architect Punch List	13 Jul 2017	18 Jul 2017



2017-07-13 12:46:15 Repaint entire area

2017-07-13 12:46:22

End of 001015 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001020	Repaint walls as needed		Webster > LEVEL_03 > 342_OFF. ASP	Open	Spectra Painting	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 12:59:31

2017-07-13 12:59:37

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date



2017-07-13 12:59:54

End of 001020 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001026	Repaint walls as needed		Webster > LEVEL_03 > 346_OFF. ASP	Open	Spectra Painting	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 13:12:44

2017-07-13 13:12:50

End of 001026 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001027	Repaint walls as needed		Webster > LEVEL_03 > 348_OFF. ASP	Open	Spectra Painting	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 13:13:41

2017-07-13 13:13:48

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-13 13:13:58

2017-07-13 13:14:28

End of 001027 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001029	Repaint walls as needed		Webster > LEVEL_03 > 352_CONF ROOM (10)	Open	Spectra Painting	Architect Punch List	13 Jul 2017	18 Jul 2017



2017-07-13 13:18:13

2017-07-13 13:18:20

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-13 13:18:26

End of 001029 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001031	Paint drops on carpet		Webster > LEVEL_03 > 352_CONF ROOM (10)	Open	Spectra Painting	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 13:20:24

2017-07-13 13:20:28

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date



2017-07-13 13:20:32

2017-07-13 13:20:37

End of 001031 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001035	Need to continue finish coat of paint above steel beam		Webster > LEVEL_03 > 352_CONF ROOM (10)	Open	Spectra Painting	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 13:24:38

End of 001035 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001037	Repaint walls as needed		Webster > LEVEL_03 > 352_CONF ROOM (10)	Open	Spectra Painting	Architect Punch List	13 Jul 2017	18 Jul 2017



2017-07-13 13:30:18

2017-07-13 13:30:21

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-13 13:30:31

End of 001037 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001039	Paint panel white		Webster > LEVEL_03 > 352_CONF ROOM (10)	Open	Spectra Painting	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 13:31:59

End of 001039 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001042	Entire wall to be walltalker		Webster > LEVEL_03 > 352_CONF ROOM (10)	Open	Spectra Painting	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 13:34:57

End of 001042 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001046	Repaint walls as needed		Webster > LEVEL_03 > 356_COMMONS/ (OFF FUT)	Open	Spectra Painting	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 13:44:00



2017-07-13 13:44:07

End of 001046 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001048	touchup paint above beam		Webster > LEVEL_03 > 356_COMMONS/ (OFF FUT)	Open	Spectra Painting	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 13:45:21

End of 001048 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001049	End cap should be painted white at all locations including at yellow walls.		Webster > LEVEL_03 > 356_COMMONS/ (OFF FUT)	Open	Spectra Painting	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 13:45:45

End of 001049 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001057	Repaint walls as needed		Webster > LEVEL_03 > 360_OFF. ASP	Open	Spectra Painting	Architect Punch List	13 Jul 2017	18 Jul 2017



2017-07-13 13:58:50

2017-07-13 13:58:54

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-13 13:59:04

End of 001057 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001059	Repaint walls as needed		Webster > LEVEL_03 > 362_OFF. HR DIR	Open	Spectra Painting	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 14:02:59

2017-07-13 14:03:03

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date



2017-07-13 14:03:08



2017-07-13 14:03:12

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-13 14:03:17

End of 001059 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001066	Repaint walls as needed in corridor B		Webster > LEVEL_03	Open	Spectra Painting	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 14:37:53

2017-07-13 14:38:03

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-13 14:38:15

2017-07-13 14:38:39

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date



2017-07-13 14:39:08

2017-07-13 14:39:16

End of 001066 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001071	Repaint walls as needed		Webster > LEVEL_03 > 372C_LAB STOR.	Open	Spectra Painting	Architect Punch List	13 Jul 2017	18 Jul 2017



2017-07-13 15:20:53

2017-07-13 15:20:59

End of 001071 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001076	Repaint walls as needed		Webster > LEVEL_03 > 372B_LAB WASTE - BIO	Open	Spectra Painting	Architect Punch List	13 Jul 2017	18 Jul 2017



2017-07-13 15:29:02

2017-07-13 15:29:07

End of 001076 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001077	Replace damaged ceiling tile		Webster > LEVEL_03 > 372D_OFF. LAB MGR	Open	Spectra Painting	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 15:33:03

End of 001077 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001078	Repaint walls as needed		Webster > LEVEL_03 > 372D_OFF. LAB MGR	Open	Spectra Painting	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 15:34:05

2017-07-13 15:34:08

End of 001078 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001080	Clean paint from door		Webster > LEVEL_03 > 372D_OFF. LAB MGR	Open	Spectra Painting	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 15:36:26

End of 001080 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001083	Touchup paint		Webster > LEVEL_03 > 374A_BIO FAC. RESEARCH	Open	Spectra Painting	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 15:54:59

End of 001083 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001084	Touchup paint		Webster > LEVEL_03 > 374B_TISSUE CULTURE A	Open	Spectra Painting	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 15:56:21

2017-07-13 15:56:34

End of 001084 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001087	Clean paint from door		Webster > LEVEL_03 > 374B_TISSUE CULTURE A	Open	Spectra Painting	Architect Punch List	13 Jul 2017	18 Jul 2017



2017-07-13 16:00:00

End of 001087 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001103	Repaint walls as needed		Webster > LEVEL_03 > 378_ORGANIS. BIO LAB	Open	Spectra Painting	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 16:38:35

2017-07-13 16:38:43

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-13 16:38:53



2017-07-13 16:39:38

End of 001103 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001111	Remove paint from door		Webster > LEVEL_03 > 388_MOLECULAR BIO LAB	Open	Spectra Painting	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 17:01:18

2017-07-13 17:01:26

End of 001111 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001114	Repaint walls as needed		Webster > LEVEL_03 > 388_MOLECULAR BIO LAB	Open	Spectra Painting	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 17:07:59

2017-07-13 17:08:04

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-13 17:08:19



2017-07-13 17:08:31

End of 001114 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001301	Touch up paint		Webster > LEVEL_03 > 391_ANATOMY / PHYSIO LAB	Open	Spectra Painting	Architect Punch List	14 Jul 2017	19 Jul 2017

2017-07-14 10:02:26

2017-07-14 10:02:35

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-14 10:02:40

End of 001301 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001307	Touch up paint		Webster > LEVEL_03 > 389_BIO LAB PREP ROOM A	Open	Spectra Painting	Architect Punch List	14 Jul 2017	19 Jul 2017

2017-07-14 10:20:16

2017-07-14 10:20:32

End of 001307 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001312	Touch up paint		Webster > LEVEL_03 > 383_CELL BIO / BIOCHEM LAB	Open	Spectra Painting	Architect Punch List	14 Jul 2017	19 Jul 2017

2017-07-14 10:43:58

2017-07-14 10:44:25

End of 001312 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001319	Clean paint from partitions		Webster > LEVEL_03 > 379_MEN	Open	Spectra Painting	Architect Punch List	14 Jul 2017	19 Jul 2017

2017-07-14 11:14:21

End of 001319 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001320	Paint should not be "wavy" in and out at tile		Webster > LEVEL_03 > 379_MEN	Open	Spectra Painting	Architect Punch List	14 Jul 2017	19 Jul 2017



2017-07-14 11:15:26

End of 001320 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001326	Repaint walls as needed in N-S corridor		Webster > LEVEL_03	Open	Spectra Painting	Architect Punch List	14 Jul 2017	19 Jul 2017

2017-07-14 11:53:00

2017-07-14 11:53:07

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-14 11:53:21



2017-07-14 11:53:31

End of 001326 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001327	Paint should be grey at the soffit all the way to mullion (end of corridor)		Webster > LEVEL_03	Open	Spectra Painting	Architect Punch List	14 Jul 2017	19 Jul 2017

2017-07-14 11:53:56

End of 001327 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001331	Seal concrete		Webster > LEVEL_03 > 375_JC	Open	Spectra Painting	Architect Punch List	14 Jul 2017	19 Jul 2017

2017-07-14 12:02:13

End of 001331 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000904	Replace damaged ceiling tiles		Webster > LEVEL_03 > 300A_WORK / COPY	Open	St Charles Acoustics	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 13:51:11

2017-07-12 13:51:19

End of 000904 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000908	Replace damaged and scuffed ceiling tile in corridor		Webster > LEVEL_03	Open	St Charles Acoustics	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 14:12:56



2017-07-12 14:13:03

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date



2017-07-12 14:13:06

2017-07-12 14:13:19

End of 000908 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000917	Replace damaged and scuffed ceiling tiles		Webster > LEVEL_03 > 305_OFF. STAFF (3)	Open	St Charles Acoustics	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 14:28:07

2017-07-12 14:28:18

End of 000917 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000920	Replace damaged ceiling tile		Webster > LEVEL_03 > 306_OFF. SCI	Open	St Charles Acoustics	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 14:33:47

End of 000920 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000956	All cut edges to be painted		Webster > LEVEL_03 > 323_OFF. SCI	Open	St Charles Acoustics	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 15:39:59

2017-07-12 15:40:03

End of 000956 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000994	Repair ceiling as needed		Webster > LEVEL_03 > 323_OFF. SCI	Open	St Charles Acoustics	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 10:45:43

End of 000994 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000997	Replace ceiling components as needed		Webster > LEVEL_03 > 319_OFF. SCI	Open	St Charles Acoustics	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 10:52:07

End of 000997 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001001	Replace ceiling components as needed		Webster > LEVEL_03 > 332_OFF. ADJ.	Open	St Charles Acoustics	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 10:59:58

2017-07-13 11:00:06

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-13 11:00:34

End of 001001 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001011	Replace damaged ceiling tile		Webster > LEVEL_03 > 337_OFF. ASP	Open	St Charles Acoustics	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 12:42:17

End of 001011 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001014	Replace damaged ceiling tile		Webster > LEVEL_03 > 337_OFF. ASP	Open	St Charles Acoustics	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 12:45:36

End of 001014 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001018	Ceiling grid to be continuous past grill, back of grid should be cut out not tile		Webster > LEVEL_03 > 342_OFF. ASP	Open	St Charles Acoustics	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 12:55:58



2017-07-13 12:56:03

End of 001018 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001022	Repair ceiling components as needed -		Webster > LEVEL_03 > 342_OFF. ASP	Open	St Charles Acoustics	Architect Punch List	13 Jul 2017	18 Jul 2017



2017-07-13 13:07:36

2017-07-13 13:07:42

End of 001022 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001038	Repair ceiling components as needed -		Webster > LEVEL_03 > 352_CONF ROOM (10)	Open	St Charles Acoustics	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 13:31:12

2017-07-13 13:31:17

End of 001038 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001056	Repair ceiling components as needed -		Webster > LEVEL_03 > 360_OFF. ASP	Open	St Charles Acoustics	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 13:58:22

2017-07-13 13:58:24

End of 001056 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001058	Repair ceiling components as needed -		Webster > LEVEL_03 > 362_OFF. HR DIR	Open	St Charles Acoustics	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 14:02:21

End of 001058 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001062	Repair ceiling components as needed -		Webster > LEVEL_03 > 364_SM. MTG.	Open	St Charles Acoustics	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 14:10:08

2017-07-13 14:10:14

End of 001062 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001065	Repair ceiling components as needed in corridor B		Webster > LEVEL_03	Open	St Charles Acoustics	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 14:35:21



2017-07-13 14:35:30

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date



2017-07-13 14:35:42

2017-07-13 14:35:58

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-13 14:36:08

End of 001065 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001072	Repair ceiling components as needed -		Webster > LEVEL_03 > 372C_LAB STOR.	Open	St Charles Acoustics	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 15:22:09

End of 001072 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001102	Repair ceiling components as needed -		Webster > LEVEL_03 > 378_ORGANIS. BIO LAB	Open	St Charles Acoustics	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 16:37:36

2017-07-13 16:37:47

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-13 16:37:55

2017-07-13 16:38:01

End of 001102 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001302	Repair ceiling components as needed -		Webster > LEVEL_03 > 391_ANATOMY / PHYSIO LAB	Open	St Charles Acoustics	Architect Punch List	14 Jul 2017	19 Jul 2017

2017-07-14 10:03:03

2017-07-14 10:03:12

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-14 10:03:24

End of 001302 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001313	Repair ceiling components as needed -		Webster > LEVEL_03 > 383_CELL BIO / BIOCHEM LAB	Open	St Charles Acoustics	Architect Punch List	14 Jul 2017	19 Jul 2017

2017-07-14 10:57:13

2017-07-14 10:57:17

End of 001313 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001328	Repair ceiling components as needed in N-S corridor		Webster > LEVEL_03	Open	St Charles Acoustics	Architect Punch List	14 Jul 2017	19 Jul 2017

2017-07-14 11:55:01

2017-07-14 11:55:12

End of 001328 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001330	Install missing ceiling tile		Webster > LEVEL_03 > 375_JC	Open	St Charles Acoustics	Architect Punch List	14 Jul 2017	19 Jul 2017

2017-07-14 12:00:50

End of 001330 images

000909	Clean off curtainwall mullions		Webster > LEVEL_03	Open	Titan Contractor Services	Architect Punch List	12 Jul 2017	17 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000938	Clean off curtainwall		Webster > LEVEL_03 > 315_OFF. SCI	Open	Titan Contractor Services	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 15:02:13

End of 000938 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000947	Clean light		Webster > LEVEL_03 > 319_OFF. SCI	Open	Titan Contractor Services	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 15:23:34

2017-07-12 15:23:39

End of 000947 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000993	Clean top of curtainwall		Webster > LEVEL_03 > 323_OFF. SCI	Open	Titan Contractor Services	Architect Punch List	13 Jul 2017	18 Jul 2017



2017-07-13 10:44:03

End of 000993 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000998	Clean top of curtainwall		Webster > LEVEL_03 > 319_OFF. SCI	Open	Titan Contractor Services	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 10:52:47

End of 000998 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001016	Clean off curtainwall		Webster > LEVEL_03 > 337_OFF. ASP	Open	Titan Contractor Services	Architect Punch List	13 Jul 2017	18 Jul 2017

2017-07-13 12:47:52

2017-07-13 12:47:57

End of 001016 images

001115	All light fixtures to be cleaned throughout entire building.		Webster > LEVEL_03 > 388_MOLECULAR BIO LAB	Open	Titan Contractor Services	Architect Punch List	13 Jul 2017	18 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001300	Clean overhead service carrier		Webster > LEVEL_03 > 391_ANATOMY / PHYSIO LAB	Open	Titan Contractor Services	Architect Punch List	14 Jul 2017	19 Jul 2017

2017-07-14 10:01:41

End of 001300 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001316	Cleanup of base and toilets		Webster > LEVEL_03 > 379_MEN	Open	Titan Contractor Services	Architect Punch List	14 Jul 2017	19 Jul 2017

2017-07-14 11:11:14

2017-07-14 11:11:17

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-14 11:11:22

End of 001316 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
001323	Clean off tile/base trim/toilets/toilet paper holders/ mirrors		Webster > LEVEL_03 > 377_WOMEN	Open	Titan Contractor Services	Architect Punch List	14 Jul 2017	19 Jul 2017

2017-07-14 11:26:23

2017-07-14 11:26:27

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-14 11:26:31

2017-07-14 11:28:03

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-14 11:32:40

End of 001323 images