Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000675	Fire sprinkler head above ceiling		Webster > LEVEL_04 > 400B_DATA	Open	Ahern Fire Protection	Architect Punch List	11 Jul 2017	16 Jul 2017
000803	Cardboard shims to be removed from under countertop, back panel needed		Webster > LEVEL_04 > 478_CHEM LAB PREP	Open	Cannon Design	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 16:48:03

2017-07-11 16:48:07

End of 000803 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000848	All casework to be adjusted to be level with other doors/drawers (typical all locations)		Webster > LEVEL_04 > 491_CHEM LAB PHYSICAL	Open	Cannon Design	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 10:22:28

End of 000848 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000787	Missing filler panel		Webster > LEVEL_04 > 472_CHEM LAB - GENERAL	Open	Carroll Seating	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 15:34:29

End of 000787 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000788	Edge of countertop damaged at south table		Webster > LEVEL_04 > 472_CHEM LAB - GENERAL	Open	Carroll Seating	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 15:37:08

End of 000788 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000795	Replacement top needed (shipping 7/21)		Webster > LEVEL_04 > 472_CHEM LAB - GENERAL	Open	Carroll Seating	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 16:15:14

End of 000795 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000796	Confirm "auto sash return" on fume hoods (typical), gaskets should be flush		Webster > LEVEL_04 > 472_CHEM LAB - GENERAL	Open	Carroll Seating	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 16:20:58

2017-07-11 16:21:05

End of 000796 images

000797	Auto returns and slides need adjusted on most large drawers	Webster > LEVEL_04 > 472_CHEM LAB - GENERAL	Open	Carroll Seating	Architect Punch List	11 Jul 2017	16 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000798	Shelves loose in base cabinets. Carrol to check all and adjust as needed.		Webster > LEVEL_04 > 472_CHEM LAB - GENERAL	Open	Carroll Seating	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 16:27:51

End of 000798 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000799	Access panel should be added.		Webster > LEVEL_04 > 472_CHEM LAB - GENERAL	Open	Carroll Seating	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 16:29:44

End of 000799 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000805	Patch holes where screws are missing		Webster > LEVEL_04 > 478_CHEM LAB PREP	Open	Carroll Seating	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 16:51:19

2017-07-11 16:51:23

End of 000805 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000806	Shelf missing		Webster > LEVEL_04 > 480_CHEM LAB - ORGANIC	Open	Carroll Seating	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 17:00:15

End of 000806 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000807	Castors missing		Webster > LEVEL_04 > 480_CHEM LAB - ORGANIC	Open	Carroll Seating	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 17:01:15

End of 000807 images

000808	Slides and self closers need to be adjusted at drawers (typical)		Webster > LEVEL_04 > 480_CHEM LAB - ORGANIC	Open	Carroll Seating	Architect Punch List	11 Jul 2017	16 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000814	Finish edge needed at P-lam and countertop		Webster > LEVEL_04 > 480_CHEM LAB - ORGANIC	Open	Carroll Seating	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 17:13:24

End of 000814 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000815	Epoxy "bubble" on surface.		Webster > LEVEL_04 > 480_CHEM LAB - ORGANIC	Work Completed	Carroll Seating	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 17:14:35



2017-07-14 13:16:06

End of 000815 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000816	Change backsplash to 4" under wiremold		Webster > LEVEL_04 > 488_CHEM LAB - ANALYT / INORGANIC	Open	Carroll Seating	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 09:19:32

End of 000816 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000817	Replacement pegboard needed and cylinder rack needed.		Webster > LEVEL_04 > 488_CHEM LAB - ANALYT / INORGANIC	Open	Carroll Seating	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 09:21:09

End of 000817 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000818	Table missing		Webster > LEVEL_04 > 488_CHEM LAB - ANALYT / INORGANIC	Work Completed	Carroll Seating	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 09:25:53

2017-07-14 13:17:07

End of 000818 images

000819	Casters needed (typical)		Webster > LEVEL_04 > 488_CHEM LAB - ANALYT / INORGANIC	Open	Carroll Seating	Architect Punch List	12 Jul 2017	17 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000823	Scuff on table leg		Webster > LEVEL_04 > 488_CHEM LAB - ANALYT / INORGANIC	Open	Carroll Seating	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 09:31:53

End of 000823 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000824	Shelves missing in cabinet (multiple locations)		Webster > LEVEL_04 > 488_CHEM LAB - ANALYT / INORGANIC	Work Completed	Carroll Seating	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 09:32:40

2017-07-14 13:17:39

End of 000824 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000827	Void in edge of P-lam		Webster > LEVEL_04 > 488_CHEM LAB - ANALYT / INORGANIC	Open	Carroll Seating	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 09:35:32

End of 000827 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000831	Drywall to be finished at back wall under sink		Webster > LEVEL_04 > 488_CHEM LAB - ANALYT / INORGANIC	Open	Carroll Seating	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 09:43:22

End of 000831 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000832	Shelf that would have originally gone in this shelf but cannot fit should be provided for another cabinet.		Webster > LEVEL_04 > 488_CHEM LAB - ANALYT / INORGANIC	Open	Carroll Seating	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 09:44:14

End of 000832 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000833	Black mark on inside face of cabinet under sink		Webster > LEVEL_04 > 488_CHEM LAB - ANALYT / INORGANIC	Work Completed	Carroll Seating	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 09:46:10

2017-07-14 13:20:35

End of 000833 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000834	Pegboard to be replaced		Webster > LEVEL_04 > 491_CHEM LAB PHYSICAL	Open	Carroll Seating	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 09:49:44

End of 000834 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000835	Cabinet missing casters		Webster > LEVEL_04 > 491_CHEM LAB PHYSICAL	Open	Carroll Seating	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 09:53:32

End of 000835 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000838	Cabinet delaminating near pegboard		Webster > LEVEL_04 > 491_CHEM LAB PHYSICAL	Open	Carroll Seating	Architect Punch List	12 Jul 2017	17 Jul 2017



2017-07-12 10:05:06

End of 000838 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000841	Scratch on face of cabinet		Webster > LEVEL_04 > 491_CHEM LAB PHYSICAL	Open	Carroll Seating	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 10:07:34

End of 000841 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000844	Chipped paint on faceplates (multiple locations)		Webster > LEVEL_04 > 491_CHEM LAB PHYSICAL	Open	Carroll Seating	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 10:14:48



2017-07-12 10:17:08

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-12 10:17:21

End of 000844 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000846	Scratches on countertop		Webster > LEVEL_04 > 491_CHEM LAB PHYSICAL	Open	Carroll Seating	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 10:19:49

End of 000846 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000847	Chip at corner of casework door		Webster > LEVEL_04 > 491_CHEM LAB PHYSICAL	Open	Carroll Seating	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 10:21:36

End of 000847 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000849	Rough surface on corner of table leg		Webster > LEVEL_04 > 491_CHEM LAB PHYSICAL	Open	Carroll Seating	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 10:23:40

End of 000849 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000852	Mobile lab benches need extended shelf and "lips" (typical)		Webster > LEVEL_04	Open	Carroll Seating	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 10:29:17

End of 000852 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000853	Remainder of millwork to be installed		Webster > LEVEL_04	Open	Carroll Seating	Architect Punch List	12 Jul 2017	17 Jul 2017



2017-07-12 10:32:27

End of 000853 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000859	Fume hood to be installed closer to wall, no gap between top and bottom		Webster > LEVEL_04 > 483_CHEM LAB - RESEARCH	Work Completed	Carroll Seating	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 10:45:50

2017-07-14 13:26:59

End of 000859 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000860	Broken glass at fume hood		Webster > LEVEL_04 > 483_CHEM LAB - RESEARCH	Open	Carroll Seating	Architect Punch List	12 Jul 2017	17 Jul 2017



2017-07-12 10:46:42

End of 000860 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000861	Missing countertops (shipping 7/20)		Webster > LEVEL_04 > 483_CHEM LAB - RESEARCH	Open	Carroll Seating	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 10:47:44

End of 000861 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000862	Missing blade handles (shipping 7/7)		Webster > LEVEL_04 > 483_CHEM LAB - RESEARCH	Open	Carroll Seating	Architect Punch List	12 Jul 2017	17 Jul 2017



2017-07-12 10:50:46

End of 000862 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000864	Scratch on shelves		Webster > LEVEL_04 > 483_CHEM LAB - RESEARCH	Work Completed	Carroll Seating	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 10:58:40

2017-07-14 13:28:30

End of 000864 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000793	Screws needed in emergency eye washes		Webster > LEVEL_04 > 472_CHEM LAB - GENERAL	Work Completed	Deluca Plumbing	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 16:10:14

End of 000793 images

000822	Screws missing in emergency eye wash		Webster > LEVEL_04 > 488_CHEM LAB - ANALYT / INORGANIC	Open	Deluca Plumbing	Architect Punch List	12 Jul 2017	17 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000851	Emergency eye wash needs to be sealed against wall if not installed flush (typical)		Webster > LEVEL_04 > 491_CHEM LAB PHYSICAL	Open	Deluca Plumbing	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 10:27:49

End of 000851 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000653	Clean up grout at top of backsplash, fill holes, grout on bottom of cabinets		Webster > LEVEL_04 > 400A_WORK / COPY	Open	Flooring Systems, Inc.	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 09:25:52

2017-07-11 09:28:53

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-11 09:30:47

2017-07-11 09:31:42

End of 000653 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000655	Chipped tile at faceplate		Webster > LEVEL_04 > 400A_WORK / COPY	Open	Flooring Systems, Inc.	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 09:27:53

End of 000655 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000657	Missing base at cabinet, glue on face of cabinet		Webster > LEVEL_04 > 400A_WORK / COPY	Open	Flooring Systems, Inc.	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 09:34:34

End of 000657 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000660	Trim base and install missing base so that doors operate properly.		Webster > LEVEL_04 > 400A_WORK / COPY	Open	Flooring Systems, Inc.	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 09:50:24

End of 000660 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000682	Base needs to fit properly behind door		Webster > LEVEL_04 > 404_OFF. FLX	Open	Flooring Systems, Inc.	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 10:51:31

End of 000682 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000688	Float and carpet at exposed clips		Webster > LEVEL_04 > 403_OFF. FLX	Open	Flooring Systems, Inc.	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 11:02:37

2017-07-11 11:02:44

End of 000688 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000701	Corners must be tighter at base (Flooring systems to check all locations)		Webster > LEVEL_04 > 405_OFF. FLX	Open	Flooring Systems, Inc.	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 11:31:24

End of 000701 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000714	Flooring transition needed		Webster > LEVEL_04 > 410_ELEC	Open	Flooring Systems, Inc.	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 12:12:49

End of 000714 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000723	All voids to be sealed (flooring systems to check all locations)		Webster > LEVEL_04 > 412_TESTING	Open	Flooring Systems, Inc.	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 12:29:10

End of 000723 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000758	Carpet missing in corner		Webster > LEVEL_04 > 435_OFF. IL	Open	Flooring Systems, Inc.	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 13:59:00

End of 000758 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000772	Missing carpet in corner		Webster > LEVEL_04 > 452_OFF. TA	Open	Flooring Systems, Inc.	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 14:27:53

End of 000772 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000879	Tiles uneven, chipped		Webster > LEVEL_04 > 477_WOMEN	Open	Flooring Systems, Inc.	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 11:39:47

2017-07-12 11:39:50

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-12 11:39:54

2017-07-12 11:40:02

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date



2017-07-12 11:40:05

2017-07-12 11:40:09

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date



2017-07-12 11:40:23

End of 000879 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000883	Finish and seal floor		Webster > LEVEL_04 > 480_CHEM LAB - ORGANIC	Open	Flooring Systems, Inc.	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 12:53:38

End of 000883 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000886	Missing transition strip		Webster > LEVEL_04 > 475_LAB WASTE - CHEM	Open	Flooring Systems, Inc.	Architect Punch List	12 Jul 2017	17 Jul 2017



2017-07-12 12:59:39

End of 000886 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000894	Seal at flooring to curtainwall at north punch window		Webster > LEVEL_04	Open	Flooring Systems, Inc.	Architect Punch List	12 Jul 2017	17 Jul 2017



2017-07-12 13:26:24

End of 000894 images

000654	Properly secure outlet faceplate		Webster > LEVEL_04 > 400A_WORK / COPY	Open	Guarantee Electric	Architect Punch List	11 Jul 2017	16 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000664	Colors to match on faceplates		Webster > LEVEL_04 > 400A_WORK / COPY	Open	Guarantee Electric	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 10:01:34

End of 000664 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000669	Lower light escutcheon so that it does not push up ceiling grid		Webster > LEVEL_04 > 401_OFF. ADJ (4)	Open	Guarantee Electric	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 10:16:59

End of 000669 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000710	All penetrations to be fire caulked		Webster > LEVEL_04 > 410_ELEC	Open	Guarantee Electric	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 11:59:59



2017-07-11 12:12:25

End of 000710 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000856	Scratch on light fixture		Webster > LEVEL_04 > 489_CHEM INSTR. LAB	Open	Guarantee Electric	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 10:39:20

End of 000856 images

000873	Hand dryers to be installed		Webster > LEVEL_04 > 479_MEN	Open	Guarantee Electric	Architect Punch List	12 Jul 2017	17 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000882	Need switch cover		Webster > LEVEL_04 > 480_CHEM LAB - ORGANIC	Open	Guarantee Electric	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 12:52:23

End of 000882 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000711	All penetrations to be fire caulked		Webster > LEVEL_04 > 410_ELEC	Open	ICON Mechanical	Architect Punch List	11 Jul 2017	16 Jul 2017



2017-07-11 12:01:11

End of 000711 images

000773	Missing screws in floor diffusers (452 and 454)		Webster > LEVEL_04 > 452_OFF. TA	Open	ICON Mechanical	Architect Punch List	11 Jul 2017	16 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000854	Mechanical supports need painted, marks should be removed		Webster > LEVEL_04 > 489_CHEM INSTR. LAB	Open	ICON Mechanical	Architect Punch List	12 Jul 2017	17 Jul 2017



2017-07-12 10:34:00

2017-07-12 10:34:05

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date



2017-07-12 10:34:11

2017-07-12 10:34:16

End of 000854 images

000691	Shade needs a stop so it does not touch mullion at bottom (interior investments)		Webster > LEVEL_04 > 401_OFF. ADJ (4)	Open	Interior Investments	Architect Punch List	11 Jul 2017	16 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000734	Chain to be shortened (interior investments)		Webster > LEVEL_04 > 415_OFF. IL	Open	Interior Investments	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 12:53:55

End of 000734 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000737	Chain to be shortened (interior investments)		Webster > LEVEL_04 > 417_OFF. IL	Open	Interior Investments	Architect Punch List	11 Jul 2017	16 Jul 2017



2017-07-11 13:07:45

End of 000737 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000761	Shorten chain for shades (Interior investments)		Webster > LEVEL_04 > 441_SM. MTG.	Open	Interior Investments	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 14:03:56

End of 000761 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000804	Shades needed		Webster > LEVEL_04 > 478_CHEM LAB PREP	Open	Interior Investments	Architect Punch List	11 Jul 2017	16 Jul 2017



2017-07-11 16:49:16

End of 000804 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000842	Mullion should bridge gap between shades, need to be shifted - Interior investments		Webster > LEVEL_04 > 491_CHEM LAB PHYSICAL	Open	Interior Investments	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 10:10:52

End of 000842 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000755	Remove roofing adhesive from curtainwall		Webster > LEVEL_04 > 435_OFF. IL	Open	Kirberg Company	Architect Punch List	11 Jul 2017	16 Jul 2017



2017-07-11 13:53:30

2017-07-11 13:53:34

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-11 13:53:40

End of 000755 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000663	Scuffs on aluminum door frames, clean up sealant around frame, seal around entire frame		Webster > LEVEL_04 > 400A_WORK / COPY	Open	National Glass & Glazing, Inc.	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 10:00:10

2017-07-11 10:03:00

End of 000663 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000667	Door scuffed during glass installation		Webster > LEVEL_04 > 400A_WORK / COPY	Open	National Glass & Glazing, Inc.	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 10:13:44

End of 000667 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000672	Scuffs on aluminum framing		Webster > LEVEL_04 > 401_OFF. ADJ (4)	Open	National Glass & Glazing, Inc.	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 10:28:06

End of 000672 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000677	Scratch in glass near door		Webster > LEVEL_04 > 402_OFF. WORK STUDY	Open	National Glass & Glazing, Inc.	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 10:43:42

End of 000677 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000680	Aluminum frame over cut at hinge		Webster > LEVEL_04 > 404_OFF. FLX	Open	National Glass & Glazing, Inc.	Architect Punch List	11 Jul 2017	16 Jul 2017



2017-07-11 10:49:27

End of 000680 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000681	Sealant needed at aluminum frame		Webster > LEVEL_04 > 404_OFF. FLX	Open	National Glass & Glazing, Inc.	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 10:50:44

End of 000681 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000684	Sealant at aluminum frame		Webster > LEVEL_04 > 403_OFF. FLX	Open	National Glass & Glazing, Inc.	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 10:57:01

2017-07-11 10:57:05

End of 000684 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000693	Add sealant that matches carpet to hide void between floor and aluminum frame.		Webster > LEVEL_04 > 403_OFF. FLX	Open	National Glass & Glazing, Inc.	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 11:13:19

End of 000693 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000698	Gaskets at aluminum framing to be continuous with no holes (NGG to check all locations)		Webster > LEVEL_04 > 405_OFF. FLX	Open	National Glass & Glazing, Inc.	Architect Punch List	11 Jul 2017	16 Jul 2017



2017-07-11 11:26:26

End of 000698 images

000699	Add sealant that matches carpet at base of aluminum frame to fill void.		Webster > LEVEL_04 > 405_OFF. FLX	Open	National Glass & Glazing, Inc.	Architect Punch List	11 Jul 2017	16 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000702	No bubbles in sealant between glass (NGG to check all locations)		Webster > LEVEL_04 > 405_OFF. FLX	Open	National Glass & Glazing, Inc.	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 11:33:21

End of 000702 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000704	Scratches in aluminum framing, framing needs to be adjusted to be flush.		Webster > LEVEL_04 > 406_OFF. ADJ (4)	Open	National Glass & Glazing, Inc.	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 11:36:48

2017-07-11 11:36:53

End of 000704 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000707	Aluminum door frames scuffs and black marks.		Webster > LEVEL_04 > 407_OFF. STAFF	Open	National Glass & Glazing, Inc.	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 11:52:04

2017-07-11 11:52:11

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-11 11:52:15

End of 000707 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000717	Scratches in glass		Webster > LEVEL_04 > 411_OFFICE FLX	Open	National Glass & Glazing, Inc.	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 12:16:43

End of 000717 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000718	Caulk around aluminum frame, scuffs on frame		Webster > LEVEL_04 > 411_OFFICE FLX	Open	National Glass & Glazing, Inc.	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 12:18:07

End of 000718 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000721	Excess gasket material to be cut off		Webster > LEVEL_04 > 411_OFFICE FLX	Open	National Glass & Glazing, Inc.	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 12:21:50

End of 000721 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000726	Glass to be replaced due to small holes, to be caulked all around, gasket cannot be loose.		Webster > LEVEL_04 > 413_OFF. IL	Open	National Glass & Glazing, Inc.	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 12:36:13

2017-07-11 12:36:27

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-11 12:36:35

2017-07-11 12:36:54

End of 000726 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000731	Scuffs on aluminum framing		Webster > LEVEL_04 > 415_OFF. IL	Open	National Glass & Glazing, Inc.	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 12:44:53

2017-07-11 12:45:12

End of 000731 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000736	Scuffs on aluminum framing		Webster > LEVEL_04 > 416_OFF. IL WS (2)	Open	National Glass & Glazing, Inc.	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 13:06:04

End of 000736 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000738	Scuffs on aluminum framing		Webster > LEVEL_04 > 417_OFF. IL	Open	National Glass & Glazing, Inc.	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 13:08:41

End of 000738 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000739	Adjust aluminum framing to make gaps smaller		Webster > LEVEL_04 > 417_OFF. IL	Open	National Glass & Glazing, Inc.	Architect Punch List	11 Jul 2017	16 Jul 2017



2017-07-11 13:10:01

End of 000739 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000759	Touch up scratches at curtainwall		Webster > LEVEL_04 > 435_OFF. IL	Open	National Glass & Glazing, Inc.	Architect Punch List	11 Jul 2017	16 Jul 2017



2017-07-11 14:00:03

End of 000759 images

000767	Missing corrected frames	Webster > LEVEL_04 > 452_OFF. TA	Open	National Glass & Glazing, Inc.	Architect Punch List	11 Jul 2017	16 Jul 2017
000770	Missing corrected frames	Webster > LEVEL_04 > 454_OFF. INTL	Open	National Glass & Glazing, Inc.	Architect Punch List	11 Jul 2017	16 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000810	Seal around aluminum frame		Webster > LEVEL_04 > 480_CHEM LAB - ORGANIC	Open	National Glass & Glazing, Inc.	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 17:04:59

End of 000810 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000811	Sealant needed at bottom of aluminum frames in all lab spaces (typical). Should be grey to match flooring.		Webster > LEVEL_04	Open	National Glass & Glazing, Inc.	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 17:09:24

End of 000811 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000836	Secure cover at curtainwall		Webster > LEVEL_04 > 491_CHEM LAB PHYSICAL	Open	National Glass & Glazing, Inc.	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 10:00:41

End of 000836 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000858	Remove all stickers from interior framing and doors		Webster > LEVEL_04 > 489_CHEM INSTR. LAB	Open	National Glass & Glazing, Inc.	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 10:42:59

End of 000858 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000865	Gap to be sealed at top of frame		Webster > LEVEL_04 > 483_CHEM LAB - RESEARCH	Open	National Glass & Glazing, Inc.	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 10:59:56

End of 000865 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000782	Otis to reinstall panel correctly		Webster > LEVEL_04	Open	Otis Elevator Company	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 15:17:18

End of 000782 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000651	Cork board to be installed on east wall		Webster > LEVEL_04 > 400A_WORK / COPY	Open	PARIC (Self-Perform)	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 09:21:02

End of 000651 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000652	Cabinet door to be installed		Webster > LEVEL_04 > 400A_WORK / COPY	Open	PARIC (Self-Perform)	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 09:24:27

End of 000652 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000658	Cabinet doors to be adjusted to be flush		Webster > LEVEL_04 > 400A_WORK / COPY	Open	PARIC (Self-Perform)	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 09:39:23

2017-07-11 09:47:09

End of 000658 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000662	Install sealant at back of west countertop		Webster > LEVEL_04 > 400A_WORK / COPY	Open	PARIC (Self-Perform)	Architect Punch List	11 Jul 2017	16 Jul 2017



2017-07-11 09:58:57

End of 000662 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000665	Finish drywall patch above door.		Webster > LEVEL_04 > 400B_DATA	Open	PARIC (Self-Perform)	Architect Punch List	11 Jul 2017	16 Jul 2017



2017-07-11 10:08:17

End of 000665 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000666	Scuff in door		Webster > LEVEL_04 > 400A_WORK / COPY	Open	PARIC (Self-Perform)	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 10:12:15

End of 000666 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000674	Seal both sides of mullion mate at end cap. Typical all locations		Webster > LEVEL_04 > 401_OFF. ADJ (4)	Open	PARIC (Self-Perform)	Architect Punch List	11 Jul 2017	16 Jul 2017



2017-07-11 10:32:26

End of 000674 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000683	Scuff on outside face of door		Webster > LEVEL_04 > 404_OFF. FLX	Open	PARIC (Self-Perform)	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 10:53:00

End of 000683 images

000686	Seal both sides of mullion mate at end cap.		Webster > LEVEL_04 > 403_OFF. FLX	Open	PARIC (Self-Perform)	Architect Punch List	11 Jul 2017	16 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000689	Finish drywall at column cover		Webster > LEVEL_04 > 403_OFF. FLX	Open	PARIC (Self-Perform)	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 11:03:58

End of 000689 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000692	Chip on door		Webster > LEVEL_04 > 403_OFF. FLX	Open	PARIC (Self-Perform)	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 11:09:34

End of 000692 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000695	Need to finish drywall in pocket		Webster > LEVEL_04 > 405_OFF. FLX	Open	PARIC (Self-Perform)	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 11:21:45

End of 000695 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000712	Penetrations to be sealed		Webster > LEVEL_04 > 411_OFFICE FLX	Open	PARIC (Self-Perform)	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 12:02:26

2017-07-11 12:02:31

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-11 12:02:41

End of 000712 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000724	Chips on door		Webster > LEVEL_04 > 412_TESTING	Open	PARIC (Self-Perform)	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 12:31:51



2017-07-11 12:32:03

End of 000724 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000728	Damaged door		Webster > LEVEL_04 > 413_OFF. IL	Open	PARIC (Self-Perform)	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 12:38:59

End of 000728 images

000729	Door hinges cut incorrectly, door to be re-ordered		Webster > LEVEL_04 > 414_TESTING	Open	PARIC (Self-Perform)	Architect Punch List	11 Jul 2017	16 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000740	Seal wall to base of curtainwall at all locations		Webster > LEVEL_04 > 419_TRANSLATION	Open	PARIC (Self-Perform)	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 13:18:03

End of 000740 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000753	Sand down excess drywall mud at soffit trim		Webster > LEVEL_04 > 435_OFF. IL	Open	PARIC (Self-Perform)	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 13:51:51

End of 000753 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000757	Damaged door		Webster > LEVEL_04 > 435_OFF. IL	Open	PARIC (Self-Perform)	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 13:56:01

End of 000757 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000765	Fix caulking (backer rod bulging out)		Webster > LEVEL_04 > 452_OFF. TA	Open	PARIC (Self-Perform)	Architect Punch List	11 Jul 2017	16 Jul 2017



2017-07-11 14:18:53

End of 000765 images

000768	Missing doors (pending frame by NGG)	Webster > LEVEL_04 > 452_OFF. TA	Open	PARIC (Self-Perform)	Architect Punch List	11 Jul 2017	16 Jul 2017
000771	Missing doors (pending frames by NGG)	Webster > LEVEL_04 > 454_OFF. INTL	Open	PARIC (Self-Perform)	Architect Punch List	11 Jul 2017	16 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000775	Fill holes at end of light cove in southwest corridor and finish edges of drywall (possibly use trim)		Webster > LEVEL_04	Open	PARIC (Self-Perform)	Architect Punch List	11 Jul 2017	16 Jul 2017



2017-07-11 14:59:48

2017-07-11 14:59:55

End of 000775 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000780	Top panel should be flush with elevator door jamb.		Webster > LEVEL_04	Open	PARIC (Self-Perform)	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 15:14:45

End of 000780 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000781	Caulk edge of elevator jamb to wall		Webster > LEVEL_04	Open	PARIC (Self-Perform)	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 15:16:25

End of 000781 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000783	Finish drywall mud at corner beads at inset.		Webster > LEVEL_04	Open	PARIC (Self-Perform)	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 15:18:35

End of 000783 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000784	Seal between wood panels and aluminum frames (typical at all locations)		Webster > LEVEL_04 > 472_CHEM LAB - GENERAL	Open	PARIC (Self-Perform)	Architect Punch List	11 Jul 2017	16 Jul 2017



2017-07-11 15:24:01

End of 000784 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000785	Cork board should be flush with wood panel		Webster > LEVEL_04 > 472_CHEM LAB - GENERAL	Open	PARIC (Self-Perform)	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 15:27:27

End of 000785 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000791	Drywall repairs needed throughout room		Webster > LEVEL_04 > 472_CHEM LAB - GENERAL	Open	PARIC (Self-Perform)	Architect Punch List	11 Jul 2017	16 Jul 2017



2017-07-11 16:05:34

2017-07-11 16:05:40

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date



2017-07-11 16:06:00

2017-07-11 16:06:09

End of 000791 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000792	Filler panels at end of casework need to be flush with wall, no void should be at base.		Webster > LEVEL_04 > 472_CHEM LAB - GENERAL	Open	PARIC (Self-Perform)	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 16:07:51

2017-07-11 16:07:56

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-11 16:07:59

End of 000792 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000801	Drywall needs touched up		Webster > LEVEL_04 > 478_CHEM LAB PREP	Open	PARIC (Self-Perform)	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 16:45:36



2017-07-11 16:46:01

End of 000801 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000809	Doors need to be adjusted at teaching wall. Door hits marker tray and are not even.		Webster > LEVEL_04 > 480_CHEM LAB - ORGANIC	Open	PARIC (Self-Perform)	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 17:03:33

End of 000809 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000812	Filler panels at all teaching walls to be flush with wall. (Typical)		Webster > LEVEL_04	Open	PARIC (Self-Perform)	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 17:10:37

End of 000812 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000828	Touch up drywall on window ledge		Webster > LEVEL_04 > 488_CHEM LAB - ANALYT / INORGANIC	Open	PARIC (Self-Perform)	Architect Punch List	12 Jul 2017	17 Jul 2017



2017-07-12 09:36:35

End of 000828 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000830	Filler panels to be flush with wall		Webster > LEVEL_04 > 488_CHEM LAB - ANALYT / INORGANIC	Open	PARIC (Self-Perform)	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 09:40:50

End of 000830 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000839	Finish tape behind all handicap sinks		Webster > LEVEL_04 > 491_CHEM LAB PHYSICAL	Open	PARIC (Self-Perform)	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 10:06:11

End of 000839 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000868	Mirrors to be centered on tile, need weep holes on bottom trim.		Webster > LEVEL_04 > 479_MEN	Open	PARIC (Self-Perform)	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 11:05:17

End of 000868 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000870	Use correct spacer at partition screw		Webster > LEVEL_04 > 479_MEN	Open	PARIC (Self-Perform)	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 11:07:23

End of 000870 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000877	Mirrors to be centered on backsplash and have weeps on bottom trim.		Webster > LEVEL_04 > 479_MEN	Open	PARIC (Self-Perform)	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 11:18:58

End of 000877 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000878	Install backsplash		Webster > LEVEL_04 > 477_WOMEN	Open	PARIC (Self-Perform)	Architect Punch List	12 Jul 2017	17 Jul 2017



2017-07-12 11:19:43

End of 000878 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000881	Damaged door frame		Webster > LEVEL_04 > 480_CHEM LAB - ORGANIC	Open	PARIC (Self-Perform)	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 12:50:42

End of 000881 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000885	Dent in door frame		Webster > LEVEL_04 > 475_LAB WASTE - CHEM	Open	PARIC (Self-Perform)	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 12:58:47

End of 000885 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000887	Missing wood panels at encoves along N-S corridor		Webster > LEVEL_04	Open	PARIC (Self-Perform)	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 13:12:41

2017-07-12 13:12:50

End of 000887 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000888	Ceilings needed in areas above breaker boxes in corridors (typical all locations)		Webster > LEVEL_04	Open	PARIC (Self-Perform)	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 13:14:06

End of 000888 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000889	Vertical edge of paneling should line up with edge of horizontal paneling.		Webster > LEVEL_04	Open	PARIC (Self-Perform)	Architect Punch List	12 Jul 2017	17 Jul 2017



2017-07-12 13:18:27

End of 000889 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000891	Chipped panel at northwest of corridor		Webster > LEVEL_04	Open	PARIC (Self-Perform)	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 13:20:54

End of 000891 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000892	Touchup drywall at northeast of corridor		Webster > LEVEL_04	Open	PARIC (Self-Perform)	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 13:22:27

End of 000892 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000749	Seal penetrations in ceiling tile for WAPS- whose scope?		Webster > LEVEL_04	Open	Paric Corp.	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 13:42:27

End of 000749 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000763	Blue tape behind shades - whose scope?		Webster > LEVEL_04 > 441_SM. MTG.	Open	Paric Corp.	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 14:07:00

End of 000763 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000821	Fill hole in steel - scope?		Webster > LEVEL_04 > 488_CHEM LAB - ANALYT / INORGANIC	Open	Paric Corp.	Architect Punch List	12 Jul 2017	17 Jul 2017



2017-07-12 09:29:38

End of 000821 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000826	Remove concrete from steel - scope?		Webster > LEVEL_04 > 488_CHEM LAB - ANALYT / INORGANIC	Open	Paric Corp.	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 09:34:41

End of 000826 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000837	All fire extinguishers to be installed after the phones (typical)		Webster > LEVEL_04 > 491_CHEM LAB PHYSICAL	Open	Paric Corp.	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 10:03:46

End of 000837 images

000850	Sealant needed where ceiling grid is not flush with wall (typical) - whose scope?		Webster > LEVEL_04 > 491_CHEM LAB PHYSICAL	Open	Paric Corp.	Architect Punch List	12 Jul 2017	17 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000857	Wall too close to aluminum framing to install emseal		Webster > LEVEL_04 > 489_CHEM INSTR. LAB	Open	Paric Corp.	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 10:41:36

End of 000857 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000671	Paint exposed metal edge where wall meets curtainwall.		Webster > LEVEL_04 > 401_OFF. ADJ (4)	Open	Spectra Painting	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 10:25:22

End of 000671 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000673	Touch up paints above door		Webster > LEVEL_04 > 401_OFF. ADJ (4)	Open	Spectra Painting	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 10:29:27

End of 000673 images

000687	Paint needed at end caps		Webster > LEVEL_04 > 403_OFF. FLX	Open	Spectra Painting	Architect Punch List	11 Jul 2017	16 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000690	Caulk and paint holes for lighting penetrations		Webster > LEVEL_04 > 403_OFF. FLX	Open	Spectra Painting	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 11:05:39

2017-07-11 11:05:45

End of 000690 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000694	Paint exposed metal to match mullion		Webster > LEVEL_04 > 405_OFF. FLX	Open	Spectra Painting	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 11:19:49

End of 000694 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000696	Soffit to be painted white		Webster > LEVEL_04 > 405_OFF. FLX	Open	Spectra Painting	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 11:23:36

End of 000696 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000700	Touch up scuff marks on drywall ceiling		Webster > LEVEL_04 > 405_OFF. FLX	Open	Spectra Painting	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 11:29:55

End of 000700 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000705	Paint scuffs and touch ups on walls.		Webster > LEVEL_04 > 407_OFF. STAFF	Open	Spectra Painting	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 11:45:06

2017-07-11 11:45:23

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-11 11:49:19

2017-07-11 11:50:10

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-11 11:50:24

2017-07-11 11:50:52

End of 000705 images

000715	Paint needed at end caps		Webster > LEVEL_04 > 411_OFFICE FLX	Open	Spectra Painting	Architect Punch List	11 Jul 2017	16 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000716	Clean paint from light fixture		Webster > LEVEL_04 > 411_OFFICE FLX	Open	Spectra Painting	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 12:14:43

End of 000716 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000733	Paint to be touched up		Webster > LEVEL_04 > 415_OFF. IL	Open	Spectra Painting	Architect Punch List	11 Jul 2017	16 Jul 2017



2017-07-11 12:52:28

2017-07-11 12:52:34

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-11 12:52:42

2017-07-11 12:52:50

End of 000733 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000744	Touch up paint, paint end caps		Webster > LEVEL_04 > 431_OFF. FUT	Open	Spectra Painting	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 13:25:26



2017-07-11 13:25:36

End of 000744 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000745	Touch up "fuzz" in paint		Webster > LEVEL_04 > 419_TRANSLATION	Open	Spectra Painting	Architect Punch List	11 Jul 2017	16 Jul 2017



2017-07-11 13:30:36

End of 000745 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000747	Touch up paint		Webster > LEVEL_04 > 432_OFF. ADJ. (3)	Open	Spectra Painting	Architect Punch List	11 Jul 2017	16 Jul 2017



2017-07-11 13:35:45

2017-07-11 13:35:51

End of 000747 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000750	Touch up paint		Webster > LEVEL_04 > 434_OFF. ADJ (3)	Open	Spectra Painting	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 13:46:51

End of 000750 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000752	Touch up paint at soffit trim		Webster > LEVEL_04 > 435_OFF. IL	Open	Spectra Painting	Architect Punch List	11 Jul 2017	16 Jul 2017



2017-07-11 13:49:48

End of 000752 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000754	Touch up paint (following drywall repair at soffit)		Webster > LEVEL_04 > 435_OFF. IL	Open	Spectra Painting	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 13:52:29

End of 000754 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000756	Touch up paint above aluminum framing		Webster > LEVEL_04 > 435_OFF. IL	Open	Spectra Painting	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 13:54:27

End of 000756 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000762	Touch up paint		Webster > LEVEL_04 > 441_SM. MTG.	Open	Spectra Painting	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 14:05:36

2017-07-11 14:08:00

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-11 14:08:11

End of 000762 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000764	Damaged ceiling tiles		Webster > LEVEL_04 > 452_OFF. TA	Open	Spectra Painting	Architect Punch List	11 Jul 2017	16 Jul 2017



2017-07-11 14:17:32



2017-07-11 14:17:40

End of 000764 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000766	Touch up paint, fix "runs"		Webster > LEVEL_04 > 452_OFF. TA	Open	Spectra Painting	Architect Punch List	11 Jul 2017	16 Jul 2017



2017-07-11 14:20:06

2017-07-11 14:20:13

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-11 14:20:17

2017-07-11 14:20:23

End of 000766 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000769	Touch up paint		Webster > LEVEL_04 > 454_OFF. INTL	Open	Spectra Painting	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 14:23:19

2017-07-11 14:23:22

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-11 14:23:26



2017-07-11 14:23:32

End of 000769 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000776	Touchup paint on walls and hard ceilings where marked with blue tape in corridors (typical)		Webster > LEVEL_04	Open	Spectra Painting	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 15:07:37

2017-07-11 15:08:01

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-11 15:08:04

2017-07-11 15:08:19

End of 000776 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000778	Clean paint from ceiling grid where hard ceiling meets ceiling tile in the corridor		Webster > LEVEL_04	Open	Spectra Painting	Architect Punch List	11 Jul 2017	16 Jul 2017



2017-07-11 15:11:13

End of 000778 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000779	Clean paint from light fixtures (typical in corridor hard ceilings)		Webster > LEVEL_04	Open	Spectra Painting	Architect Punch List	11 Jul 2017	16 Jul 2017



2017-07-11 15:13:22

End of 000779 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000786	Should be a wall talker and not paint		Webster > LEVEL_04 > 472_CHEM LAB - GENERAL	Open	Spectra Painting	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 15:33:16

End of 000786 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000790	Touchup paint on walls		Webster > LEVEL_04 > 472_CHEM LAB - GENERAL	Open	Spectra Painting	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 16:03:27



2017-07-11 16:03:33

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date



2017-07-11 16:03:42

2017-07-11 16:03:50

End of 000790 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000794	Cleanup paint around edges of eye washes		Webster > LEVEL_04 > 472_CHEM LAB - GENERAL	Open	Spectra Painting	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 16:13:52

End of 000794 images

000802	Touch up paint		Webster > LEVEL_04 > 478_CHEM LAB PREP	Open	Spectra Painting	Architect Punch List	11 Jul 2017	16 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000820	Paint on the floor		Webster > LEVEL_04 > 488_CHEM LAB - ANALYT / INORGANIC	Open	Spectra Painting	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 09:27:19

End of 000820 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000829	Touch up paint		Webster > LEVEL_04 > 488_CHEM LAB - ANALYT / INORGANIC	Open	Spectra Painting	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 09:38:38

2017-07-12 09:38:40

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-12 09:38:47

End of 000829 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000840	Paint under handicap sink (following drywall finishing) typical all locations		Webster > LEVEL_04 > 491_CHEM LAB PHYSICAL	Open	Spectra Painting	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 10:06:57

End of 000840 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000855	Entire wall to be repainted		Webster > LEVEL_04 > 489_CHEM INSTR. LAB	Open	Spectra Painting	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 10:38:35

End of 000855 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000866	Touchup walls and soffits		Webster > LEVEL_04 > 483_CHEM LAB - RESEARCH	Open	Spectra Painting	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 11:02:29



2017-07-12 11:02:34

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-12 11:02:41

2017-07-12 11:02:53

End of 000866 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000871	Painting needs to be better where ceiling meets tile		Webster > LEVEL_04 > 479_MEN	Open	Spectra Painting	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 11:08:49

2017-07-12 11:08:55

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-12 11:09:08

End of 000871 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000872	Repaint wall under sink		Webster > LEVEL_04 > 479_MEN	Open	Spectra Painting	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 11:09:53

End of 000872 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000875	Cleanup paint around escutcheon		Webster > LEVEL_04 > 479_MEN	Open	Spectra Painting	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 11:14:58

End of 000875 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000880	Remove paint from can light		Webster > LEVEL_04 > 477_WOMEN	Open	Spectra Painting	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 11:41:03

End of 000880 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000884	Touch up paint on door frame		Webster > LEVEL_04 > 480_CHEM LAB - ORGANIC	Open	Spectra Painting	Architect Punch List	12 Jul 2017	17 Jul 2017



2017-07-12 12:58:13

2017-07-12 12:58:17

End of 000884 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000890	Crack in cork wall covering - north corridor		Webster > LEVEL_04	Open	Spectra Painting	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 13:19:57

End of 000890 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000893	Touchup paint in corridor		Webster > LEVEL_04	Open	Spectra Painting	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 13:24:18

2017-07-12 13:24:54

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date



2017-07-12 13:25:04

End of 000893 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000895	Remove cork board adhesive from base		Webster > LEVEL_04	Open	Spectra Painting	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 13:27:01

End of 000895 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000661	Clean up scuffs on ceiling tile (typ), fix holes and damaged tiles, scratches on ceiling grid.		Webster > LEVEL_04 > 400A_WORK / COPY	Open	St Charles Acoustics	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 09:53:08

2017-07-11 09:53:21

End of 000661 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000668	Scuffed ceiling tiles and damaged grid		Webster > LEVEL_04 > 401_OFF. ADJ (4)	Open	St Charles Acoustics	Architect Punch List	11 Jul 2017	16 Jul 2017



2017-07-11 10:15:17

2017-07-11 10:15:20

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-11 10:15:24

End of 000668 images

000670	Adjust tees so that void is not visible		Webster > LEVEL_04 > 401_OFF. ADJ (4)	Open	St Charles Acoustics	Architect Punch List	11 Jul 2017	16 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000676	Scuffed ceiling tiles and damaged grid		Webster > LEVEL_04 > 402_OFF. WORK STUDY	Open	St Charles Acoustics	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 10:41:09

2017-07-11 10:41:17

End of 000676 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000678	Adjust ceiling tee so no void is visible		Webster > LEVEL_04 > 404_OFF. FLX	Open	St Charles Acoustics	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 10:46:42

End of 000678 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000679	Scuffed ceiling tiles and damaged grid		Webster > LEVEL_04 > 404_OFF. FLX	Open	St Charles Acoustics	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 10:48:38

2017-07-11 10:48:44

End of 000679 images

000685	Scuffed ceiling tiles and damaged grid		Webster > LEVEL_04 > 403_OFF. FLX	Open	St Charles Acoustics	Architect Punch List	11 Jul 2017	16 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000697	Raw edge to be cleaned up on ceiling tiles		Webster > LEVEL_04 > 405_OFF. FLX	Open	St Charles Acoustics	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 11:24:56

End of 000697 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000703	Scuffed and chipped ceiling tiles		Webster > LEVEL_04 > 406_OFF. ADJ (4)	Open	St Charles Acoustics	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 11:34:45

End of 000703 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000706	Ceiling tile scuff marks and corner damage.		Webster > LEVEL_04 > 407_OFF. STAFF	Open	St Charles Acoustics	Architect Punch List	11 Jul 2017	16 Jul 2017



2017-07-11 11:47:38

2017-07-11 11:47:48

End of 000706 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000719	Scuffed ceiling tiles		Webster > LEVEL_04 > 411_OFFICE FLX	Open	St Charles Acoustics	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 12:19:23

End of 000719 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000722	Scuffed ceiling tiles and grid needs to be adjusted		Webster > LEVEL_04 > 412_TESTING	Open	St Charles Acoustics	Architect Punch List	11 Jul 2017	16 Jul 2017



2017-07-11 12:28:41

2017-07-11 12:28:46

End of 000722 images

000727	Scuffed ceiling tiles		Webster > LEVEL_04 > 413_OFF. IL	Open	St Charles Acoustics	Architect Punch List	11 Jul 2017	16 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000730	Ceiling tile cut incorrectly, raw edges to be dressed up		Webster > LEVEL_04 > 414_TESTING	Open	St Charles Acoustics	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 12:41:42



2017-07-11 12:42:45

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-11 12:43:21

End of 000730 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000735	Scuffs on ceiling tile, adjust grid as needed		Webster > LEVEL_04 > 416_OFF. IL WS (2)	Open	St Charles Acoustics	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 13:03:59

2017-07-11 13:04:04

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-11 13:04:13

End of 000735 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000741	Scuffed ceiling tiles		Webster > LEVEL_04 > 419_TRANSLATION	Open	St Charles Acoustics	Architect Punch List	11 Jul 2017	16 Jul 2017



2017-07-11 13:20:35

2017-07-11 13:20:40

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-11 13:20:46

End of 000741 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000742	Adjust ceiling tile		Webster > LEVEL_04 > 431_OFF. FUT	Open	St Charles Acoustics	Architect Punch List	11 Jul 2017	16 Jul 2017



2017-07-11 13:22:44

End of 000742 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000746	Scuffs on tile, tile need to be adjusted to lay flat, gap in tee too large.		Webster > LEVEL_04 > 432_OFF. ADJ. (3)	Open	St Charles Acoustics	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 13:33:43

2017-07-11 13:33:46

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-11 13:33:50



2017-07-11 13:33:57

End of 000746 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000748	Scuffs on ceiling tile		Webster > LEVEL_04 > 433_OFF. IL	Open	St Charles Acoustics	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 13:38:43

End of 000748 images

000751	Replace miscolored ceiling tile		Webster > LEVEL_04 > 435_OFF. IL	Open	St Charles Acoustics	Architect Punch List	11 Jul 2017	16 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000760	Scuffs at ceiling tile		Webster > LEVEL_04 > 439_OFF. ESL	Open	St Charles Acoustics	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 14:02:09



2017-07-11 14:02:13

End of 000760 images

000774	Dark spot on ceiling tile		Webster > LEVEL_04 > 456_OFF. SAFETY OFFICER	Open	St Charles Acoustics	Architect Punch List	11 Jul 2017	16 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000777	Scuffs and damaged ceiling tile and grid throughout the corridors marked with blue tape (typ)		Webster > LEVEL_04	Open	St Charles Acoustics	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 15:09:40

2017-07-11 15:09:44

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date



2017-07-11 15:09:57

2017-07-11 15:10:04

End of 000777 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000800	Damaged/scuffed ceiling tiles, uneven gaps at grid		Webster > LEVEL_04 > 478_CHEM LAB PREP	Open	St Charles Acoustics	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 16:43:00



2017-07-11 16:43:05

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date

2017-07-11 16:43:17

End of 000800 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000845	Adjust ceiling tile and fixed scuffed tile		Webster > LEVEL_04 > 491_CHEM LAB PHYSICAL	Open	St Charles Acoustics	Architect Punch List	12 Jul 2017	17 Jul 2017



2017-07-12 10:19:08



2017-07-12 10:19:13

End of 000845 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000867	Replace damaged ceiling tiles		Webster > LEVEL_04 > 483_CHEM LAB - RESEARCH	Open	St Charles Acoustics	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 11:03:46

2017-07-12 11:03:50

End of 000867 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000896	Replace damaged ceiling tile in corridor		Webster > LEVEL_04	Open	St Charles Acoustics	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 13:28:04

2017-07-12 13:28:14

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date



2017-07-12 13:28:38

2017-07-12 13:28:53

End of 000896 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000789	Damaged and scuffed ceiling tiles		Webster > LEVEL_04 > 472_CHEM LAB - GENERAL	Open	St. Charles Acoustics L.L.C.	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 16:01:40

2017-07-11 16:01:47

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date



2017-07-11 16:01:57

End of 000789 images

000825	Scuffs and damaged ceiling tile		Webster > LEVEL_04 > 488_CHEM LAB - ANALYT / INORGANIC	Open	St. Charles Acoustics L.L.C.	Architect Punch List	12 Jul 2017	17 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000656	Clean sink and black mark on bottom of countertop		Webster > LEVEL_04 > 400A_WORK / COPY	Open	Titan Contractor Services	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 09:30:14



2017-07-11 09:33:23

End of 000656 images

000659	General cleanup of floor, inside of cabinets		Webster > LEVEL_04 > 400A_WORK / COPY	Open	Titan Contractor Services	Architect Punch List	11 Jul 2017	16 Jul 2017

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000709	General cleanup		Webster > LEVEL_04 > 410_ELEC	Open	Titan Contractor Services	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 11:58:34

End of 000709 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000720	Escutcheon plates to be cleaned		Webster > LEVEL_04 > 411_OFFICE FLX	Open	Titan Contractor Services	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 12:21:09

End of 000720 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000725	Clean stains from carpet (Titan please advise if carpet tile must be replaced)		Webster > LEVEL_04 > 413_OFF. IL	Open	Titan Contractor Services	Architect Punch List	11 Jul 2017	16 Jul 2017



2017-07-11 12:34:02

End of 000725 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000732	Ceiling grid to be cleaned off		Webster > LEVEL_04 > 415_OFF. IL	Open	Titan Contractor Services	Architect Punch List	11 Jul 2017	16 Jul 2017



2017-07-11 12:49:41

End of 000732 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000743	Clean lights		Webster > LEVEL_04 > 431_OFF. FUT	Open	Titan Contractor Services	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 13:23:55

2017-07-11 13:23:59

End of 000743 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000813	Clean under counter		Webster > LEVEL_04 > 480_CHEM LAB - ORGANIC	Open	Titan Contractor Services	Architect Punch List	11 Jul 2017	16 Jul 2017

2017-07-11 17:11:33

End of 000813 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000863	Clean at top of fume hoods		Webster > LEVEL_04 > 483_CHEM LAB - RESEARCH	Open	Titan Contractor Services	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 10:51:51

End of 000863 images

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date
000869	General cleanup at floors, access panels, can lights		Webster > LEVEL_04 > 479_MEN	Open	Titan Contractor Services	Architect Punch List	12 Jul 2017	17 Jul 2017

2017-07-12 11:06:18

2017-07-12 11:06:55

Issue ID	Description	Location Detail	Location	Status	Company	Type	Date Created	Due Date



2017-07-12 11:07:00

2017-07-12 11:11:33

End of 000869 images