



PARIC CORPORATION
77 Westport Plaza Suite 250
St. Louis, MO 63146
TEL: 636-561-9500
FAX: 636-561-9501

REQUEST FOR INFORMATION **DATE:** May 19, 2016 **NO.:** RFI-102

To: Cannon Design

Attn: Kelvin Patel

From: Paric Corporation

Requested By: Joe Voypick

Project Name: Webster University Interdisciplinary Science Building Project No.: 15051

Subject: Wall mounting bracket box conflict with wall

Response Required By: May 26, 2016

Drawing / Spec Reference:

Information Requested:

Sheet P0601 specifies the TMV-2 and TMV-3 mixing valves to have a "wall mounting bracket" for the mixing valve. This is a recessed box that houses the mixing valve. This box requires a 6" stud minimum (6" block is too narrow and will not work). These emergency fixtures that have TMV-2/TMV-3 are almost all on 3-5/8" stud walls.

Please advise if the 'wall mounting bracket box' for the mixing valve can be eliminated, or else increase the walls to a minimum of a 6" stud wall.

Response:

The manufacturers wall mounting bracket is not the same as the manufacturers recessed (or surface mounted) valve cabinet.
TMV-2 is located above the ceiling, TMV-3 is located in the cabinet below the sink.
Coordinate with the TMV manufacturer for the wall mounting bracket.

ARCHITECT'S RESPONSE:

This information is provided as an interpretation of the Contract Documents for implementation. It is not an authorization for change to the Contract Sum or Contract Time. If this information results in a claim for a change to the Contract, the Contractor shall notify the [Construction Manager][Architect] of a change through the change process.

Cc: Kathy Bathe, Paric Corporation

Answered By: Mike Whitworth - WES

Date: May 21, 2016