




Akins Consulting Services, LLP

SITE ACTIVITY REPORT FOR 01/31/2017

Reported by Joseph Osuma, P.E.

ACS representative visited the Job Site to observe foundation trench excavation. Photograph 1 shows the location observed and Photograph 2 shows the foundation trench observed on January 31, 2017.



Photograph 1



Photograph 2

The foundation trench excavation had already been completed prior to my arrival. The exposed surface of the trench was evaluated and found to be in compliance with the design bearing capacity. Trench excavation observed during this visit was in accordance with good earthwork practice.